

INS. CASE OWNER:

IRONE

CC 6/CTI1901 8282, K hb<sup>a3</sup> m2

LKK:

IDAC:

Surveyor:

Kenneth

DOI:

12/10/19

Date / Time:

12/10/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : SMD 8063R  
Name of Insured : MY WEL SLANG WORKS  
Insured Tel No. : HP: 12/10/19  
Excess Sec II : \$\$ D.O.A : 12/10/19

Claim No. : SNM19D204902-9208082-THP  
Policy No. : DMP15N306271900  
Make / Model : VOLKSWAGEN  
Place of Accident : APT

Is driver the owner? ( YES / NO ) Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

NA

SMD 8063R

SMN 8120G

SMJ 876R



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS: 01



INSRS: WEI  
WSP: LEE  
Tel:  
Liability:  
RMKS: TP



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
21/10/19	After call ltr to OI:	21/10/19 - OIC
	Documentation Check List: Handler	Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>
<b>PRELIMINARY ADVICE</b> Date/Time: 16/10/19 Sent By: b3		
<b>FINALIZATION</b> Date/Time: Confirm with: Confirm by:		
Repair Cost: 49	\$S 8,200.00 ( 7 days) Reduction: 59 %	Email <input type="checkbox"/> Call <input type="checkbox"/>
<b>FINAL SETTLEMENT</b> Date/Time: 23/02/2020 Confirm with: KAREN		
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No. : 28	If NO or B 28, Ass. Lia : 0% (CG WAH. C.O.; OI 3RD)
Repair Cost: (2) (50)	\$S 8,774.00	
Loss of Rental (LOR):	\$S - ( days)	
Loss of Use (LOU):	\$S 420.00 (S 60 x 7 days)	
Loss of Income (LOI):	\$S - (5 x days)	
LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]	
GIA/LTA Search	\$S 7.45	
Medical:	\$S -	
Disbursement:	\$S - (e.g. Tow/ Independent)	
Legal Cost	\$S -	
<b>Total:</b>	\$S 9,201.45 Global Sum \$S: -	
<b>FINAL PAYMENT</b> Date/Time: Confirm with: Email <input type="checkbox"/> Cal <input type="checkbox"/>		
Payee 1:	\$S 9,201.45 Name 1: WEI LEE MOTOR WORKS	
Payee 2: (Strike if N.A.)	\$S - Name 2: -	
Payee 3: (Strike if N.A.)	\$S - Name 3: -	

ASS. REC. BY:

REF: 012/

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop n/s \_\_\_\_\_ Wei Kee

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 07 days Res.: Yes or No

Lum Sum: 1.3.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SMN81206 Yr Regn: 12 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda VTEC c.c. 1496

Colour: M.P. White A/C: Insured / Std / NI / NA

Sp. Reading: 88515 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KUI 1104382

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16 R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Kumho

Front R/Bal. 9 mm Rear R/Bal. 9 mm

L/Bal. 9 mm L/Bal. 9 mm

D.O.A. 12/10/19 D.O.I. 15/10/19

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or & FR

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
/	File pass to
	L/S \$8,200.00
	CRSD: \$5,221.12 (39%)

Date/Time, File Pass to?  : Prell. Report  : Final Report

Date/Time, File Return to?

Days Of Repair: \_\_\_\_\_ Resurvey No. of Trip: \_\_\_\_\_

Report Format : Lump Sum / I.B.I: (\$

Add Fee:  : Site Insp (\$  : Interview (\$  : Tech Invs (\$  : Weekend (\$

Survey Fee:	
Transportation:	
S - RS, SI	
Fuel/Exp	
Others	
TOTAL	



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised  
Our ref: CC6/CTI19018282/Khb3

Date: 16.10.2019

The Motor Claims Department  
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**


**SMN8120G**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15.10.2019 at the premises of M/s Wei Lee Motor Works and have the following to report:-

Workshop Estimate Amount	: S\$	<u>9,851.30</u>
Revised Estimate Amount	: S\$	<u>6,987.92</u>
"Check" Items Amount	: S\$	<u>794.20</u>
Market Value	: S\$	<u>-</u>
LTA Reimbursement Value	: S\$	<u>-</u>
Nett Value	: S\$	<u>-</u>

Description of Damage:  
The vehicle sustained damages at the  
Front & Rear Portion



Comments/Present Status:  
Damages Consistent  
Estimated normal period for repairs: 7 days

Yours faithfully,

KENNETH KONG  
Licensed Appraiser

# 威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,  
SINGAPORE 575644.  
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com  
Business Regn No: 269436/00J

*Not Authorised*  
*Resurvey Bypaint*  
*7 days*

14, OCT 2019

China Taiping Insurance (S) PI  
105 Cecil Street #18-00  
The Octagon  
S 069534

Attn: motor claim dept-3<sup>rd</sup> party claim  
Claiming against your insured vehicle no: SMD8063R  
Accident involving vehicle No; SMN8120G/SMD8063R/SMJ856R/NA/SMA8453P/SMN8605A  
DOA: 12/10/2019 AT AYE (MCE) 10KM

Dear officer incharge  
Re: estimate cost of repair for vehicle no: SMN8120G  
To supply—

Description	Qty	Amount	
Tailgate	1	<i>RM</i> 1,472.40	✓
Tailgate absorber @129.80	2	<i>RM</i> 259.60	X
Tailgate lock	1	<i>RM</i> 174.90	✓
End panel	1	<i>RM</i> 474.10	✓
End panel top garnish	1	<i>RM</i> 84.90	✓
Rear bumper	1	<i>RM</i> 508.80	✓
Rear bumper side @118.50	2	237.00	?
Rear bumper tow cover	1	<i>RM</i> 37.50	X
Front bumper	1	<i>RM</i> 891.10	✓
Front bumper foglamp	1	273.90	?
Front grille base	1	<i>CM</i> 374.20	✓
Front grille chrome	1	283.30	?
Front bumper side moulding @49.30	2	<i>CM</i> 98.60	✓
Front bumper H logo	1	<i>RM</i> 45.10	X
Tailgate H logo	1	<i>RM</i> 45.10	✓
Tailgate Vezel emblem	1	<i>RM</i> 52.50	✓
Boot weather strip	1	<i>RM</i> 186-90	✓
Front bumper lower grille	1	<i>RM</i> 137-50	✓
Boot tool compartment <i>loan</i>	1	<i>CM</i> 226-90	✓
○ Bonnet	1	<i>RM</i> 988-80	✓
○ Front & Rr bumper clip		<i>RM</i> 76-00	✓
○ Rear bumper reflector, RH		<i>CM</i> 92-20	✓

*208*

LKIC Auto Repairs hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Vehicle no: SMN8120G

Reverse sensor	<i>nd</i> 220,00	<i>200sn</i>
To remove/replace rear windscreen glass	150.00	<i>1201</i>
To transfer tailgate doorboard, rear wiper motor and all attachments to new door.	160.00	<i>601</i>
To remove damaged parts and attachments-front n rear		
Repair/reshape dented areas.		
Straighten rear chassis frames where necessary.		
To replace/align all parts into position.	1,200.00	<i>9001</i>
To spray paint	1,100.00	<i>10001</i>

Kh

# 威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,  
SINGAPORE 575644.  
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com  
Business Regn No: 269436/00J

*Not Authorise*

*Resurvey By paint*

*7 days*

*1/1 Sur @ 5350k*

14, OCT 2019

China Taiping Insurance (S) PI  
105 Cecil Street #18-00  
The Octagon  
S 069534

Attn: motor claim dept-3<sup>rd</sup> party claim  
Claiming against your insured vehicle no: SMD8063R  
Accident involving vehicle No; SMN8120G/SMD8063R/SMJ856R/NA/SMA8453P/SMN8605A  
DOA: 12/10/2019 AT AYE (MCE) 10KM

Dear officer incharge  
Re: estimate cost of repair for vehicle no: SMN8120G

To supply—

Description	Qty	Amount	
Tailgate <i>1100.90</i>	1	<i>Per</i> 1,472.40	✓
Tailgate absorber @129.80	2	<i>Per</i> 259.60	X
Tailgate lock	1	<i>Per</i> 174.90	✓
End panel	1	<i>Per</i> 474.10	✓
End panel top garnish	1	<i>Per</i> 84.90	✓
Rear bumper	1	<i>Per</i> 508.80	✓
Rear bumper side @118.50	2	<i>Per</i> 237.00	X
Rear bumper tow cover	1	<i>Per</i> 37.50	X
Front bumper	1	<i>Per</i> 891.10	✓
Front bumper foglamp	1	<i>Per</i> 273.90	X
Front grille base	1	<i>CM</i> 374.20	✓
Front grille chrome	1	<i>Per</i> 283.30	X
Front bumper side moulding @49.30	2	<i>CM</i> 98.60	✓
Front bumper H logo	1	<i>Per</i> 45.10	X
Tailgate H logo	1	<i>Per</i> 45.10	✓
Tailgate Vezelem emblem	1	<i>Per</i> 52.50	✓
Boot weather strip	1	<i>Per</i> 186.90	✓
Front bumper lower grille	1	<i>Per</i> 137.50	✓
Boot tool compartment <i>Loan</i>	1	<i>CM</i> 226.90	✓
Bonnet	1	<i>Per</i> 988.80	✓
Front & Rr bumper clip	1	<i>Per</i> 76.00	✓
Rear bumper reflector, RH <i>209</i>	1	<i>CM</i> 92.20	✓

LKK Auto Insurance hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Vehicle no: SMN8120G

Reverse sensor

To remove/replace rear windscreen glass

To transfer tailgate doorboard, rear wiper motor and all attachments to new door.

To remove damaged parts and attachments-front n rear

Repair/reshape dented areas.

Straighten rear chassis frames where necessary.

To replace/align all parts into position.

To spray paint

*Ad* 220,00 *2001n*  
150.00 *1201*  
160.00 *601*

1,200.00 *900*  
1,100.00 *1000*

# 威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,  
SINGAPORE 575644.  
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com  
Business Regn No: 269436/00J

*Not Authorise*

*Resurvey Repairing*

*7 days*

*U.S. \$ 8200/2*

14, OCT 2019

China Taiping Insurance (S) Pl  
105 Cecil Street #18-00  
The Octagon  
S 069534

Attn: motor claim dept-3<sup>rd</sup> party claim

Claiming against your insured vehicle no: SMD8063R

Accident involving vehicle No; SMN8120G/SMD8063R/SMJ856R/NA/SMA8453P/SMN8605A

DOA: 12/10/2019 AT AYE (MCE) 10KM

Dear officer incharge

Re: estimate cost of repair for vehicle no: SMN8120G

To supply—

Description	Qty	Amount	
Tailgate <i>1100-90</i>	1	<i>Bu</i> 1,472.40	✓
Tailgate absorber @129.80	2	<i>Sn</i> 259.60	X
Tailgate lock	1	<i>nu</i> 174.90	✓
End panel	1	<i>R</i> 474.10	✓
End panel top garnish	1	<i>nd</i> 84.90	✓
Rear bumper	1	<i>R</i> 508.80	✓
Rear bumper side @118.50	2	<i>Sn</i> 237.00	R
Rear bumper tow cover	1	<i>Sn</i> 37.50	X
Front bumper	1	<i>Bu</i> 891.10	✓
Front bumper foglamp	1	<i>Sn</i> 273.90	R
Front grille base	1	<i>CM</i> 374.20	✓
Front grille chrome	1	<i>Sn</i> 283.30	R
Front bumper side moulding @49.30	2	<i>CM</i> 98.60	✓
Front bumper H logo	1	<i>nu</i> <del>45.10</del>	X
Tailgate H logo	1	<i>nu</i> 45.10	✓
Tailgate Vezel emblem	1	<i>nu</i> 52.50	✓
Boot weather strip	1	<i>cut</i> 186-90	✓
Front bumper lower grille	1	<i>nu</i> 137-50	✓
Boot tool compartment <i>loan</i>	1	<i>CM</i> 226-90	✓
Bonnet	1	<i>R</i> 988-80	✓
Front & Rr bumper clip		<i>nu</i> 76-00	✓
Rear bumper reflector, RH		<i>CM</i> 92-20	✓

*209*

*265*  
*180*  
*180*

Vehicle no: SMN8120G

Reverse sensor	220,00	<i>2005n</i>
To remove/replace rear windscreen glass	150,00	<i>1201</i>
To transfer tailgate doorboard, rear wiper motor and all attachments to new door.	160,00	<i>601</i>
To remove damaged parts and attachments-front n rear		
Repair/reshape dented areas.		
Straighten rear chassis frames where necessary.		
To replace/align all parts into position.	1,200.00	<i>9001</i>
To spray paint	1,100.00	<i>10001</i>

# 威利摩托 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,  
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com  
Business Regn No: 269436/00J

China Taiping Insurance (S) Pl

CC: LKK Kenneth

Vehicle no: SMN8120G

Supplementary parts for vehicle no: <sup>SMN</sup>SDM8120G

To supply---

Description	Qty	Amount
Headlamp,Rh <span style="float: right;">3518.20</span>	1 <i>CM</i>	3,840.00 ✓
Spare tyre panel	1 <i>R</i>	962.30 X
Front bumper enforcement	1 <i>R</i>	274.30 ✓
Headlamp lower bracket @53.70	2 <i>CM</i>	107.40 ✓
Buzzer assy,Rear	1 <i>CM</i>	96.10 ✓
Parts		5,280.10
Parts less 20%		1,056.02
		4,224.08

To check wiring and all related connectors,replace/focus headlamp

120.00

*401*

Cut n weld badly damaged spare tyre panel,replace panel.

450.00

*2501*

To apply rust proofing

180.00

*906*

-----  
4,974.08

## Shu Pei (LKKAuto)

---

**From:** Irene Tay <irene.tay@sg.cntaiping.com>  
**Sent:** Thursday, 17 October 2019 12:30 PM  
**To:** Shu Pei (LKKAuto); Vic (LKKAuto)  
**Cc:** Shu Pei (LKKAuto); Vic (LKKAuto)  
**Subject:** RE: OUR REF: SNM19D204902-SMD8063R-THP- Accident Involving SMD8063R (OI : CTI - TBA) and SMN8120G (TP : LKK REF - CC6/CTI19018282/Khb3) on 12.10.2019  
**Attachments:** 20191017122429.pdf

Dear Sir/Mdm,

We enclosed herewith our Insured GIA REPORT as requested by you.

Regards,

**Irene Tay**  
Executive  
Claims Department (Motor Division)

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 63896192 | F:(65) 62247478/62247175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Claims Dept of CTI  
**Sent:** Thursday, October 17, 2019 10:10 AM  
**To:** Irene Tay <irene.tay@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Shu Pei (LKKAuto) <shupeil@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>  
**Subject:** OUR REF: SNM19D204902-SMD8063R-THP- Accident Involving SMD8063R (OI : CTI - TBA) and SMN8120G (TP : LKK REF - CC6/CTI19018282/Khb3) on 12.10.2019

Dear Irene,

Please revert LKK.

Note : officer in charge – Irene Tay

Thank you

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 63896116 | F: (65) 62247175



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CT119018282/Kha3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 02-03-2020	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMD 8063R	Veh. Inspected	SMN 8120G
Policy No.	DMPCSN3062771900	Coverage (\$)	0.00
Claim No.	SNM19D204902C02	Excess (\$)	0.00
Assign From		Assign Date	15/10/2019
2. Vehicle Particulars & Condition			
Make & Model	HONDA VEZEL (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	RU11104382	Colour	METALLIC PEARL WHITE
Odometer	88515	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	KUMHO	9 mm
L/H Front Tyre	215/60 R16	KUMHO	9 mm
R/H Rear Tyre	215/60 R16	KUMHO	9 mm
L/H Rear Tyre	215/60 R16	KUMHO	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	12/10/2019	Inspection Date	15/10/2019
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 8120G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	TAILGATE	BENT	1,472.40	1,100.90
2	TAILGATE ABSORBER @\$129.80	SERVICEABLE	259.60	-
1	TAILGATE LOCK	DENTED	174.90	174.90
1	END PANEL	BENT	474.10	474.10
1	END PANEL TOP GARNISH	DENTED	84.90	84.90
1	REAR BUMPER	BENT	508.80	508.80
2	REAR BUMPER SIDE @\$118.50	SERVICEABLE	237.00	-
1	REAR BUMPER TOW COVER	SERVICEABLE	37.50	-
1	FRONT BUMPER	BUCKLED	891.10	891.10
1	FRONT BUMPER FOGLAMP	SERVICEABLE	273.90	-
1	FRONT GRILLE BASE	CRACKED	374.20	374.20
1	FRONT GRILLE CHROME	SERVICEABLE	283.30	-
2	FRONT BUMPER SIDE MOULDING @\$49.30	CRACKED	98.60	98.60
1	FRONT BUMPER H LOGO	NOT NECESSARY	45.10	-
1	TAILGATE H LOGO	NECESSARY	45.10	45.10
1	TAILGATE VEZEL EMBLEM	NECESSARY	52.50	52.50
1	BOOT WEATHER STRIP	CUT	186.90	186.90
1	FRONT BUMPER LOWER GRILLE	DISTORTED	137.50	137.50
1	BOOT TOOL COMPARTMENT FOAM	CRACKED	226.90	226.90
1	BONNET	BENT	988.80	988.80
1	FRONT & RR BUMPER CLIP	NECESSARY	76.00	76.00
1	REAR BUMPER REFLECTOR RH	CRACKED	92.20	92.20
1	HEADLAMP ,RH (ADDITIONAL)	CRACKED	3,840.00	3,518.20
1	SPARE TYRE PANEL (ADDITIONAL)	TO REPAIR SEE LABOUR	962.30	-
1	FRONT BUMPER ENFORCEMENT (ADDITIONAL)	BENT	274.30	274.30
2	HEADLAMP LOWER BRACKET @\$53.70 (ADDITIONAL)	CRACKED	107.40	107.40
1	BUZZER ASSY ,REAR (ADDITIONAL)	CRACKED	96.10	96.10
	LESS 20% DISCOUNT		-2,460.28	-1,901.88
			<b>9,841.12</b>	<b>7,607.52</b>

Report Ref No. CC6/CTI19018282/Kha3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>SPECIAL NETT ITEMS</b>			
1	REVERSE SENSOR (SN)	DENTED	220.00	200.00
			220.00	200.00
	<b>LABOUR</b>			
	TO REMOVE/REPLACE REAR WINDSCREEN GLASS.		150.00	120.00
	TO TRANSFER TAILGATE DOORBOARD ,REAR WIPER MOTOR AND ALL ATTACHMENTS TO NEW DOOR.		160.00	60.00
	TO REMOVE DAMAGED PARTS AND ATTACHMENTS-FRONT N REAR REPAIR/RESHAPE DENTED AREAS.STRAIGHTEN REAR CHASSIS FRAMES WHERE NECESSARY.TO REPLACE/ALIGN ALL PARTS INTO POSITION.INCLUSIVE OF THE REPAIR OF SPARE TYRE PANEL.		1,200.00	900.00
	TO SPRAY PAINT.		1,100.00	1,000.00
	TO CHECK WIRING AND ALL RELATED CONNECTORS ,REPLACE /FOCUS HEADLAMP. (ADDITIONAL)		120.00	40.00
	CUT N WELD BADLY DAMAGED SPARE TYRE PANEL ,REPLACE PANEL.(ADDITIONAL)		450.00	250.00
	TO APPLY RUST PROOFING .(ADDITIONAL)		180.00	90.00
			<b>3,360.00</b>	<b>2,460.00</b>
	<b>GRAND TOTAL</b>		<b>13,421.12</b>	<b>10,267.52</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>8,200.00</b>

Report Ref No. CC6/CT119018282/Kha3n2

**KONG SENG CHEONG**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.