

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 8834G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	TO REPAIR SEE LABOUR	812.40	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	57.80	-
1	RH FRONT FENDER	BENT	868.70	868.70
1	RH FRONT FENDER UNDERSHIELD	SERVICEABLE	185.64	-
10	RH FRONT FENDER UNDERSHIELD CLIP	NOT NECESSARY	25.00	-
1	RHF FENDER WORDING "HYBRID"	NECESSARY	44.17	44.17
1	RH FRONT FENDER QUARTER GARNISH	DENTED	122.70	122.70
	LESS 25% DISCOUNT		-529.10	-258.89
			1,587.31	776.68
	<u>LABOUR</u>			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (BONNET, RHF FENDER, RH WINDSCREEN PILLAR). INCLUSIVE OF THE REPAIR OF BONNET AND BONNET HINGE RH.		800.00	400.00
	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (BONNET, RHF FENDER, RH WINDSCREEN PILLAR).		800.00	600.00
	TO CHECK WIRING.		50.00	15.00
	TO TUFF COAT.	NOT NECESSARY	80.00	-
			1,730.00	1,015.00
	GRAND TOTAL		3,317.31	1,791.68
	RECOMMENDED COST OF REPAIRS			1,791.68

Report Ref No. CS/FCI19018288/Kyd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.