

Accident Photo



Accident Photo



Accident Photo



Accident Photo





PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

INVOICE

Mr Tan Chee Kiong
C/o. Blk 3019A Ubi Road 1
#01-30
Singapore 408713

Invoice No. : HA/1909-56
Date : 20/09/2019

Descriptions	Amount (SGD)
Services rendered for appraiser / inspection report :-	
Survey Fee	
Photographs	
Transport Fees	
Re-inspection Fees	
Total :	SGD : \$ 496.00
SGD Dollar : Four Hundred Ninety Six Dollars Only.	
Our Reference : PAS/TP/0360719	
Vehicle No. : SJC8403J	
Make & Model : Mitsubishi Evolution 10	
Your Claim No. : Third Party Claim	

Notes:

All cheque payment should be Crossed and made payable to "PROMINENT APPRAISER SERVICES PTE LTD".

Please indicate our "INVOICE NO." on the reverse side of the cheque.

Should you have any enquiries, please do not hesitate to contact us.



For PROMINENT APPRAISER SERVICES PTE LTD



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

VEHICLE INSPECTION REPORT

Report No. : PAS/TP/0360719

Date of Report : 20/09/2019

To : Mr Tan Chee Kiong
C/o. Blk 3019A Ubi Road 1
#01-30
Singapore 408713

Date of Assignment : 26/07/2019
Report requested by : Mr Tan Chee Kiong
Date of Accident : 23/07/2019
Date of Inspection : 26/07/2019
Claim No. : Third Party Claim
Policy No. : -

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : SJC8403J
Make & Model : Mitsubishi Evolution 10
Date of Registration : 29/02/2008
Colour : Met. Blue

Engine Capacity (cc) : 1998cc
Mileage (km) : 41899km
Chassis / Frame No. : CZ4A0000976
Engine No. : 4B11AX6148

TYRE CONDITION

Front LH : 6 mm	Front RH : 6 mm
Make : Yokohama	Make : Yokohama
Rear LH : 6 mm	Rear RH : 6 mm
Make : Yokohama	Make : Yokohama

Road wheels Type : Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good
Paintwork : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable
Apparent Engine Modification : Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. C. H. Motor Vehicle Repair Training
Blk 3019A, Ubi Road 1, #01-30, Singapore 408713

ASSESSMENT

Repairer's Estimate : \$ 9,595.96
Revised Amount : \$ 7,988.86
Less Excess : \$ -
Recommended Reserve : \$ 6,390.00 (Lump Sum)

Estimated Normal Period of Repairs : 7 Working Days

Disclaimer: This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party.



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvos@hotmail.com

Business Reg. 201404434D

Vehicle No : SJC8403J

Report No. : PAS/TP/0360719

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. C. H. Motor Vehicle Repair Training, Blk 3019A, Ubi Road 1, #01-30, Singapore 408713.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the rear portion.

DAMAGES

The boot lid, boot spoiler, rear bumper, rear end panel, rear floor panel, rear chassis members, rear fenders, taillamps, rear reflectors, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$7,988.86.

CONCLUSION


The repairer has agreed to undertake the repairs at a lump sum of SGD \$6,390.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,
Prominent Appraiser Services Pte Ltd


Andrew How
Automobile Appraiser
MSAAA
Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No. : SJC8403J

Report No. : PAS/TP/0360719

APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition	Repairer's Estimate (\$)	Our Assessment (\$)
1	1 pc	Boot lid	Dented	\$ 831.00	\$ 831.00
2	1 pc	Boot lid third brake lamp	Dented/Cracked	\$ 324.00	\$ 324.00
3	2 pc	Boot lid reflector lamp R/L	Cracked	\$ 364.00	\$ 364.00
4	1 pc	Boot lid emblem (Logo)	Necessary	\$ 48.00	\$ 48.00
5	1 pc	Boot lid emblem (Lancer)	Necessary	\$ 40.00	\$ 40.00
6	1 pc	Boot lid emblem (Evolution)	Necessary	\$ 62.00	\$ 62.00
7	1 pc	Boot lid lock switch seal	Necessary	\$ 18.00	\$ 18.00
8	1 pc	Boot lid lining	Refit	\$ 147.00	\$ -
9	7 pcs	Boot lid lining clip	Necessary	\$ 21.00	\$ 21.00
10	1 pc	Boot lid lock (w/motor)	Bent/Damaged	\$ 169.00	\$ 169.00
11	1 pc	Boot lid lock striker	Bent	\$ 65.00	\$ 65.00 X SVC
12	1 pc	Boot lid weatherstrip	Torn/Necessary	\$ 167.00	\$ 167.00
13	1 pc	Boot lid spoiler	Dented/Cracked	\$ 1,283.40	\$ 1,283.40
14	2 pc	Taillamp R/L	Broken/Cracked	\$ 688.00	\$ 688.00
15	1 pc	Rr bumper	Dented	\$ 724.00	\$ 724.00
16	1 pc	Rr bumper diffuser	Refit	\$ 396.00	\$ -
17	6 pcs	Rr bumper clip	Necessary	\$ 18.00	\$ 18.00
18	2 pcs	Rr bumper retainer R/L	Necessary	\$ 76.00	\$ 76.00
19	1 pc	Rr bumper beam	Dented/Bent	\$ 86.00	\$ 86.00
20	1 pc	Rr bumper reinforcement	Refit	\$ 393.00	\$ -
21	2 pcs	Rr bumper no.plate lamp	Cracked	\$ 144.00	\$ 144.00 X SVC
22	1 pc	Rr end panel	Dented/Distorted	\$ 521.00	\$ 521.00 RX
23	1 pc	Rr end panel trim	Refit	\$ 183.00	\$ -
24	4 pcs	Rr end panel trim clip	Necessary	\$ 16.00	\$ 16.00 X SVC
25	2 pcs	Rr fender R/L	Dented/Repair		(Refer labour no. 6 & 7)
26	1 pc	Rr floor panel	Dented/Repair		(Refer labour no. 6 & 7)
				\$ 6,784.40	\$ 5,665.40 4919.40
Less Discount : 10%				\$ 678.44	10% \$ 566.54
List Parts Sub-Total :				\$ 6,105.96	\$ 5,098.86 4429.46
1	1 set	Rr reverse sensor	Dented/Damaged	\$ 250.00	\$ 220.00 200
2	1 pc	Rr reverse camera	Dented/Damaged	\$ 280.00	\$ 250.00 200
Special Nett Sub-Total :				\$ 530.00	\$ 470.00 400.
Parts Total :				\$ 6,635.96	\$ 5,568.86



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvos@hotmail.com

Business Reg. 201404434D

Vehicle No. : SJC8403J

Report No. : PAS/TP/0360719

S/No.	Labour Descriptions	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	To check rear electrical wiring system.	\$ 60.00	\$ 50.00 ³⁰
2	To transfer boot component parts to new boot. (Include install rear spoiler and supply sealant)	\$ 160.00	\$ 140.00 ⁶⁰
3	To remove and reinstall rear interior trims, garnishes, etc. for necessary repairs.	\$ 150.00	\$ 120.00 ⁶⁰
4	To remove, replace and reinstall rear reverse sensors & control unit.	\$ 50.00	\$ 30.00 ¹
5	To remove, replace and reinstall rear reverse camera.	\$ 50.00	\$ 50.00 ³⁰
6	To straighten, repair, realign on affected area and replace damaged parts.	\$ 1,000.00	\$ 770.00 ⁶⁰⁰
7	To spray painting, blending on affected and adjacent area.	\$ 1,400.00	\$ 1,200.00 ¹⁰⁰⁰
8	To spray anti-rust coating on new and affected panels.	\$ 90.00	\$ 60.00 ⁵⁰
Labour Total :		\$ 2,960.00	\$ 2,420.00 ¹⁸⁰⁰
Total (Parts & Labour) :		\$ 9,595.96	\$ 7,988.86 ^{6687.46}

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 6,390.00

Under normal circumstances, the repairs should be completed within a reasonable period

of **7 Working Days.** (Exclude waiting days of PRI, Sunday, Public Holiday and awaiting of shipment for spare parts)

66 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall have the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Jul 2019		26 Jul 2019 15:09 Edit Adj Rpt	S\$5,350.00 Edit Estimates	S\$5,350.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:	ZERO SPORT LAUNDRY SERVICE PTE LTD , Co. Reg. No.: 199707580W								
Main Claimant:	TAN CHEE KIONG , ID: S7638133Z								
Vehicle Reg. No.:	SJC8403J	Date of Loss:	23/07/2019 00:00 - :59 [136 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 600930	Policy/Cover Note No.:	29098105MKC Coverage: 28/09/2018 - 27/09/2019						
Vehicle Reg. No. (Insured):	YP9349E	Policy No. (Claimant):							
		Excess:							
Repairer:	C H Motor Vehicle Repair Training (HQ) Blk 3019A Ubi Road 1 #01-30, 408713 Ubi - Tel: 68418841								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 16/10/2019]								
Driver/Custodian (Insured):	HAN JIFU (), NRIC: G8484636N Email:								
Adj Asg. Remarks:	on WP. (Manual Assign). Liab: 100%. Disagree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Mr Joe @ 6841 8841 / 6748 8888. Manual assigned to LKK via email on 26/07/19.								
ASSOCIATED MAIL RECEIVED			View All Compose Case Mail						
<ul style="list-style-type: none"> MSIG_SG (14/10/2019): Report Send Back Alerts - SJC8403J (TP) 									
ALL ASSOCIATED TASKS			View All Search Tasks Create New Task Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

94

Claim Documents

*SJC8403J (600930)

[YP9349E]









































TP

TAN CHEE KIONG


Jul 23 2019 12:00AM

[ZERO SPORT LAUNDRY SERVICE PTE LTD]

C H Motor Vehicle Repair Training

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
2	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
3	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
4	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
5	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
6	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
7	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
8	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
9	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
10	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
11	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
12	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
13	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
14	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
15	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
16	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
17	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
18	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
19	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
20	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
21	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
22	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
23	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
24	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
25	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
26	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
27	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
28	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
29	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
30	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
31	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
32	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
33	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
34	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
35	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
36	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
37	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
38	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
39	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>
40	30/07/19 15:18	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	30/07/19 15:18	General View		<input checked="" type="checkbox"/>
42	30/07/19 15:18	General View		<input checked="" type="checkbox"/>
43	30/07/19 15:18	General View		<input checked="" type="checkbox"/>
44	30/07/19 15:18	General View		<input checked="" type="checkbox"/>
45	30/07/19 15:18	General View		<input checked="" type="checkbox"/>
46	30/07/19 15:18	General View		<input checked="" type="checkbox"/>
47	30/07/19 15:18	General View		<input checked="" type="checkbox"/>
48	30/07/19 15:18	General View		<input checked="" type="checkbox"/>
49	30/07/19 15:18	General View		<input checked="" type="checkbox"/>
50	30/07/19 15:18	General View		<input checked="" type="checkbox"/>
51	30/07/19 15:18	General View		<input checked="" type="checkbox"/>
52	30/07/19 15:18	General View		<input checked="" type="checkbox"/>
53	30/07/19 15:19	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
54	30/07/19 15:19	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
55	30/07/19 15:19	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
56	30/07/19 15:19	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
57	30/07/19 15:19	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
58	30/07/19 15:19	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
59	30/07/19 15:19	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
60	30/07/19 15:19	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
61	30/07/19 15:19	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
62	30/07/19 15:19	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
63	30/07/19 15:19	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
64	30/07/19 15:19	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
65	30/07/19 15:19	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
66	30/07/19 15:19	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
67	30/07/19 15:19	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
68	30/07/19 15:19	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
69	30/07/19 15:19	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
70	30/07/19 15:19	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
71	29/08/19 17:18	Photo After Spray		<input checked="" type="checkbox"/>
72	29/08/19 17:18	Photo After Spray		<input checked="" type="checkbox"/>
73	29/08/19 17:18	Photo After Spray		<input checked="" type="checkbox"/>
74	29/08/19 17:18	Photo After Spray		<input checked="" type="checkbox"/>
75	29/08/19 17:18	Photo After Spray		<input checked="" type="checkbox"/>
76	29/08/19 17:18	Photo After Spray		<input checked="" type="checkbox"/>
77	29/08/19 17:18	Photo After Spray		<input checked="" type="checkbox"/>
78	29/08/19 17:18	Photo After Spray		<input checked="" type="checkbox"/>
79	29/08/19 17:18	Photo After Spray		<input checked="" type="checkbox"/>
80	29/08/19 17:18	Photo After Spray		<input checked="" type="checkbox"/>
81	29/08/19 17:18	Photo After Spray		<input checked="" type="checkbox"/>
82	29/08/19 17:18	Photo After Spray		<input checked="" type="checkbox"/>
83	29/08/19 17:18	Photo After Spray		<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/07/19 11:49	Email - PRI		
2	26/07/19 11:50	SJC8403J GIA Rpt		
3	26/07/19 11:51	YP9349E GIA Rpt		
4	26/07/19 11:55	Workshop Details		
5	26/07/19 11:55	Disagree on SJE		
6	14/10/19 12:57	Survey report		
7	14/10/19 12:57	Survey photos		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	26/07/19 15:07	Survey Request - Manual Assigned		

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	01/11/19 11:17	PRS INVOICE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19013194/T1SF3S2-1
Date: 01/11/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29098105MKC
Claimant Vehicle No :	SJC8403J	Insured Vehicle No :	YP9349E
Date of Loss:	23/07/2019	Nature of Claim:	TP
		Claim No:	600930

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJC8403J	Engine No:	4B11AX6148
Make & Model:	MITSUBISHI EVO 10, 2.0 GSR (M)	Chassis No:	CZ4A0000976
Reg. Date:	29/02/2008 (Man. Year: 2007)	Odometer:	41899 km
Colour:	Blue		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/35 R19	Rear Tyre Size:	205/35 R19
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,635.96	4,827.46	1,808.50	27.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,960.00	1,860.00	1,100.00	37.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,595.96	6,687.46	2,908.50	30.31
Approved Total (Overridden) (S\$)		5,350.00		
Nett Amount (S\$)	9,595.96	5,350.00	4,245.96	44.25

INSPECTION

Date of Assignment:	26/07/2019	
Date Inspected:	26/07/2019	Inspected At: C H Motor Vehicle Repair Training (HQ) Blk 3019A Ubi Road 1 #01-30 Singapore 408713
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Nov 2019)
Parts:	143	mitsubishi EVO 10 2.0 GSR (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJC8403J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	831.00 FL	*831.00 FL
2	1		*BOOT LID THIRD BRAKE LAMP	Dented / Cracked	324.00 FL	*324.00 FL
3	2		*BOOT LID REFLECTOR LAMP R/L	Cracked	364.00 FL	*364.00 FL
4	1		*BOOT LID EMBLEM (LOGO)	Necessary	48.00 FL	*48.00 FL
5	1		*BOOT LID EMBLEM (LANCER)	Necessary	40.00 FL	*40.00 FL
6	1		*BOOT LID EMBLEM (EVOLUTION)	Necessary	62.00 FL	*62.00 FL
7	1		*BOOT LID LOCK SWITCH SEAL	Necessary	18.00 FL	*18.00 FL
8	1		*BOOT LID LINING	Refit	147.00 FL	*- FL
9	7		*BOOT LID LINING CLIP	Necessary	21.00 FL	*21.00 FL
10	1		*BOOT LID LOCK (W/MOTOR)	Bent / Damaged	169.00 FL	*169.00 FL
11	1		*BOOT LID LOCK STRIKER	Serviceable	65.00 FL	*- FL
12	1		*BOOT LID WEATHERSTRIP	Torn / Necessary	167.00 FL	*167.00 FL
13	1		*BOOT LID SPOILER	Dented / Cracked	1,283.40 FL	*1,283.40 FL
14	2		*TAILLAMP R/L	Broken / Cracked	688.00 FL	*688.00 FL
15	1		*RR BUMPER	Dented	724.00 FL	*724.00 FL
16	1		*RR BUMPER DIFFUSER	Refit	396.00 FL	*- FL
17	6		*RR BUMPER CLIP	Necessary	18.00 FL	*18.00 FL
18	2		*RR BUMPER RETAINER R/L	Necessary	76.00 FL	*76.00 FL
19	1		*RR BUMPER BEAM	Dented / Bent	86.00 FL	*86.00 FL
20	1		*RR BUMPER REINFORCEMENT	Refit	393.00 FL	*- FL
21	2		*RR BUMPER NO. PLATE LAMP	Serviceable	144.00 FL	*- FL
22	1		*RR END PANEL	Repair	521.00 FL	*- FL
23	1		*RR END PANEL TRIM	Refit	183.00 FL	*- FL
24	4		*RR END PANEL TRIM CLIP	Serviceable	16.00 FL	*- FL
25	1		*RR FENDER R/L (NPA)	Repair	0.00 FL	*- FL
26	1		*RR FLOOR PANEL (NPA)	Repair	0.00 FL	*- FL
27	1		*SET RR REVERSE SENSOR	Dented / Damaged	250.00 FS	*200.00 FS
28	1		*RR REVERSE CAMERA	Dented / Damaged	280.00 FS	*200.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	7,314.40	5,319.40
- List Item Discount on L Items 10.00/10.00% (\$\$)	678.44	491.94
Total Parts (\$\$)	6,635.96	4,827.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR ELECTRICAL WIRING SYSTEM.	New	60.00	30.00
2	TO TRANSFER BOOT COMPARTMENT PART TO NEW BOOT. (INCLUDE INSTALL REAR SPOILER AND SUPPLY SEALANT)	New	160.00	60.00
3	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS, GARNISHES, ETC. FOR NECESSARY REPAIRS.	New	150.00	60.00
4	TO REMOVE, REPLACE AND REINSTALL REAR REVERSE SENSOR & CONTROL UNIT.	New	50.00	30.00
5	TO REMOVE, REPLACE AND REINSTALL REAR REVERSE CAMERA.	New	50.00	30.00
6	TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS.	New	1,000.00	600.00
7	TO SPRAY PAINTING, BLENDING ON AFFECTED AND ADJACENT AREA.	New	1,400.00	1,000.00
8	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS.	New	90.00	50.00
Gross Labour Cost (\$\$)			2,960.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >