

ASS. REC. BY:

REF: CS/MSG19018305/T2y f3⁰⁷

Special Instruction:

Surveyor: Taufikn ASSIGNMENT (Office)

From (Person): monica chung pei zhu of MSLG Date/Time: 16.10.19 16.16p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMC 25074 Insured: SKC 4518B

at Workshop m/s: Hin Lung workshop Tel: 68583000

of Blok 1008 Bukit merah lane 3 #01-20

Policy No: 28677091 Claim No: 607910

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 6.10.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 16.10.19 4.54 p.m Person Contacted: Anna

H.O.D. Endorsement: _____

Vehicle IN / OUT

Photo O.K

Meriman

"imp"

Date/Time	Action/Instruction (✓) Estimate
	SMC 25074 - X
	SKC 4518B - X

Tanpin

REF: MS19

ASS. REC. BY:

ASSIGNMENT

From: _____ Date: 18-10-2019

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMC 25074

at Workshop m/s Hin Lung workshop

of B1c 1008 Bukit Merah Law 3 #01-20

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: H.00A.M own way

Veh No: SMC 25074 Yr Regn: 208, June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Hyundai Accent c.c 1368

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 4594 T/Radio: Insured / Std / NI / NA

Eng/No: 4594

C/No: KM HCY415TJ1433826

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175 / 70R14
R: _____

N/S	O/S

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{mp}

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Yunko

Front		Rear	
R/Bal. <u>7</u> mm		R/Bal. <u>7</u> mm	
L/Bal. <u>7</u> mm		L/Bal. <u>7</u> mm	
D.O.A. _____		D.O.I. <u>18/10/19</u>	

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or Frnt O/S, U/C

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
24/10/19	Sent Preli by merimer
14/11/19	\$2479.20 4 days (Red \$8133-80, 76%)

RECEIVED 15 NOV 2019

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to? _____

2) 15/11/19 Typist

Rep. Form: _____

Lump Sum / R.R. / C/P: _____

PIP \$2479-20

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$))
 : Interview (\$))
 : Tech. Invs (\$))
 : Weekend (\$))

Survey Fee: _____

Transportation: _____

S+RS: SI 200

Other: 11

TOTAL 211

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 24 Oct 2019

Preliminary Advice

Insured Vehicle No	: SKC4518B	Accident Date	: 06/10/2019
TP Vehicle No	: SMC2507Y	Assignment Date	: 16/10/2019
Make	: HYUNDAI ACCENT	Est. Duration of Repair	: 4.00
Date of Inspection	: 18/10/2019		
Inspection At	: HIN LUNG WORKSHOP (HQ) BLK 1008 BUKIT MERAH LANE 3, #01-20 SINGAPORE 159722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,613.00
Revised Amount	:S\$	2,849.00
Check Items (Estimated)	:S\$	2,305.00
Total	:S\$	5,154.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Oct 2019 13:42		16 Oct 2019 16:16 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	MOHAMED NASEEM, ID: S2020315C, Tel: +6597871409								
Main Claimant:	SEAH TECK KHIM, ID: S6921670F								
Vehicle Reg. No.:	SMC2507Y	Date of Loss:	06/10/2019 16:00 - :59 [15 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 607910	Policy/Cover Note No.:	28677091 (Comprehensive) Coverage: 01/03/2019 - 29/02/2020						
Vehicle Reg. No. (Insured):	SKC4518B	Policy No. (Claimant):	P2148314						
Repairer:	Hin Lung Workshop (HQ) Bik 1008 Bukit Merah Lane 3, #01-20, 159722 Bukit Merah - Tel: 68583000								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 17/10/2019]								
Driver/Custodian (Insured):	MOHAMED NASEEM (70 / Male), NRIC: S2020315C, Tel: +6597871409 Email:								
Adj Asg. Remarks:	Survey appt 18/10/19, 11am. Owner waiting. on WP. Please contact us ASAP if you cannot attend this assignment. Liab: unclear. Contact: Anna @ 6858 3000.								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	670F
Vehicle Details	
Vehicle No.:	SMC2507Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	07 Oct 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	ACCENT (RB) 1.4 CVT
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	G4LCJU000858
Chassis No.:	KMHCU41BTJU433826
Maximum Power Output:	73.6 kW (98 bhp)
Open Market Value:	\$7,928.00
Original Registration Date:	28 Jun 2018
First Registration Date:	28 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$7,928.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jun 2028
PARF Rebate Amount:	\$5,946.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jun 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,001.00
COE Rebate Amount:	\$30,400.00
Total Rebate Amount:	\$36,346.00

The information contained herein is correct as at 07 Oct 2019

OK

HIN LUNG WORKSHOP

Blk 1008 Bukit Merah Lane 3 #01-20, S'pore 159722. Tel: 68583000 Fax: 64760075
 Website: www.hinlung.com.sg GST Regn. No: M2-0065859-X

Your Ref:
 Our Ref : 0673/10/19
 M/s : MSIG INSURANCE (SINGAPORE) PTE LTD
 4 SHENTON WAY #21-01 SGX CENTRE 2
 SINGAPORE 068807

Page: 1
 Date: 10/10/2019

Attn : MOTOR CLAIM DEPARTMENT

Dear Sir/Madam,

ACCIDENT REPAIR ON : SMC2507Y - ACCENT (RB) 1.4 CVT 0
 INSURED : SEAH TECK KHIM
 DATE OF ACCIDENT : 06/10/2019
 YOUR INSURED VEH NO: SKC4518B

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED:-

		S\$	S\$	S\$
REPLACEMENT OF PARTS				
1 FRONT BUMPER	1 @	430.00	430.00 <i>de</i>	
2 BRACKET - FRONT BUMPER, RH	1 @	18.00	18.00 <i>de</i>	
3 FRONT BUMPER ABSORBER	1 @	155.00	155.00 <i>x un</i>	
4 RAIL ASSY - FRONT BUMPER	1 @	280.00	280.00 <i>x un</i>	
5 BRACKET - FRONT BUMPER UPPER SIDE MOUNTING, RH.	1 @	24.00	24.00 <i>de</i>	
6 BUMPER CLIPS	10 @	5.00	50.00 <i>some</i>	
7 LAMP ASSY - HEAD RH	1 @	705.00	705.00 <i>cut</i>	
8 GUARD ASSY - FRONT WHEEL, RH	1 @	78.00	78.00 <i>de</i>	
9 KNUCKLE - FRONT AXLE, RH	1 @	375.00	375.00 <i>x un</i>	
10 FENDER RH	1 @	564.00	564.00 <i>bt</i>	
11 BEARING - FRONT WHEEL HUB	1 @	125.00	125.00 <i>x</i>	} <i>un</i>
12 COVER - FRONT BRAKE DISC DUST, RH	1 @	55.00	55.00 <i>x</i>	
13 HUB ASSY - FRONT WHEEL	1 @	160.00	160.00 <i>x</i>	
15 DISC - FRONT WHEEL BRAKE	1 @	170.00	170.00 <i>x</i>	
16 STRUT ASSY - FRONT, RH	1 @	285.00	285.00 <i>x</i>	
17 TYRE - FRONT RH	1 @	120.00	120.00 <i>x</i>	
18 TIE RODS	1 @	65.00	65.00 <i>x</i>	
19 TIE RODS END	1 @	65.00	65.00 <i>x</i>	
20 LOWER ARM	1 @	285.00	285.00 <i>x</i>	
21 STEERING RACK	1 @	745.00	745.00 <i>x</i>	
22 COLUMN ASSY - UPPER	1 @	3,259.00	3,259.00 <i>x</i>	} <i>20% - 1849</i>
SUB-TOTAL				8,013.00
*SPECIAL NETT				
23 WHEEL ASSY - STEEL	1 @	210.00	210.00 <i>x un</i>	
24 CAP ASSY - WHEEL HUB	1 @	90.00	90.00 <i>de</i>	

LABOUR CHARGES

1 REMOVE, REPAIR AND REPLACE PARTS FOR

1,200.00

\$00

HIN LUNG WORKSHOP

Blk 1008 Bukit Merah Lane 3 #01-20, S'pore 159722. Tel: 68583000 Fax: 64760075
 Website: www.hinlung.com.sg GST Regn. No: M2-0065859-X


Your Ref:
 Our Ref : 0673/10/19

Page: 2
 Date: 10/10/2019

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED:-

	S\$	S\$	S\$
1 THE EFFECTED AREAS.			
1			
2 SPRAY PAINT ON THE EFFECTED AREAS		900.00	400
2 WITH 2K PAINT.			
2			
3 CHECK WIRING AND PROPER FUNCTIONING.		80.00	30
3			
C4W COMPUTERISED 4 WHEEL ALIGNMENT.		120.00	80
			=====
Nett Total Before GST			10,613.00
			=====

Yours faithfully,



(Workshop Manager)

1479.20
 910
 90

 2389.20
 2479.20 #

Tanpin 97495749
 WP'

18/10/19 @ 1115

Resurvey before paint

04 days

sure (huan to...)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19018305/T1YF3N2

Date: 18/11/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28677091
Claimant Vehicle No :	SMC2507Y	Insured Vehicle No :	SKC4518B
Date of Loss:	06/10/2019	Nature of Claim:	TP
		Claim No:	607910

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC2507Y	Engine No:	G4LCJU000858
Make & Model:	HYUNDAI ACCENT, 1.4 (A)	Chassis No:	KMHCU41BTJU433826
Reg. Date:	28/06/2018 (Man. Year: 2018)	Odometer:	4594 km
Colour:	Red		
Engine Capacity:	1368 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	175/70R14	Rear Tyre Size:	175/70R14
Front Left Side:	Kumho 7 mm	Rear Left Side:	Kumho 7 mm
Front Right Side:	Kumho 7 mm	Rear Right Side:	Kumho 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,313.00	1,569.20	6,743.80	81.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	910.00	1,390.00	60.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,613.00	2,479.20	8,133.80	76.64
+ GST 7.00/7.00% (S\$)	742.91	173.54	569.37	76.64
Nett Amount (S\$)	11,355.91	2,652.74	8,703.17	76.64

INSPECTION

Date of Assignment:	16/10/2019	
Date Inspected:	18/10/2019	Inspected At:
		Hin Lung Workshop (HQ) Bik 1008 Bukit Merah Lane 3, #01-20 Singapore 159722

Estimated Period of Repair: 4.0 days**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Nov 2019)	
Parts: 144	HYUNDAI ACCENT 1.4 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SMC2507Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	430.00 F	*430.00 FL
2	1		*BRACKET-FRONT BUMPER,RH	Deformed	18.00 F	*18.00 FL
3	1		*FRONT BUMPER ABSORBER	Not Necessary	155.00 F	*- FL
4	1		*RAIL ASSY-FRONT BUMPER	Not Necessary	280.00 F	*- FL
5	1		*BRACKET-FRONT BUMPER UPPER SIDE MOUNTING,RH	Deformed	24.00 F	*24.00 FL
6	10		*BUMPER CLIPS	Necessary	50.00 F	*30.00 FL
7	1		*LAMP ASSY-HEAD RH	Cut	705.00 F	*705.00 FL
8	1		*GUARD ASSY-FRONT WHEEL,RH	Deformed	78.00 F	*78.00 FL
9	1		*KNUCKLE-FRONT AXLE,RH	Not fitted	375.00 F	*- FL
10	1		*FENDER RH	Bent	564.00 F	*564.00 FL
11	1		*BEARING-FRONT WHEEL HUB	Not Necessary	125.00 F	*- FL
12	1		*COVER-FRONT BRAKE DISC DUST,RH	Not Necessary	55.00 F	*- FL
13	1		*HUB ASSY-FRONT WHEEL	Not Necessary	160.00 F	*- FL
14	1		*DISC-FRONT WHEEL BRAKE	Not Necessary	170.00 F	*- FL
15	1		*STRUT ASSY-FRONT,RH	Not Necessary	285.00 F	*- FL
16	1		*TYRE-FRONT RH	Not Necessary	120.00 F	*- FL
17	1		*TIE RODS	Not Necessary	65.00 F	*- FL
18	1		*TIE RODS END	Not Necessary	65.00 F	*- FL
19	1		*LOWER ARM	Not Necessary	285.00 F	*- FL
20	1		*STEERING RACK	Not Necessary	745.00 F	*- FL
21	1		*COLUMN ASSY-UPPER	Not Necessary	3,259.00 F	*- FL
22	1		*WHEEL ASSY-STEEL	Not Necessary	210.00 FS	*- FS
23	1		*CAP ASSY-WHEEL HUB	Deformed	90.00 FS	*90.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,313.00	1,939.00
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	369.80
Total Parts (S\$)	8,313.00	1,569.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE,REPAIR AND REPLACE PARTS FOR THE EFFECTED AREAS	New	1,200.00	400.00
2	SPRAY PAINT ON THE EFFECTED AREAS WITH 2K PAINT	New	900.00	400.00
3	CHECK WIRING AND PROPER FUNCTIONING	New	80.00	30.00
4	COMPUTERISED 4 WHEEL ALIGNMENT	New	120.00	80.00
Gross Labour Cost (S\$)			2,300.00	910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >