



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 3120S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT HEADLAMP (N) (CONSISTENT)	SCRATCHED / CRACKED	1,617.00	1,617.00
1	FRONT GRILLE (N) (CONSISTENT)	NOT NECESSARY	322.40	-
1	FRONT GRILLE LOGO (N) (CONSISTENT)	NOT NECESSARY	58.40	-
1	FRONT BUMPER (N) (CONSISTENT)	DISTORTED	1,855.00	646.00
1	FRONT BUMPER FOG LAMP RIM (N) (CONSISTENT)	NOT NECESSARY	102.00	-
1	FRONT BUMPER INNER SPONGE (N) (CONSISTENT)	TORN	207.20	207.20
1	FRONT BUMPER REINFORCEMENT TOP (N) (CONSISTENT)	NOT NECESSARY	591.90	-
2	FRONT BUMPER SIDE RETAINERS (N) (CONSISTENT)	N/S BENT	54.60	27.30
1	FRONT FENDER -L/H (N) (CONSISTENT)	BENT / BUCKLED	622.70	622.70
1	FRONT FENDER ARCH GARNISH (N) (CONSISTENT)	TORN	541.40	541.40
1	FRONT KNUCKLE ARM (N) (CONSISTENT)	NOT NECESSARY	676.70	-
1	FRONT LOWER ARM (N) (CONSISTENT)	NOT NECESSARY	248.60	-
	LESS 10% DISCOUNT		-689.79	-366.16
			6,208.11	3,295.44
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	35.00	35.00
1	FRONT BUMPER FOG LAMP (SN) (CONSISTENT)	CRACKED	279.20	279.20
1	FRONT TYRE (SN) (CONSISTENT)	NOT NECESSARY	400.00	-
1	FRONT WHEEL RIM -L/H (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	850.00	-
1	FRONT SHOCK ABSORBER (SN) (CONSISTENT)	NOT NECESSARY	453.20	-
			2,017.40	314.20
<b><u>LABOUR</u></b>				
	TO CHECK WIRING AND RESETTING HEADLAMPS FOCUSING.		80.00	20.00
	TO REMOVE AND REFIT FRONT UNDERCARRIAGE .	NOT NECESSARY	300.00	-
	TO CONDUCT WHEEL ALIGNMENT .		150.00	60.00
	TO APPLY UNDERCOATING.		100.00	30.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT WHEEL RIM -L/H .		1,400.00	400.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS .		1,200.00	600.00
			3,230.00	1,110.00
	<b>GRAND TOTAL</b>		<b>11,455.51</b>	<b>4,719.64</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,700.00</b>

Report Ref No. CC4/ASM19018321/Ugs3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.