

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119018323/EYF3E2

Date: 22/06/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN30972918011

Claimant Vehicle
No : PC5554EInsured Vehicle
No : GBG9913X

Date of Loss: 10/10/2019

Nature of Claim: TP

Claim
No: SNM19D204881C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PC5554E**

Make & Model: KING LONG XMQ6902K, 6.7 D (A)

Engine No: ISB67E522522003479

Reg. Date: 10/09/2015 (Man. Year: 2014)

Chassis No: LA6R1DSC4EB103121

Colour: Multi-colour

Odometer: 164387 km

Engine Capacity: 6690 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/70 R22.5	Rear Tyre Size:	255/70 R22.5 (D)
Front Left Side:	OHTSU 5 mm	Rear Left Side:	OHTSU 5/5 mm
Front Right Side:	OHTSU 5 mm	Rear Right Side:	OHTSU 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,854.00	588.50	1,265.50	68.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	1,600.00	1,600.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,054.00	2,188.50	2,865.50	56.70
Approved Total (Overridden) (S\$)		1,750.00		
(S\$)	5,054.00	1,750.00	3,304.00	65.37
+ GST 7.00/7.00% (S\$)	353.78	122.50	231.28	65.37
Nett Amount (S\$)	5,407.78	1,872.50	3,535.28	65.37

INSPECTION

Date of Assignment: 17/10/2019

Date Inspected: 21/10/2019 Inspected At:

LexBuild International Pte Ltd (HQ)
2 WOODLANDS SECTOR 1, #05-12
(WOODLANDS SPECTRUM 1)
SINGAPORE 738068

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 21 Jun 2020)	
Parts:	N/A	KING LONG XMQ6902K 6.7 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC5554E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	3		*PANEL LOCK	Not Necessary	105.00 F	*- FL
2	3		*MARKER LAMP	Not Necessary	84.00 F	*- FL
3	1		*COMPARTMENT DOOR HANDLE	Cut	75.00 F	*75.00 FL
4	1		*TYRE RIM COVER	Cut	1,400.00 F	*400.00 FL
5	1		*ROAD LAMP	Cut	90.00 F	*90.00 FL
6	1		*COMPANY STICKER	Necessary	100.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,854.00	645.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	56.50
Total Parts (S\$)	1,854.00	588.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO SUPPLY SKILLED LABOUR TO REPAIR, PUTTY, GRINDING AND SPRAY PAINT LHS 2ND BIG LUGGAGE COMPARTMENT PANEL, REAR LHS WHEELARC PANEL, LHS 2ND LAST BODYPANEL WITH COVER, LHS LAST GRILL PANEL (3-COLOR CODE) 4 DAYS	New	3,200.00	1,600.00
Gross Labour Cost (S\$)			3,200.00	1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >