

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG19018337/ASF3E2  
**Date:** 04/01/2021

### REFERENCE

Insured/Claimant: HAN DONG Policy No: 1900110506  
Date of Loss: 12/10/2019 Nature of Claim: OD Claim No: 9920739512SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKB123M**  
Make & Model: AUDI Q8, 3.0 TFSI QU TIP (A) Engine No: DCB051796  
Reg. Date: 28/06/2019 (Man. Year: 2018) Chassis No: WAUZZZF1XKD010190  
Colour: Grey Odometer: 2709 km  
Engine Capacity: 2995 cc  
Market Value/New Car Price: S\$320,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 285/45 R21 Rear Tyre Size: 285/45 R21  
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm  
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,085.00	2,578.40	5,506.60	68.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,802.00	3,252.00	2,550.00	43.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>13,887.00</b>	<b>5,830.40</b>	<b>8,056.60</b>	<b>58.02</b>
<b>- Excess (S\$)</b>	700.00	700.00	0.00	0.00
<b>(S\$)</b>	13,187.00	5,130.40	8,056.60	61.10
<b>+ GST 7.00/7.00% (S\$)</b>	923.09	359.13	563.96	61.09
<b>Nett Amount (S\$)</b>	<b>14,110.09</b>	<b>5,489.53</b>	<b>8,620.56</b>	<b>61.10</b>

### INSPECTION

Date of Assignment: 17/10/2019  
Date Inspected: 17/10/2019 Inspected At: Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699  
Estimated Period of Repair: 4.0 days

**Adjuster:** ADRIAN LING

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,306.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS - FRONT	Not Necessary	342.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - RH	Not Necessary	109.00 FS	*- FS
4	1		*FRONT BUMPER FRAME - RH	Not Necessary	74.00 FS	*- FS
5	1		*FRONT BUMPER COVER - RH	Not Necessary	74.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT - CENTRE	Not Necessary	253.00 FS	*- FS
7	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	191.00 FS	*- FS
8	1		*FRONT BUMPER SPOILER - RH	Cut	192.00 FS	*153.60 FS
9	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	167.00 FS	*- FS
10	1		*ULTRASOUND SENSOR SUPPORT - RH	Not Necessary	26.00 FS	*- FS
11	1		*FRONT BUMPER BRACKET - RH	Not Necessary	31.00 FS	*- FS
12	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	40.00 FS	*- FS
13	1		*FRONT PARKING AID SENSOR	Not Necessary	231.00 FS	*- FS
14	4		*FRONT PARKING AID SEAL RING	Not Necessary	12.00 FS	*- FS
15	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	232.00 FS	*- FS
16	1		*REAR WHEEL HOUSING LINER - RH	Not Necessary	232.00 FS	*- FS
17	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	66.00 FS	*- FS
18	1		*FRONT SPOILER - RH	Not Necessary	62.00 FS	*- FS
19	2		*FRONT WHEEL COVER - LH / RH	Necessary	1,044.00 FS	*834.40 FS
20	1		*FRONT ALUMINIUM RIM - RH	Cut	1,988.00 FS	*1,590.40 FS
21	4		*ALUMINIUM RIM RUBBER VALVE	Not Necessary	13.00 FS	*- FS
22	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 8,085.00 2,578.40

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, RHS FRONT BUMPER SPOILER AND BOTH FRONT WHEEL ARCH TRIMS	New	3,500.00	1,800.00
3	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
5	TO DISMANTLE AND RENEW FRONT BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,350.00	500.00
<b>Gross Labour Cost (S\$)</b>			<b>5,802.00</b>	<b>3,252.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >