

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19018353/R1EA3Q2

Date: 17/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant

Vehicle No : SMP5439Y

Insured Vehicle No : SLZ5774M

Date of Loss: 15/10/2019

Nature of Claim: TP

Claim No: 9157399871SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMP5439Y

Make & Model: SKODA KODIAQ, 1.4 (A)

Engine No: CZD737272

Reg. Date: 30/09/2019 (Man. Year: 2019)

Chassis No: TMBKC7NSXK8071990

Colour: Green

Odometer: 912 km

Engine Capacity: 1395 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18

Rear Tyre Size: 235/55 R18

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,198.08	4,789.16	2,408.92	33.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,000.00	5,020.00	3,980.00	44.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,198.08	9,809.16	6,388.92	39.44
+ GST 7.00/7.00% (S\$)	1,133.87	686.64	447.23	39.44
Nett Amount (S\$)	17,331.95	10,495.80	6,836.15	39.44
+ Car Rental (7.0 x S\$80.00/day + 7.00% GST) (S\$)		599.20		
	Nett Liability (S\$)	11,095.00		

INSPECTION

Date of Assignment: 21/10/2019

Date Inspected: 21/10/2019 **Inspected At:**

Volkswagen Centre Singapore (HQ)

247 Alexandra Road

Singapore 159934

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR (REAR BUMPER COVER)	Repair	1,740.00 FS	*- FS
2	1		*COVER FOR (BUMPER LOWER COVER BLACK)	Scratched	571.00 FS	*571.00 FS
3	1		*FOAM REINF	Serviceable	129.00 FS	*- FS
4	1		*BUMPE STRIP	Serviceable	226.00 FS	*- FS
5	1		*RETAINING (REAR BUMPER RETAINER)	Serviceable	70.90 FS	*- FS
6	1		*COVER FOR (TOWING COVER)	Scratched	25.80 FS	*25.80 FS
7	1		*GUIDE PIEC (BUMPER GUIDE RH)	Serviceable	42.50 FS	*- FS
8	1		*GUIDE PIEC (BUMPER BRACKET RH)	Serviceable	42.50 FS	*- FS
9	1		*REFLECTOR (RH REFLECTOR)	Serviceable	35.00 FS	*- FS
10	1		*SENSOR BRA	Necessary	13.00 FS	*13.00 FS
11	1		*SENSOR BRA	Necessary	13.00 FS	*13.00 FS
12	1		*SENSOR BRA	Necessary	13.00 FS	*13.00 FS
13	1		*SENSOR BRA	Necessary	13.00 FS	*13.00 FS
14	1		*SENSOR BRA	Necessary	13.00 FS	*13.00 FS
15	1		*SENSOR BRA	Necessary	13.00 FS	*13.00 FS
16	1		*BONDING AGENT FOR PLASTIC	Necessary	56.90 FS	*56.90 FS
17	1		*2K-PLASTIC ADHESIVE	Necessary	74.29 FS	*74.29 FS
18	1		*REAR TRUNK	Bent	3,535.00 FS	*3,535.00 FS
19	1		*INSCRIPTIO(SKODA)	Necessary	72.80 FS	*72.80 FS
20	1		*LETTERING	Necessary	98.50 FS	*98.50 FS
21	1		*2K-GLASS GLUE APPLICATION	Not Necessary	123.02 FS	*- FS
22	1		*PRIMER	Necessary	25.92 FS	*25.92 FS
23	2		*APPLICATOR	Necessary	18.96 FS	*18.96 FS
24	1		*ACTIVATOR FOR PRECOATED W	Necessary	24.00 FS	*24.00 FS
25	1		*ALL PURPOSE CLEANER	Necessary	89.95 FS	*89.95 FS
26	1		*1K WINDOW ADHESIVE	Necessary	49.88 FS	*49.88 FS
27	1		*SKODA EMBI EAR EMBLEM XR-12/11/2019	Necessary	64.40 FS	*64.40 FS
28	2		*RIVETTED CAP NUT	Necessary	3.76 FS	*3.76 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **7,198.08** **4,789.16**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
2	CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	0.00
3	R&R REAR WINDSCREEN	New	840.00	840.00
4	LABOUR	New	3,360.00	1,680.00
5	TRANSFER BOOTLID MECHANISM PARTS	New	840.00	420.00
6	SPRAY PAINTING	New	3,200.00	1,600.00
Gross Labour Cost (\$)			9,000.00	5,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >