12/10/21, 2:50 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/AIG19018356/KPS3Q2

Date:

10/12/2021

REFERENCE

Date of Loss:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

14/10/2019

Policy No:

2100506588-02

Claimant Vehicle No: SHC5850U Insured Vehicle No:

Nature of Claim:

SCW222U ΤP

Claim No: 2977295767SG

652563 km

M9R8839C002341

VF1ABL15AUC280925

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC5850U

Make & Model: RENAULT LATITUDE, 2.0 D dCi (A)

Reg. Date: 11/12/2014 (Man. Year: 2014)

Colour: Metallic White/Red

Engine Capacity: 1995 cc Market Value/New Car Price: N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good

Steering (Serviceable):

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

Yes No

Pre-accident Condition:

Engine No:

Chassis No:

Odometer:

CONDITION OF TYRES

Front Tyre Size: Front Left Side:

Front Right Side:

215/60 R16 Sailun 9 mm Rear Tyre Size: Rear Left Side:

215/60 R16 Giti 4 mm

Sailun 9 mm

Rear Right Side:

Giti 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		10,196.23	1,989.20	8,207.03	80.49
Miscellaneous Items		0.00	0.00	0.00	
Labour		14,720.00	490.00	14,230.00	96.67
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	24,916.23	2,479.20	22,437.03	90.05
	Approved Total (Overridden) (S\$)		2,000.00		

(S\$)	24,916.23	2,000.00	22,916.23	91.97
+ GST 7.00/7.00% (S\$)	1,744.14	140.00	1,604.14	91.97
Nett Amount (S\$)	26,660.37	2,140.00	24,520.37	91.97
+ Car Rental (2.0	x S\$96.99/day) (S\$)	193.98		
+ D	oc/Search Fee (S\$)	7.45		
	Nett Liability (S\$)	2,341.43		
Global St	um Settlement (S\$)	2,300.00		

INSPECTION

Date of Assignment: 16/10/2019

Trans-cab Auto Services Pte Ltd (Ang Mo Kio) Date Inspected: Inspected At: 2, Ang Mo Kio Street 63 16/10/2019

Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: **CHEW HSIAO TONG**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other circumstances is hereby expressly

REPAIR DETAILS

Recommended Parts

No. Qty Part No.	Particulars	Condition	Repairer's	Amount
1 1	*BUMPER COVER REAR	Buckled / Cracked	561.70 FL	*561.70 FL
2 1	*BUMPER LOWER REAR	Dented / Distorted	411.90 FL	*411.90 FL
3 1	*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*- FL
4 1	*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	*- FL
5 1	*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	*- FL
6 1	*BUMPER REFLECTOR RH	Serviceable	16.60 FL	*- FL
7 1	*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	*- FL
8 1	*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*- FL
9 1	*BUMPER REFLECTOR LH	Cracked	16.60 FL	*16.60 FL
10 1	*BUMPER BEAM REAR	Bent	547.80 FL	*547.80 FL
11 1	*BUMPER BEAM BRACKET LH REAR	Repair	114.50 FL	*- FL
12 1	*BUMPER BEAM BRACKET RH REAR	Repair	100.90 FL	*- FL
13 1	*OUTER PANEL REAR (END PANEL)	Repair	745.80 FL	*- FL
14 1	*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	404.56 FL	*- FL
15 1	*TAILLAMP RH	Serviceable	313.10 FL	*- FL
16 1	*TAILLAMP PANEL RH	Repair	401.40 FL	*- FL
17 1	*TAILLAMP LH	Serviceable	401.40 FL	*- FL
18 1	*TAILLAMP PANEL LH	Repair	401.40 FL	*- FL
19 1	*BOOT REAR	Repair	1,677.20 FL	*- FL
20 1	*BOOT FINISHER	Serviceable	344.70 FL	*- FL
21 1	*BOOT WEATHERSTRIP	Serviceable	178.20 FL	*- FL
22 1	*BOOT REFLECTOR LAMP LH	Serviceable	277.70 FL	*- FL
23 1	*BOOT REFLECTOR LAMP RH	Serviceable	277.70 FL	*- FL
24 1	*BOOT BADGE RENAULT	Not Necessary	82.40 FL	*- FL
25 1	*BOOT BADGE	Not Necessary	95.80 FL	*- FL
26 1	*BOOT STRUT LH	Serviceable	145.10 FL	*- FL
27 1	*BOOT STRUT RH	Serviceable	145.10 FL	*- FL
28 1	*BOOT HINGE LH	Repair	254.20 FL	*- FL
29 1	*BOOT HINGE RH	Repair	253.80 FL	*- FL
30 1	*BOOT INNER TRIM BOARD	Serviceable	611.00 FL	*- FL
31 1	*BOOT SWITCH	Serviceable	113.00 FL	*- FL
32 1	*BOOT LOCK	Repair	246.60 FL	*- FL
33 1	*BOOT LOCK CATCH	Repair	41.70 FL	*- FL
34 1	*EXHAUST CAP REAR	Serviceable	125.40 FL	*- FL
35 1	*SET PARKING AID	Shorted	700.00 FS	*400.00 FS

No. Qty Part No.	Particulars	Condition	Repairer's	Amount
36 1	*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
37 1	*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
38 1	*SE BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*-FS
39 1	*SET BUMPER RETAINER R CLIP RR	Not Necessary	20.00 FS	*-FS
40 1	*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*-FS
41 1	*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*-FS
42 1	*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*-FS
43 1	*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
44 1	*BOOT STICKER TRANS-CAB	Not Necessary	30.00 FS	*-FS
45 1	*BOOT STICKER 6555-3333	Not Necessary	30.00 FS	*-FS
46 1	*EXHAUST MOUNTING REAR	Serviceable	16.00 FS	*-FS
47 2	*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*-FS
48 1	*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
49 1	*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*-FS
50 1	*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*-FS
51 1	*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*-FS
52 1	*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*-FS
53 1	*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*-FS
54 1	*REAR BUMPER PROTECTOR	Necessary	100.00 FS	*40.00 FS
F=Franchise part. S=SpcN	lett. L=ListItemDisc.			
		Sub Total (S\$)	11,164.46	2,143.00
		- List Item Discount on L Items 10.00/10.00% (S\$)	968.23	153.80
		Total Parts (S\$)	10,196.23	1,989.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

12/10/21, 2:50 PM

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	New	380.00	0.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	170.00	0.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	170.00	10.00
5	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	New	170.00	0.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR.	New	170.00	60.00
7	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	6,000.00	200.00
8	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
9	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR.	New	170.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	0.00
11	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
12	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	New	380.00	0.00
13	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	6,000.00	220.00
14	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	New	170.00	0.00
	Gross	Labour Cost (S\$)	14,720.00	490.00
	Report was unsubmitted during this print-out.			

< END OF ESTIMATES >