

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG19018357/ARS3Q2  
**Date:** 10/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800026518
<b>Claimant Vehicle No :</b>	SFW5977G	<b>Insured Vehicle No :</b>	SLX1353G
Date of Loss:	12/10/2019	Nature of Claim:	TP
		Claim No:	7463279896SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SFW5977G</b>	Engine No:	CAV076315
Make & Model:	VOLKSWAGEN SCIROCCO, 1.4 TSI (A)	Chassis No:	WVWZZZ13Z9V032636
Reg. Date:	15/06/2009 (Man. Year: 2019)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	235/35 R19	Rear Tyre Size:	235/35 R19
Front Left Side:	Kinforest 6 mm	Rear Left Side:	Kinforest 6 mm
Front Right Side:	Kinforest 6 mm	Rear Right Side:	Kinforest 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	65,772.61	39,534.65	26,237.96	39.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,300.00	5,070.00	4,230.00	45.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>75,072.61</b>	<b>44,604.65</b>	<b>30,467.96</b>	<b>40.58</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>34,800.00</b>		

## Adjuster Report

	(S\$)	75,072.61	34,800.00	40,272.61	53.64
<b>+ GST 7.00/7.00% (S\$)</b>		5,255.08	2,436.00	2,819.08	53.64
<b>Nett Amount (S\$)</b>		<b>80,327.69</b>	<b>37,236.00</b>	<b>43,091.69</b>	<b>53.64</b>
<b>+ Loss of Use (35.0 x S\$60.00/day) (S\$)</b>			2,100.00		
	(S\$)		39,336.00		
<b>Liabe Amount (90.00%) (S\$)</b>			<b>35,402.40</b>		
<b>+ Doc/Search Fee (S\$)</b>			31.00		
<b>Nett Liability (S\$)</b>			<b>35,433.40</b>		
<b>Global Sum Settlement (S\$)</b>			<b>35,000.00</b>		

INSPECTION

Date of Assignment: 16/10/2019

Date Inspected: 16/10/2019

Estimated Period of Repair: 28.0 days

Inspected At:

Kang Car Repairers Pte Ltd (HQ)  
No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit  
Singapore 417883**Adjuster:** ADRIAN LING**Manager:** Jaslin Kok Chin Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	1,700.71 FL	*1,199.00 FL
2	1		*BONNET EMBLEM	Necessary	69.20 FL	*69.20 FL
3	1		*FRT FENDER LH	Distorted	888.96 FL	*888.96 FL
4	1		*FRT FENDER COWLING LH	Missing	230.71 FL	*230.71 FL
5	1		*HEADLAMP LH	Smashed	899.79 FL	*899.79 FL
6	1		*HEADLAMP PANEL	Not Necessary	123.71 FL	*- FL
7	1		*FRT BUMPER	Distorted	1,400.90 FL	*1,258.00 FL
8	1		*FRT BUMPER REINFORCEMENT	Not Necessary	689.89 FL	*- FL
9	1		*FRT BUMPER SPONGE	Not Necessary	199.70 FL	*- FL
10	1		*FRT BUMPER SIDE RETAINER	O/S Damaged	98.20 FL	*49.10 FL
11	1		*FRT BUMPER GRILLE	Cracked	300.93 FL	*300.93 FL
12	1		*FRT FOG LAMP LH	Cracked	200.97 FL	*200.97 FL
13	1		*FRT FOG LAMP COVER LH	Deformed	189.79 FL	*189.79 FL
14	1		*FRT LH SIGNAL LAMP	Cracked	165.80 FL	*165.80 FL
15	1		*FRT BUMPER LOWER GARNISH	Deformed	244.60 FL	*244.60 FL
16	1		*FRT GRILLE	Cracked	300.87 FL	*300.87 FL
17	1		*FRT GRILLE TOP BRACKET	Not Necessary	89.40 FL	*- FL
18	1		*FRT GRILLE TOP INNER BRACKET	Cracked	199.60 FL	*199.60 FL
19	1		*FRT SUPPORT PANEL	Cracked	1,500.93 FL	*1,055.00 FL
20	2		*FRT SUPPORT PANEL SIDE GARNISH	Deformed	97.80 FL	*97.80 FL
21	1		*AIR CONDENSER	Dented	670.00 FL	*670.00 FL
22	1		*RADIATOR	Dented	480.00 FL	*480.00 FL
23	1		*AIRCON FAN	Not Necessary	66.90 FL	*- FL
24	1		*AIRCON FAN MOTOR	Not Necessary	499.60 FL	*- FL
25	1		*RADIATOR FAN	Not Necessary	78.90 FL	*- FL
26	1		*RADIATOR FAN MOTOR	Not Necessary	386.70 FL	*- FL
27	1		*FAN COWLING	Not Necessary	274.90 FL	*- FL
28	1		*FRT DOOR LH	Dented	2,139.67 FL	*1,575.00 FL
29	2		*FRT DOOR HINGE LH	Not Necessary	138.84 FL	*- FL
30	1		*FRT DOOR CHECK LH	Not Necessary	128.50 FL	*- FL
31	1		*FRT DOOR RUBBER LH	Necessary	188.63 FL	*188.63 FL
32	1		*FRT DOOR PROTECTOR LH	Cut	193.72 FL	*193.72 FL
33	1		*FRT LH SIDE SKIRT	Deformed	699.10 FL	*699.10 FL
34	1		*FRT LH SIDE SKIRTLLOWER GARNISH	Cut	224.90 FL	*224.90 FL
35	1		*FRT SHOCK ABSORBER MOUNTING LH	Damaged	199.70 FL	*199.70 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*FRT LOWER ARM LH	Bent	500.91 FL	*500.91 FL
37	1		*FRT LOWER ARM BALL JOINT LH	Bent	197.60 FL	*197.60 FL
38	1		*FRT LOWER BRACKET LH	Cracked	398.62 FL	*398.62 FL
39	1		*FRT KNUCKLE ARM LH	Damaged	700.71 FL	*700.71 FL
40	1		*FRT WHEEL HUB AND BEARING	Damaged	689.98 FL	*689.98 FL
41	1		*FRT DRIVE SHAFT LH	Bent	2,339.97 FL	*2,016.00 FL
42	1		*FRT BRAKE ROTOR LH	Not Necessary	380.98 FL	*- FL
43	1		*ANTI ROLL BAR	Bent	500.71 FL	*500.71 FL
44	1		*ANTI ROLL BAR LINKAGE	Bent	112.80 FL	*112.80 FL
45	1		*FRT CORSSMEMBER	Bent	1,770.10 FL	*1,770.10 FL
46	1		*FRT CORSSMEMBER BRACKET LH	Damaged	487.90 FL	*487.90 FL
47	1		*STEERING RACK & PINION	Damaged	4,200.71 FL	*2,650.00 FL
48	1		*FLOORBOARD PANEL UNDER	Damaged	394.30 FL	*394.30 FL
49	1		*REAR LOWER ARM LH	Bent	497.00 FL	*497.00 FL
50	1		*REAR TOP ARM LH	Bent	398.40 FL	*398.40 FL
51	1		*REAR KNUCKLE ARM LH	Damaged	678.10 FL	*678.10 FL
52	1		*REAR WHEEL HUB LH	Damaged	426.40 FL	*426.40 FL
53	1		*REAR TRAILING ARM LH	Bent	548.90 FL	*548.90 FL
54	1		*FRT DASHBOARD	Torn	4,900.71 FL	*3,372.00 FL
55	1		*FRT STEERING AIRBAG	Activated	3,600.70 FL	*3,032.00 FL
56	1		*FRT PASSENGER STEERING AIR BAG	Activated	3,899.70 FL	*2,164.00 FL
57	1		*FRT AIRBAG CNTROL UNIT	Activated	1,477.66 FL	*748.00 FL
58	1		*FRT STEERING LOCK SENSOR	Activated	200.75 FL	*200.75 FL
59	1		*FRT SEATBELT	Activated	800.97 FL	*658.00 FL
60	1		*FRT PASSENGER SEAT BELT	Activated	800.97 FL	*658.00 FL
61	1		*REAR LH STAY ARM	Bent	303.00 FL	*303.00 FL
62	1		*AUTO GEARBOX ASSY	Cracked	14,724.81 FS	*3,000.00 FS
63	1		*FRT INTERCOOLER	Dented	697.60 FL	*697.60 FL
64	1		*SET FRT FENDER COWLING CLIPS LH	Necessary	48.00 FS	*30.00 FS
65	1		*SET FRT BUMPER GRILLE CLIPS	Necessary	40.00 FS	*20.00 FS
66	1		*SET FRT BUMPER CLIPS	Necessary	48.00 FS	*30.00 FS
67	1		*SET FRT LH SIDE SKIRT CLIPS	Necessary	40.00 FS	*40.00 FS
68	1		*FRT SOUND PROOF SEAL PROTECTOR	Necessary	1,000.00 FS	*600.00 FS
69	1		*FRT SPORTS RIM LH	Cut	1,500.00 FS	*600.00 FS
70	1		*FRT TYRE LH	Punctured	650.00 FS	*380.00 FS
71	1		*FRT SHOCK ABSORBER LH	Bent	500.00 FS	*400.00 FS
72	1		*SET FLOORBOARD PANEL UNDER CLIPS	Necessary	40.00 FS	*40.00 FS
73	1		*REAR SPORTS RIM LH	Cut	1,500.00 FS	*600.00 FS
74	1		*REAR TYRE LH	Not Necessary	650.00 FS	*- FS
75	1		*REAR SHOCK ABSORBER LH	Bent	450.00 FS	*450.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
76	1		<b>*REAR RH SPORT RIM</b>	Cut	1,500.00 FS	*600.00 FS	
					<b>Sub Total (\$\$)</b>	<b>70,559.48</b>	<b>43,172.95</b>
					<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	4,786.87	3,638.30
					<b>Total Parts (\$\$)</b>	<b>65,772.61</b>	<b>39,534.65</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TOWING	New	100.00	100.00
2	TO CHECK WIRING	New	100.00	30.00
3	TO REMOVE AND REFIT DASHBOARD	New	480.00	220.00
4	TO REMOVE AND REFIT ENGINE	New	800.00	0.00
5	TO REMOVE AND REFIT UNDERCARRIAGE (FRONT)	New	700.00	300.00
6	TO CHECK WHEEL ALIGNMENT	New	120.00	80.00
7	TO REMOVE AND REFIT UNDERCARRIAGE (REAR)	New	450.00	220.00
8	TO SPRAY UNDERSEAL	New	150.00	60.00
9	TO SPRAY PAINTING	New	1,800.00	1,400.00
10	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS ,AND FOR CUTTING/WELDING WORKS	New	2,400.00	1,400.00
11	TO REMOVE AND REFIT DOOR GLASS	New	150.00	80.00
12	TO REMOVE AND REFIX AUTO GEARBOX	New	900.00	600.00
13	TO REMOVE AND REFIX AIRBAG	New	750.00	380.00
14	TO PROGRAM AND RESET	New	400.00	200.00
			<b>Gross Labour Cost (\$)</b>	<b>9,300.00</b>
				<b>5,070.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >