

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/MSG19013820/R1VF3S2-1**Date:** 23/10/2019REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29130850APO		
Claimant Vehicle No :	SJZ4998P	Insured Vehicle No :	SMG1292B		
Date of Loss:	01/08/2019	Nature of Claim:	TP	Claim No:	601607

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJZ4998P		
Make & Model:	BMW 320I, 2.0 AT D/AB 4DR ABS HID NAV (A)	Engine No:	A1930177N20B20B
Reg. Date:	15/05/2012 (Man. Year: 2012)	Chassis No:	WBA3B12070E983530
Colour:	White	Odometer:	152126 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/40 R18	Rear Tyre Size:	235/40 R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,962.00	6,098.02	3,863.98	38.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,650.00	1,660.00	3,990.00	70.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,612.00	7,758.02	7,853.98	50.31
Approved Total (Overridden) (S\$)		6,200.00		
Nett Amount (S\$)	15,612.00	6,200.00	9,412.00	60.29

INSPECTION

Date of Assignment:	06/08/2019	
Date Inspected:	28/08/2019 Inspected At:	Mtm Performance Auto Pte Ltd 48 TOH GUAN ROAD EAST #01-115 ENTERPRISE HUB Singapore 608586
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Oct 2019)

Parts: 143 BMW 320I 2.0 AT D/AB 4DR ABS HID NAV (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJZ4998P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	1,058.30 FL	*1,058.30 FL
2	1		*REAR BUMPER CENTRE TRIM	Torn	81.20 FL	*81.20 FL
3	1		*REAR BUMPER SIDE RETAINER	Serviceable	111.50 FL	*- FL
4	1		*REAR BUMPER CENTRE BRACKET	Dented	55.75 FL	*55.75 FL
5	1		*REAR BUMPER RE-ENFORCEMENT	Serviceable	487.95 FL	*- FL
6	1		*REAR BUMPER RE-ENFORCEMENT COVER	Torn	69.80 FL	*69.80 FL
7	2		*REAR BUMPER SENSOR	Shorted	590.00 FL	*590.00 FL
8	2		*SMART SENSOR	Torn	97.00 FL	*97.00 FL
9	1		*SMART SENSOR UNIT	Serviceable	494.60 FL	*- FL
10	1		*BOOT LID	Dented	1,179.80 FL	*1,179.80 FL
11	1		*BOOT LID LOGO	Necessary	72.20 FL	*72.20 FL
12	1		*BOOT LID EMBLEM 320	Necessary	64.10 FL	*64.10 FL
13	1		*BOOT LID INNER LOCK	Dented	217.15 FL	*217.15 FL
14	1		*BOOT LID INNER RUBBER	Cut	125.45 FL	*125.45 FL
15	1		*BOOT LID LAMP	Serviceable	532.60 FL	*- FL
16	1		*TAILAMP	Cracked	760.80 FL	*760.80 FL
17	1		*REAR END PANEL	Dented	592.25 FL	*592.25 FL
18	1		*REAR END PANEL INNER GARNISH	Deformed	85.05 FL	*85.05 FL
19	1		*REAR EXHAUST CLAMP	Necessary	60.06 FL	*60.06 FL
20	1		*BOOT LID SPOILER	Serviceable	900.00 FS	*- FS
21	1		*REAR EXHAUST PIPE (REMUSE)	Bent	3,000.00 FS	*1,500.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,635.56	6,608.91
- List Item Discount on L Items 10.00/10.00% (\$\$)	673.56	510.89
Total Parts (\$\$)	9,962.00	6,098.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING SYSTEM.	New	50.00	30.00
2	TO TRANSFER BUMPER ATTACHMENT.	New	100.00	60.00
3	TO R&R REAR EXHAUST PIPE.	New	400.00	80.00
4	TO RESET AND REPROGRAMME AFTER REPAIR.	New	400.00	100.00
5	TO PANEL BEAT ON REAR BOTH FENDER. TO CUT AND WELD ON REAR END PANEL. TO R&R REAR, BOOT LID AND OTHERS ATTACHMENTS.	New	2,500.00	600.00
6	TO RESPRAY ON REAR BUMPER, BOOT LID, REAR BOTH FENDERS, REAR END PANEL AND ACCIDENT AFFECTED AREA.	New	2,000.00	750.00
7	RUST PROOFING.	New	200.00	40.00
Gross Labour Cost (\$\$)			5,650.00	1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >