




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
NEW HOCK TECK MOTOR WORKSHOP		Ref : CC4/EQI19018377/Agb3s2		
BLK 1,KAKI BUKIT AVE 6 #01-43SINGAPORE 417883		Date : 12-02-2020		
ON BEHALF OF AZMAN BIN MOHD HUSSIN		Code : TP199		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	Veh. Inspected	SKC 7711P	
	Policy No.	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From	Assign Date	01/01/1900	
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	HONDA CRV	c.c	1997
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	JHLRE2850AC200111	Colour	SILVER
	Odometer	104019	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	225/65 R17	DUNLOP	6 mm
	L/H Front Tyre	225/65 R17	DUNLOP	6 mm
	R/H Rear Tyre	225/65 R17	DUNLOP	6 mm
	L/H Rear Tyre	225/65 R17	DUNLOP	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	13/10/2019	Inspection Date	17/10/2019
	Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>16 Working Days</b>	