

ASS. REC. BY:

REF:

08/FCI 19018411/Uqd3n2

Special Instruction:

Survey:

Marcus

ASSIGNMENT (Office)

CWS

From (Person): Jason Tan

of

FCI

Date/Time: 17/10/19 @ 7pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBM 3382 K

Insured:

SHD 3569R

at Workshop m/s

Euro Success

Tel: 9828 9277

of

1 Kaki Bukit Ave 6 #02-03

Autobay

Policy No:

Claim No:

D1900657AMPST

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 11/10/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9:20am @ 18/10/19

Person Contacted:

Ah huch

Vehicle IN OUT

Date/Time

Action/Instruction

Johnny's ✓

FBM 3382K - X

SHD 3569R-CC/FCI 18022294/Kvd3n2

D.O.A. 8/10/2018

17/10/19 @ 1.57pm Informed Jason Tan, we are pending estimate from repairer.

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

Zc /
ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR / Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time Action / Instruction

11/10/19 4/5 9500 confirmed with wife (Red \$12963.70, 580%)

RECEIVED

Date/Time, File Pass to?

: Prel. Report

1) 29/10 11/10/19

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech. Invs (\$

: Weekend (\$

Photo

Others

TOTAL

12x15: 180

170+180

50

50+50

166

666

Report Format:

TP

Lump Sum / I.B.I. (\$

9500

MOTOR SURVEY ASSIGNMENT

Date	15-10-2019	Our Ref No. D19006577MFSH
Accident Date	11-10-2019	Claim Type. Third Party
Insured Vehicle	SHD3569R	Third Party Vehicle. FBM3382K
Survey Location	1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY	
Contact Person.	AH HUAT	
Contact No.	6742 6231/ 9828 9277	Fax No. 0
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	EURO SUCCESS SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JASON TEA CHEE KIAT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 21 October 2019 1:57 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Jason Tea'; SUR
Subject: RE: SURVEY ASSESSMENT - D19006577MFSH/1

Dear Jason,

Please be informed that we have inspected the vehicle FBM 3382K on 18/10/2019.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Friday, 18 October 2019 10:13 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Jason Tea' <JasonTea@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19006577MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 17 October 2019 7:00 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Jason Tea <JasonTea@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19006577MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Listing Type	Free Ad
Brand	Honda (/listing/usedbike/brand/honda/)
Model	Honda CB400X (/listing/usedbike/model/honda-cb400x/)
Engine Capacity	399cc
Classification	Class 2A (/listing/usedbike/model/motorcycle-for-sale/class/class-2a/)
Registration Date	09/06/2017
COE Expiry Date	08/06/2027 (7 years 7 months left)
Mileage	13000km
No. of owners	1
Type of Vehicle	Sport Tourers (/listing/usedbike/model/motorcycle-for-sale/sport-tourers/)

Price: SGD\$19000

DETAILS

Fuel Economy & Superb Bike. No Problem At All. Fully Serving By Boon Siew. Low Mileage. Used To Go To Work And Back Home. Seldom Ride.

Accessories

Hp Charger And Holder , Kappa Box , Headlight Guard.

Google Home Mini

Buy Google Home Mini for hands-free control of your smart home. Shop now at Google Store.



SIMILAR BIKES

[VIEW ALL \(/LISTING/USEDBIKES/LISTING/\)](#)



REPORT ERROR > (/LISTING/LISTING/ERROR/USEDBIKE/11892/) [+ ADD TO SHORTLIST](#) [Like 0](#) [Share](#)

[SHARE \(WHATSAPP://SEND?TEXT=HTTPS://WWW.SGBIKEMART.COM.SG/LISTING/USEDBIKE/HONDA-HONDA-CB400X/11892/\)](#)

Honda CB400X

Listing Type	Paid Ad
Brand	Honda (/listing/usedbike/brand/honda/)
Model	Honda CB400X (/listing/usedbike/model/honda-cb400x/)
Engine Capacity	399cc
Classification	Class 2A (/listing/usedbike/model/motorcycle-for-sale/class/class-2a/)
Registration Date	11/07/2016
COE Expiry Date	10/07/2026 (6 years 8 months left)
Mileage	-
No. of owners	-
Type of Vehicle	Sport Tourers (/listing/usedbike/model/motorcycle-for-sale/sport-tourers/)

Price: SGD\$14500

DETAILS

Honda CB400X for sale. Interested parties are welcome to Neg. Trade/Loan available. Do visit us at Wing Fuat @ Sims Place! No Early Settlement Fee.

Auto Transmission Repair

Top Speed Motors can repair/rebuild automatic transmission system of any car in Singapore

SIMILAR BIKES

[VIEW ALL \(/LISTING/USEDBIKES/LISTING/\)](#)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 718E

Vehicle Details

Vehicle No.: FBM3382K
Vehicle to be Exported: No
Intended Deregistration Date: 18 Oct 2019
Vehicle Make: HONDA
Vehicle Model: CB400X MANUAL
Primary Colour: White
Manufacturing Year: 2016
Engine No.: NC47E1101686
Chassis No.: NC471101846
Maximum Power Output: -
Open Market Value: \$8,232.00
Original Registration Date: 26 Sep 2017
First Registration Date: 26 Sep 2017
Transfer Count: 1
Actual ARF Paid: \$2,366.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 25 Sep 2027
COE Category: D - Motorcycle
COE Period(Years): 10
QP Paid: \$5,701.00
COE Rebate Amount: \$4,524.00
Total Rebate Amount: \$4,524.00

The information contained herein is correct as at 18 Oct 2019

OK

Accident Photo



EURO SUCCESS SERV PTE. LTD

Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

TEL: 67426231

FAX: 67411019

H/P: 98289277 (AH HUAT)

Vehicle No: FBM3382K

Model: HONDA CB400X

not Authorized
Name
d/s 9500/
18/10/19
Take photo after repair
6 day.

QTY	List Items
1	WIND SHIELD
1	WIND SHIELD BRACKET
1	HEADLAMP (LED)
2	MIRROR @95
1	HANDLE BAR
1	CLUTCH COVER
1	CLUTCH GASKET
1	BREMSO BRAKE LEVER 125
1	HANDLE BAR BALANCER o/s
1 SET	HANDLE GRIP
2	FRONT FORK TUBES @
1	FORK UNDER BRACKET 295
1	STEEM STEERING BEARING
1	FORK OIL o/s
2	FORK OILSEAL @
1	FRONT FENDER
1	FRONT DISC
1	FRONT SPORT RIM 1050
1	FRONT RIM SAP
1	FRONT RIM BEARING
1	RADIATOR
1	RADIATOR FAN
1	RADIATOR SIDE COVER IN
1	RADIATOR SIDE COVER OUT
1	COOLANT
1	SIGNAL FRONT R/H
1	FRONT OIL TANK TOP COVER
1	TANK 180
1	TANK SIDE COVER R/H
1	HEADLAMP LOWER COVER
1 SET	CRASH BAR
1	EXHAUST PIPE
1	EXHAUST PIPE PROTECTOR Rear
1	EXHAUST PIPE FRONT PROTECTOR
1	FRONT FOOT REST R/H
1	FRONT FOOT REST BRACKET 295
1	BRAKE PENAL Panel
1	REAR FOOT REST R/H
1	REAR FOOT REST L/H
1	REAR BOX
1	REAR BOX BRACKET
1 SET	NUMBER PLATE

Price \$
scr 220.00
su 250.00 X
scr 850.00
o/s scr 190.00 1pc
scr 180.00
cu7 550.00
scr 18.00
cu7 550.00
cu7 60.00
17 30.00 X
o/s scr 720.00 1pc
scr 420.00
scr 85.00
scr 30.00
o/s scr 70.00 1pc
cu7 220.00
scr 480.00
cu7 1200.00
17 75.00 X
scr 40.00
tu/scr 780.00
cu/scr 185.00
scr 80.00
17 185.00 X
17 30.00 X
cu7 55.00
cu7 400.00
20 2600.00
cu7 450.00
scr 180.00 X
scr 480.00
scr 920.00
17 80.00
scr 160.00
scr 185.00
scr 360.00
scr 180.00
cu7 75.00
17 75.00 X
cu7 260.00
17 450.00 X
front scr 30.00 10 s.n

1 REAR R/H SIDE SLIDER
 1 FRONT CAMERA
 1 REAR CAMERA
 1 REAR R/H SEAT COVER
 1 FRONT BRAKE CALIPER *SK*

tm 155.00 ✓
11 200.00 X
11 200.00 X
12 300.00 X
cm 600.00 ✓

TOTAL \$15,793.00
 LESS 10% \$1,579.30
 TOTAL \$14,213.70

Labour Charges

Transportation charges
 To respray painting and ETC
 To check front and rear electrical wiring
 To remove,refix and realign front fork
 To straighten,repair and realign chassis frame member
 Panel beating,cut,weld remove and replace above parts

100.00 *35*
 1300.00 *400*
11 200.00 X
11 450.00 X
 1000.00 *400*
 1200.00 *380*

\$4,250.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$18,463.70

22553.70

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

11848
102
P-10663.20
L-1225.00
11888.20

EURO SUCCESS SERV PTE. LTD
1 KAKI BUKIT AVENUE 6, #02-03(AUTOBAY) SINGAPORE 417883

TEL: 67426231 FAX: 67411019 H/P: 98289277 (AH HUAT)

SUPPLEMENTARY

Vehicle No: FBM3382K

<u>QTY</u>	<u>List Items</u>	<u>Price\$</u>
1	EXHAUST MANIFOLD header	R 4000.00 X

Total \$4,000.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19018411/Uqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 04-11-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 3569R	Veh. Inspected	FBM 3382K
Policy No.		Coverage (\$)	0.00
Claim No.	D19006577MFSH	Excess (\$)	0.00
Assign From	JASON TEA	Assign Date	17/10/2019
2. Vehicle Particulars & Condition			
Make & Model	HONDA CB400X	c.c	399
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	NC471101846	Colour	WHITE
Odometer	94926	Steering	AFFECTED
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	120/70 ZR17	BRIDGESTONE	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	160/60 ZR17	BRIDGESTONE	6 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION AND O/S BODY.THE BODY STRUCTURE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	11/10/2019	Inspection Date	18/10/2019
Survey held at	EURO SUCCESS SERVICES PTE. LTD 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 3382K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	WIND SHIELD	SCRATCHED	220.00	220.00
1	WIND SHIELD BRACKET	SERVICEABLE	250.00	-
1	HEADLAMP (LED)	SCRATCHED	850.00	850.00
2	MIRROR @\$95.00	O/S SCRATCHED	190.00	95.00
1	HANDLE BAR	BENT	180.00	180.00
1	CLUTCH COVER	CUT	550.00	550.00
1	CLUTCH GASKET	NECESSARY	18.00	18.00
1	BRAKE LEVER	CUT	550.00	125.00
1	HANDLE BAR BALANCER O/S	CUT	60.00	60.00
1	SET HANDLE GRIP	NOT NECESSARY	30.00	-
2	FRONT FORK TUBES	O/S BENT	720.00	360.00
1	FORK UNDER BRACKET	BENT	420.00	395.00
1	STEEM STEERING BEARING	NECESSARY	85.00	85.00
1	FORK OIL O/S	NECESSARY	30.00	30.00
2	FORK OIL SEAL	O/S NECESSARY	70.00	35.00
1	FRONT FENDER	CRACKED	220.00	220.00
1	FRONT DISC	BENT	480.00	480.00
1	FRONT SPORT RIM	CUT	1,200.00	1,050.00
1	FRONT RIM SAP	NOT NECESSARY	75.00	-
1	FRONT RIM BEARING	NECESSARY	40.00	40.00
1	RADIATOR	TWISTED / PUNCTURE	780.00	780.00
1	RADIATOR FAN	CRACKED / JAMMED	185.00	185.00
1	RADIATOR SIDE COVER IN	DISTORTED	80.00	80.00
1	RADIATOR SIDE COVER OUT	NOT NECESSARY	185.00	-
1	COOLANT	NOT NECESSARY	30.00	-
1	SIGNAL FRONT R/H	CUT	55.00	55.00
1	FRONT OIL TANK TOP COVER	CRACKED	400.00	400.00
1	TANK	DENTED	2,600.00	1,850.00
1	TANK SIDE COVER R/H	CRACKED	450.00	450.00

Report Ref No. CS/FCI19018411/Uqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	HEADLAMP LOWER COVER	SERVICEABLE	180.00	-
1	SET CRASH BAR	BENT	480.00	480.00
1	EXHAUST PIPE	DENTED / BENT	920.00	920.00
1	EXHAUST PIPE PROTECTOR REAR	NOT NECESSARY	80.00	-
1	EXHAUST PIPE FRONT PROTECTOR	BENT	160.00	160.00
1	FRONT FOOT REST R/H	BROKEN	185.00	185.00
1	FRONT FOOT REST BRACKET	BENT	360.00	295.00
1	BRAKE PEDAL	BENT	180.00	180.00
1	REAR FOOT REST R/H	CUT	75.00	75.00
1	REAR FOOT REST L/H	NOT NECESSARY	75.00	-
1	REAR BOX	CUT	260.00	260.00
1	REAR BOX BRACKET	NOT NECESSARY	450.00	-
1	REAR R/H SIDE SLIDER	TWISTED	155.00	155.00
1	FRONT CAMERA	NOT NECESSARY	200.00	-
1	REAR CAMERA	NOT NECESSARY	200.00	-
1	REAR R/H SEAT COVER	TO REPAIR SEE LABOUR	300.00	-
1	FRONT BRAKE CALIPER	CRACKED	600.00	545.00
1	EXHAUST HEADER (ADDITIONAL)	TO REPAIR SEE LABOUR	4,000.00	-
	LESS 10% DISCOUNT		-1,586.30	-1,184.80
			18,276.70	10,663.20
1	SET NUMBER PLATE (SN)	FRONT NECESSARY	30.00	10.00
	LESS 10% DISCOUNT		-3.00	-
			27.00	10.00
	LABOUR			
	TRANSPORTATION CHARGES.		100.00	35.00
	TO RESPRAY PAINTING AND ETC.		1,300.00	400.00
	TO CHECK FRONT AND REAR ELECTRICAL WIRING.	NOT NECESSARY	200.00	-
	TO REMOVE,REFIX AND REALIGN FRONT FORK.	NOT NECESSARY	450.00	-
	TO STRAIGHTEN,REPAIR AND REALIGN CHASSIS FRAME MEMBER.		1,000.00	400.00

Report Ref No. CS/FCI19018411/Uqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING,CUT,WELD REMOVE AND REPLACE ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR R/H SEAT COVER.		1,200.00	380.00
			4,250.00	1,215.00
	GRAND TOTAL		22,553.70	11,888.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			9,500.00

Report Ref No. CS/FCI19018411/Uqd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.