

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III19018417/R1PA3Q2

**Date:** 07/04/2021

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SMN4525Z	<b>Insured Vehicle No :</b>	SHD3033U
Date of Loss: 09/10/2019	Nature of Claim: TP	Claim No: MCT19100212

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMN4525Z</b>		
Make & Model:	HONDA FIT, 1.3 (A)	Engine No:	L13B3932450
Reg. Date:	13/08/2019 (Man. Year: 2019)	Chassis No:	GK33417961
Colour:	Grey	Odometer:	16668 km
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,784.56	719.36	2,065.20	74.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,250.00	720.00	2,530.00	77.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,034.56</b>	<b>1,439.36</b>	<b>4,595.20</b>	<b>76.15</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,150.00</b>		
<b>Nett Amount (S\$)</b>	<b>6,034.56</b>	<b>1,150.00</b>	<b>4,884.56</b>	<b>80.94</b>
<b>+ Loss of Use (4.0 x S\$60.00/day) (S\$)</b>		240.00		
<b>+ Other Costs (S\$)</b>		417.00		
<b>Nett Liability (S\$)</b>		<b>1,807.00</b>		

### INSPECTION

Date of Assignment:	17/10/2019	
Date Inspected:	17/10/2019 Inspected At:	Mtm Performance Auto Pte Ltd 42 TOH GUAN ROAD EAST #01-78 ENTERPRISE HUB Singapore 608583
Estimated Period of Repair:	3.0 days	

**Adjuster:** MOHD RASUL

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 20 Jan 2020)
<b>Parts:</b>	144	HONDA FIT 1.3 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMN4525Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	770.70 FL	*770.70 FL
2	2		*FRONT BUMPER SIDE RETAINER	Torn (1 PCS ONLY)	30.40 FL	*15.20 FL
3	1		*FRONT LH FENDER	Repair	398.60 FL	*- FL
4	1		*FRONT LH FENDER INNER SHIELD	Service item	101.40 FL	*- FL
5	1		*FRONT LH FENDER BRACKET	Serviceable	68.00 FL	*- FL
6	4		*LH HEADLAMP (LED)	Serviceable	1,873.30 FL	*- FL
7	1		*LH HEADLAMP BRACKET	Cracked	38.30 FL	*38.30 FL
8	1		*SETS FRONT LH FENDER CLIPS	Necessary	80.00 FS	*30.00 FS
9	1		*SETS FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,440.70</b>	<b>884.20</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	656.14	164.84
<b>Total Parts (\$\$)</b>	<b>2,784.56</b>	<b>719.36</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO CHECK WIRING SYSTEM	New	100.00	0.00
2	TO CARRY OUT BODY CAVITY PRESERVATION	New	200.00	20.00
3	TO RESET AND REPROGRAMME AFTER REPAIR THE VEHICLE	New	300.00	0.00
4	TO CONDUCT WHEEL ALIGNMENT	New	150.00	0.00
5	TO PANEL BEAT ON FRONT LH FENDER INNER PANEL TO R&R FRONT BUMPER ,FRONT LH HEADLAMP AND OTHERS ATTACHMENTS	New	1,000.00	300.00
6	TO RESPRAY ON FRONT BUMPER ,FRONT LH FENDER ,FRONT LH FENDER INNER PANEL AND ACCIDENT AFFECTED AREA	New	1,500.00	400.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,250.00</b>	<b>720.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >