

TPPD

PRESERVE

McTPI 00212/01/BN
PRESERVE

TPPI

PRESERVE

UNINSURED LOSS

PRESERVE

SUBRO

LPPN

INVESTIGATION FEE

SURVEY FEES

LEGAL FEES

OTHERS

FRAUD CHECK

UPLOAD TO MERIMEN

GRANT RIGHTS



MTM PERFORMANCE AUTO PTE LTD

Head Office / Showroom:

42 Toh Guan Road East #01-78, Enterprise Hub S608583

Tel: 6271 2088

Co. Registration No: 200921372W



TO: India International Insurance Pte Ltd
64 Cecil Street
#05-00 IOB Building
Singapore 049711
Attn: Ms Sundari

INVOICE

NO: #80000859 / DATE: 23-Oct-2019

S/N	ITEM DESCRIPTION	QTY	PRICE
1.	Lump Sum repair cost claimed for SMN4525Z	01	\$3,900.00
2.	Loss of use / earnings 5 days @ \$120/day	01	\$600.00
3.	Survey fee (report attached)	01	\$417.00
TOTAL			\$4,917.00

IXI

MT/19100212

IXI

YOUR PASSION OUR MISSION

We are in receipt of your letter, which is regarding our attention. We shall review shortly. Kindly note that we are reserving our rights to conduct a medical re-examination on your client where necessary.

Our Ref: MT/19100212

Name: Sundari

Date: 23/10/2019

India International Insurance Pte Ltd

PAYMENT METHOD

Cheque

SALES REPRESENTATIVE

Ho



MTM Performance Auto Pte Ltd

LETTER OF AUTHORITY/WARRANT TO ACT

Re : SMN4525Z hit by SHD3033U along Hougang Ave 2 on 09/10/2019 @ 1910hrs

I, Pang Tze Kwang , Nric No. S7700598F, registered owner of vehicle SMN4525Z, hereby authorize MTM Performance Auto Pte Ltd to write, negotiate, repair & settle the claim on my behalf with India International Insurance Pte Ltd.

I also hereby authorize that the agreed settlement sum be made in favor of my representative, MTM Performance Auto Pte Ltd and that the payment be forwarded to them in full and final settlement of my damage claim to my vehicle, SMN4525Z.

Yours faithfully



Pang Tze Kwang

Nric No. S7700598F

Date : 10th October 2019

Invoice

To: Pang Tze Kwang

Invoice No: **2019/INV/0041**CC: **MTM PERFORMANCE AUTO PTE. LTD.**

Your Reference:

42 Toh Guan Road East #01-78

Our Reference: **2019/0057**

Enterprise Hub

Date : **23/10/2019**

Singapore 608583

Description	Amount S\$
<u>Particulars</u>	
Vehicle No: SMN4525Z	
Accident Date : 9/10/2019	
Date of Inspection: 10/10/2019	
<u>Service:</u>	
Assessment with report (inclusive of photographs and transport charges etc)	\$417
Total Amount:	\$417

Payment Details:

- 1) Cheque: Kindly make all cheques crossed and payable to **PRECISE APPRAISER PTE LTD**
- 2) Online Banking: **Maybank 041-9107653-9**

**Precise Appraiser Pte Ltd**

Address: 53 Hume Avenue, #05-08, Singapore 598751,
Email: Preciseappraiser@gmail.com, Mobile: +65 9103 5000

VEHICLE DAMAGE ASSESSMENT REPORT

To:

CC: **MTM PERFORMANCE AUTO PTE. LTD.**
 42 Toh Guan Road East #01-78
 Enterprise Hub
 Singapore 608583

REFERENCES

Ref No	:	2019/0057	Date of Report	:	10/10/2019
Claim Type	:	Third Party	Date of Request	:	10/10/2019
Third party vehicle	:	SMN4525Z	Date of Accident	:	
Insured Vehicle	:		Date of Inspection	:	10/10/2019

Your Reference No : -

DAMAGED VEHICAL PARTICULARS

Registration Plate No	:	SMN4525Z	Engine Modification	:	NIL
Model / Make	:	Honda Fit	Pre-accident damage	:	NIL
Colour	:	Grey	General Condition	:	Good
Manufacturing Year	:	2019	General Paint Work	:	Good
Engine No	:	L13B3932450	Steering	:	Serviceable
Engine Capacity	:	1300 cc	Handbrake	:	Serviceable
Chassis No	:	GK33417961	Footbrake	:	Serviceable
Odometer No	:	15684			
Transmission	:	Auto			

TYRES CONDITION

Front Right			Rear Left		
Make	:	Dunlop	Make	:	Dunlop
Size	:	175/70 R14	Size	:	175/70 R14
		6			6
Front Left			Rear Right		
Make	:	Dunlop	Make	:	Dunlop
Size	:	175/70 R14	Size	:	175/70 R14
		6			6

The above millimetres represent the remaining life of tyre treads

VEHICAL REPAIR COST

<u>Descriptions</u>	<u>Repairer (\$\$)</u>	<u>Difference (\$\$)</u>	<u>Adjuster (\$\$)</u>
Parts	2,784.56		2,712.40
Labour	3,250.00		2,200.00
Calculated Cost (\$\$) :	6,034.56	1,122.16	4,912.40


Recommended Lump Sum Repair Cost (\$\$)	:	3,900.00
Estimate Repair Duration	:	4
Survey Inspection At	:	MTM PERFORMANCE AUTO PTE. LTD.
Survey Inspection Address	:	42 Toh Guan Road East #01-78 Enterprise Hub Singapore 608583

DESCRIPTION OF DAMAGE

At the time of inspection, this vehicle sustained damages to the **Front LH portion**.

Front bumper, front LH fender dented LH headlamp mis-align.

Please see attached scheduled details.



SPECIAL REMARKS

We have not authorised repair. Under normal circumstances, estimated 4 working days are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.



Automotive Appraiser
MSAAA

Disclaimer:

This survey was conducted by Precise Appraiser Pte Ltd without prejudice basis and we do not authorized repair. Report by Precise Appraiser Pte Ltd is deemed as confidential and provided for the use of clients and appointed agent. *We have inspected thoroughly each and every item on the repairer's estimate against the actual damages found on the vehicle.* All findings and recommendations are listed accordingly and final decision of settlement to your good selves parts thereof accordingly and final. No liability shall be attached to Precise Appraiser Pte Ltd therefore.

Our Reference : 2019/0057

Your Reference:

Vehicle Number : SMN4525Z

S/N	Qty	Description	Condition	Repairer Estimate (S\$)	Our Assessment (S\$)
Parts					
1	1pcs	Front bumper	Dented	770.7	770.7
2	1pcs	Front bumper side retainer @15.2/pcs	Torn	30.4	15.2
3	1pcs	front lh fender	Dented	398.6	398.6
4	1pcs	front lh fender inner shield	Deformed	101.4	101.4
5	1pcs	front lh fender bracket	Dented	68	68
6	4pcs	Lh headlamp (LED)	Holder torn	1873.3	1873.3
7	1pcs	Lh headlamp bracket	Crack	38.3	38.3

Total	3280.7	3265.5
Less 20%	656.14	653.1
Parts Sub Total	2624.56	2612.4

Special Nett

8	1sets	Front lh fender clips	Necessary	80	50
9	1sets	Front bumper clips	Necessary	80	50

Total	160	100
--------------	-----	-----

Labour					
1		To check wiring sytsem		100	50
2		To carry out body cavity preservation		200	120
3		To reset and reprogramme after repair the vehicle		300	250
4		To conduct wheel alignment		150	80
5		To panel beat on front lh fender inner panel.To R&R front bumper, front lh headlamp and others attachments.		1000	800
7		To respray on front bumper, front lh fender, front lh fender inner panel and accident affected area.		1500	900
Labour Total				3250	2200
Sub Total (labour and parts)				6034.56	4912.4

Adjustment / Recommendations

Note: For Lump Sum Repair

The workshop has agreed to undertake the repair on a Lump Sum Basis, and/or use of ex-stock/reconditioned parts whichever is possible (having taken into consideration to repair instead of replacements).

The final adjusted Lump Sum contract amount is **S\$3900**

Under normal circumstances, the repair period would be about 4 working days.













