

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19018426/BKA3Q2

Date: 07/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SLQ6869P **Insured Vehicle No :** SLV3592E

Date of Loss: 16/10/2019 Nature of Claim: TP Claim No: 3331169428SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ6869P		
Make & Model:	TOYOTA C-HR HYBRID, 1.8 S CVT (A)	Engine No:	2ZR8107878
Reg. Date:	19/07/2017 (Man. Year: 2017)	Chassis No:	ZYX102039928
Colour:	Brown	Odometer:	157219 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Goodride 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	Goodride 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,824.37	5,451.20	3,373.17	38.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,690.00	2,050.00	1,640.00	44.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,514.37	7,501.20	5,013.17	40.06
Approved Total (Overridden) (\$\$)		6,000.00		
Nett Amount (\$\$)	12,514.37	6,000.00	6,514.37	52.06
+ Loss of Use (10.0 x S\$120.00/day) (\$\$)		1,200.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		7,207.45		
Global Sum Settlement (\$\$)		7,000.00		

INSPECTION

Date of Assignment: 18/10/2019

Date Inspected: 18/10/2019 Inspected At: 160 SIN MING DRIVE #01-14
Repairer: Team Autopro Pte Ltd (KAKI BUKIT)

Estimated Period of Repair: 6.0 days

Adjuster: Lim Teow Guan

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	1,124.50 FL	*1,124.50 FL
2	1		*REAR BUMPER LOWER LID	Dented	465.00 FL	*360.20 FL
3	1		*REAR BUMPER REINFORCEMENT	Bent	498.50 FL	*456.00 FL
4	2		*REAR BUMPER INNER S-SIDE BRACKET	Not Applicable	208.40 FL	*- FL
5	2		*REAR BUMPER RETAINER	Necessary	76.00 FL	*76.00 FL
6	1		*REAR BUMPER TOW COVER	Dislodged	35.00 FL	*35.00 FL
7	2		*REAR BUMPER REFLECTOR	Not Damaged	292.00 FL	*- FL
8	1		*REAR BUMPER REFLECTOR GARNISH	O/S Broken	270.00 FL	*125.60 FL
9	1		*REAR END PANEL	Dented	498.50 FL	*380.00 FL
10	1		*REAR END PANEL TOP GARNISH	Broken	185.70 FL	*185.70 FL
11	1		*TAIL GATE LOCK SENSOR	Broken	275.40 FL	*240.00 FL
12	1		*TAIL GATE INNER LOCK	Dented	364.50 FL	*364.50 FL
13	1		*TAIL GATE STRIKER	Not Damaged	106.90 FL	*- FL
14	2		*TAILGATE DAMPER	Not Damaged	375.00 FL	*- FL
15	1		*TAILGATE TRIMBOARD	Broken	267.80 FL	*267.80 FL
16	1		*TAIL GATE	Dented	1,245.50 FL	*1,200.00 FL
17	1		*TAIL GATE LOGO	Necessary	48.50 FL	*48.50 FL
18	1		*TAILGATE EMBLEM C-HR	Necessary	129.60 FL	*83.20 FL
19	1		*TAILGATE EMBLEM HYBRID SYNERGY DRIVE	Necessary	106.30 FL	*71.00 FL
20	1		*TAILGATE LAMP	O/S Cut	778.00 FL	*353.50 FL
21	1		*REAR EXHAUST ASSY	Bent	987.00 FL	*987.00 FL
22	1		*TAIL LAMP	O/S Broken	964.40 FL	*403.10 FL
23	2		*TAIL LAMP GARNISH	Not Damaged	250.00 FL	*- FL
24	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
25	4		*REVERSE SENSOR	Necessary	720.00 FS	*200.00 FS
26	1		*TAIL GATE INNER TRIMBOARD CLIPS	Necessary	50.00 FS	*30.00 FS
27	1		*SUNDRIES	Not Applicable	50.00 FS	*- FS
28	2		*TAIL LAMP SEAL	Not Applicable	100.00 FS	*- FS
29	2		*TAIL GATE REFLECTOR SEAL	Not Applicable	60.00 FS	*- FS
30	2		*TAIL GATE SEALANT	Necessary	200.00 FS	*60.00 FS
31	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
32	1		*REVERSE CAMERA	Not Damaged	280.00 FS	*- FS
33	1		*NUMBER PLATE	Not Damaged	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 11,212.50 7,141.60
- List Item Discount on L Items 25.00/25.00% (\$\$) 2,388.13 1,690.40

Total Parts (\$\$) 8,824.37 5,451.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE ,REPLACE ,CUT ,WELD ,PANEL BEAT AND STRAIGHTEN ACCIDENT DAMAGED PORTION	New	1,500.00	1,000.00
2	PUTTY AND SPRAY PAINT ACCIDENT DAMAGED PORTION INCLUDING PAINT /MATERIALS	New	1,500.00	800.00
3	APPLY RUST PROOFING	New	100.00	60.00
4	TO REMOVE REPLACE AND RESPRAY REAR BUMPER SENSORS WITH SAFETY DISTANCE SETTING	New	120.00	60.00
5	REMOVE AND REBULID REAR EXHAUST SYSTEM	New	120.00	50.00
6	TO REMOVE AND REFIT REAR TAILGATE COMPONENTS	New	200.00	80.00
7	REMOVE AND REPLACE REVERSE CAMERA & CONDUCT SAFETY DISTANCE SETTING	New	120.00	0.00
8	WIRING AND BULB CHECKS	New	30.00	0.00
Gross Labour Cost (\$\$)			3,690.00	2,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >