

15/5/2010

INS. CASE OWNER:

Yuan

CC 4 AXA1901

8471, Aq 18/10/19

LKK:
IDAC:

Surveyor:

Admin

DOI:

17/10/19

Date / Time:

18/10/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SMD 38085

Claim No.:

E9M02240 / 14-828

Name of Insured:

BOON LAY CORPORATION (M) PTE LTD

Policy No.:

Insured Tel No.:

HP:

Make / Model:

BMW

Excess Sec II : \$:

D.O.A.:

16/10/19

Place of Accident:

Mentel Rd

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

LEE HANG WONG

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

SMD 38085

SFD 890

SLS 1303C

INSRS:
WSP:
Tel:
Liability:
RMKS:

01

INSRS: MG
WSP: solution
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

SFD 890-X

SMD 38085-X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$:

9800.00

14 days

Reduction:

\$11,602.40

%

54

Email:

Call:

FINAL SETTLEMENT

Date/Time:

3/2/2020

Confirm with:

SU

Email:

Call:

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia:

100%

Repair Cost:

\$:

10,486.00

Loss of Rental (LOR):

\$:

1360.00

580 x 14 days

Loss of Use (LOU):

\$:

1360.00

580 x 14 days

Loss of Income (LOI):

\$:

1360.00

580 x 14 days

LOR only

LOU only

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

GIA/LTA Search

\$:

7.45

Medical:

\$:

-

Disbursement:

\$:

-

(e.g. Tow/ Independent)

Legal Cost

\$:

-

Total:

\$:

11,850.00

Global Sum \$:

11,850.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email:

Call:

Payee 1:

\$:

11,850.00

Name 1:

MG SOLUTION PTE LTD

Payee 2: (Strike if N.A.)

\$:

-

Name 2:

-

Payee 3: (Strike if N.A.)

\$:

-

Name 3:

-

X GIA.

REF: REC. BY:

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 14 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SFD89C ir Regn: 2008 SeptType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Stream C.G. 1799.Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 194557. T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RN61064334Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/45 R17.R: 215/45 R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 17/10/19Survey held at MG Solution.Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP AXA .

COE Expiry: 31/08/23

Ls \$9800/- (Red = \$11,602.40 / 54.1.)

MV: 26K

PV: 13.51K

Nett: 12.51K .

* 14 repair days + 2 sundays + 1 PRS = 17 days

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

3 + PS. SI

Pinsus

Others

TOTAL

Report Format: _____

Lump Sum / L.B. E /

Add Fee: ☐ : Site Insp. 1\$☐ : Interview 1\$☐ : Tech. Insp. 1\$☐ : Final Insp. 1\$

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AXA	DATE	: 17/10/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SFD89C	<i>Recilia</i>	
MODEL	: HONDA STREAM 1.8A		
CHASSIS NO		<i>RN61064334</i>	
<u>ACCIDENT DETAILS</u>		DATE	: 16-Oct-19
		TIME	: 13:10HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BONNET <i>Buckled</i>	1	\$ 1,030.00	\$ 1,030.00 <i>639.</i>
2	BONNET HINGE <i>Not New</i>	2	\$ 103.20	\$ 206.40 <i>+</i>
3	BONNET LOCK <i>Not New</i>	1	\$ 320.00	\$ 320.00 <i>+</i>
4	BONNET LOCK BRACE PANEL <i>Not New</i>	1	\$ 168.00	\$ 168.00 <i>+</i>
5	FRONT BUMPER <i>Dehnd</i>	1	\$ 922.30	\$ 922.30 <i>638.</i>
6	FRONT BUMPER SIDE RETAINER <i>New</i>	2	\$ 84.60	\$ 169.20 <i>64</i>
7	FRONT BUMPER REINFORCEMENT <i>Best</i>	1	\$ 430.00	\$ 430.00 <i>249</i>
8	FRONT BUMPER LOWER GRILLE <i>Dehnd</i>	1	\$ 288.90	\$ 288.90 <i>123</i>
9	CENTRE GRILLE <i>Crushed</i>	1	\$ 420.00	\$ 420.00 <i>241</i>
10	CENTRE GRILLE MOULDING <i>Crushed</i>	1	\$ 220.00	\$ 220.00 <i>-</i>
11	CENTRE GRILLE LOGO <i>New</i>	1	\$ 95.80	\$ 95.80 <i>40</i>
12	HEADLAMP <i>Crushed</i>	2	\$ 758.30	\$ 1,516.60 <i>1366.</i>
13	HEAD LAMP LOWER BRACKET <i>Crushed</i>	2	\$ 95.00	\$ 190.00 <i>90</i>
14	FRONT FENDER <i>Pyris</i>	2	\$ 933.50	\$ 1,867.00 <i>+</i>
15	FRONT FENDER SIGNAL LAMP <i>Not New</i>	2	\$ 188.90	\$ 377.80 <i>+</i>
16	AIR-CON CONDENSOR <i>Dehnd</i>	1	\$ 895.30	\$ 895.30 <i>✓</i>
17	TAILGATE <i>Distorted</i>	1	\$ 1,250.30	\$ 1,250.30 <i>903</i>
18	TAILGATE LOGO <i>Not New</i>	1	\$ 62.00	\$ 62.00 <i>+</i>

19	TAILGATE EMBLEM 'STREAM' <i>New</i>	1	\$ 55.00	\$ 55.00	✓
20	TAILGATE INNER LOCK <i>Damaged</i>	1	\$ 194.60	\$ 194.60	✓ 145
21	TAILGATE WEATHER STRIP <i>lit</i>	1	\$ 157.80	\$ 157.80	✓
22	TAILGATE INNER BOARD <i>Delaid</i>	1	\$ 211.00	\$ 211.00	✓
23	TAILGATE WINDSCREEN MOULDING <i>New</i>	1	\$ 133.00	\$ 133.00	✓
24	REAR BUMPER <i>Delaid</i>	1	\$ 633.20	\$ 633.20	✓
25	REAR BUMPER TOWING COVER <i>New</i>	1	\$ 48.00	\$ 48.00	✓
26	REAR BUMPER BRACKET <i>LH Bent</i>	2	\$ 58.20	\$ 116.40	✓ 28
27	REAR BUMPER SIDE RETAINER <i>New</i>	2	\$ 42.30	\$ 84.60	✓
28	TAILLAMP LH <i>could</i>	1	\$ 412.00	\$ 412.00	✓ 339
29	RAER FENDER LH <i>Buckled</i>	1	\$ 987.50	\$ 987.50	✓
30	REAR FENDER INNER TRIM <i>could</i>	1	\$ 380.00	\$ 380.00	✓ 285
31	RAER FENDER GLASS WITH MOULDING LH <i>rep m</i>	1	\$ 598.10	\$ 598.10	✓
32	RAER FENDER AIR VENT LH <i>could</i>	1	\$ 111.20	\$ 111.20	✓
33	REAR END PANEL <i>Distorted</i>	1	\$ 580.00	\$ 580.00	✓
34	REAR END PANEL TOP GARNISH <i>Delaid</i>	1	\$ 160.00	\$ 160.00	✓

Taillamp Panel *286* ✓
Buckled

TOTAL PRICE \$ 15,292.00

LESS 20% \$ 3,058.40

SUB TOTAL PRICE \$ 12,233.60

9712.60

7770.08.

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>Edge New</i>	1	\$ 50.00	\$ 50.00	✓
2	FRONT BUMPER CLIPS (SET) <i>New</i>	1	\$ 20.00	\$ 20.00	✓
3	FRONT BUMPER LOWER GRILLE CLIPS (SET) <i>rep m</i>	1	\$ 20.00	\$ 20.00	✓
4	CENTRE GRILLE CLIP (SET) <i>New</i>	1	\$ 20.00	\$ 20.00	✓
5	HEADLAMP CLIP (SET) <i>New</i>	1	\$ 20.00	\$ 20.00	✓
6	REAR NUMBER PLATE <i>Ne New</i>	1	\$ 50.00	\$ 50.00	✓
7	REAR BUMPER CLIPS (SET) <i>New</i>	1	\$ 20.00	\$ 20.00	✓
8	TAILGATE INNER BOARD CLIP (SET) <i>New</i>	1	\$ 20.00	\$ 20.00	✓
9	TAILGATE WINDSCREEN SEALANT <i>2 New</i>	1	\$ 100.00	\$ 100.00	✓ 40
10	TAILGATE WINDSCREEN INNER SEAL	1	\$ 80.00	\$ 80.00	✓ 40
11	REAR FENDER INNER TRIM CLIP (SET) <i>New</i>	1	\$ 20.00	\$ 20.00	✓
12	TAILLAMP CLIP (SET) <i>New</i>	1	\$ 20.00	\$ 20.00	✓
13	REAR END PANEL TOP GARNISH CLIPS (SET) <i>New</i>	1	\$ 20.00	\$ 20.00	✓ 10
14	REAR END PANEL INSULATION SEAL <i>New</i>	1	\$ 80.00	\$ 80.00	✓ 60
15	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00	✓ 200

TOTAL \$ 760.00

490

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,200.00	600
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	600
3	TUFF COAT	\$ 250.00	x
4	WIRING AND BULB CHECKING	\$ 80.00	30
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL GAS	\$ 120.00	✓

TOTAL \$ 2,850.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 2,000.00	1200	
2	TO SPRAY PAINT AFFECTED AREA	\$ 2,000.00	1000	
3	TUFF COAT	\$ 250.00	100	
4	WIRING AND BULB CHECK	\$ 180.00	30	
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 150.00	80	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 150.00	50	
7	REMOVE AND REFIX REVERSE CAMERA	\$ 220.00	50	
8	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 140.00	120	
9	TRANSFER TAILGATE MECHANISM	\$ 120.00	80	
10	TO REMOVE AND REFIX QUARTER GLASS	\$ 120.00	60	

TOTAL 2770 \$5,330.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 12,993.60

TOTAL LABOUR COST : \$ 8,180.00

TOTAL REPAIR COST : \$ 21,173.60

APPROVED DETAILS

SURVEYOR

CONTACT NO

PART BY PART / LUMP SUM

- LKK Auto Consultants hereby certify the Repairer of the following:
- To resurvey before/after spray painting
 - May damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
- Lodged by Repairer

FAX

Adrian Lj
H/s 17/10/19.

14 Days.

total 12260.08
H/s 9.81C

\$21402.40x

4000



NO OF DAYS

:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	794I
Vehicle Details	
Vehicle No.:	SFD89C
Vehicle to be Exported:	Yes
Intended Deregistration Date:	17 Oct 2019
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8X A
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	R18A1771528
Chassis No.:	RN61064334
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$18,023.00
Original Registration Date:	08 Sep 2008
First Registration Date:	08 Sep 2008
Transfer Count:	1
Actual ARF Paid:	\$18,023.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Aug 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$17,496.00
COE Rebate Amount:	\$13,545.00
Total Rebate Amount:	\$13,545.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 17 Oct 2019

OK

LETTER OF AUTHORITY

Name : TAY TIEN CHENG
Address : BLK 138C YUAN CHING ROAD
#22-135 S(613138)
Contact No : _____
TO: AXA INSURANCE PTE LTD

Dear Sirs,

ACCIDENT INVOLVING SFD 89C AND SMD 38085 ON 16/10/2019
AT/ALONG JUNCTION OF CLEMENTI ROAD AND KENT RIDGE CRESCENT.

I/We, TAY TIEN CHENG, am/are the registered owner of
motor car no. SFD 89C

Please note that I have assigned all compensations monies due to me/us in the above said accident
to M/S MG SOLUTION PTE LTD.

I/We, hereby authorize you to release all compensation monies pertaining to the above-mentioned
accident to M/S MG SOLUTION PTE LTD and forward your settlement cheque to M/S MG SOLUTION
PTE LTD whom I had authorized to collect the said compensation monies.

Thank you



Signature of Claimant



Witness By

MG SOLUTION PTE LTD
23 Kaki Bukit Ave 4 (South Wing) #02-03B
Vicom Inspection Centre, Singapore 415933
Tel: 6243 1373 Fax: 6243 1376
GST Reg. No. : 201427944N

MOTOR CLAIM DISCHARGE

INSURED: TAY TIEN CHENG
CAR/ LORRY/CYCLE: REG NO: SFD 89C POLICY NO:
ACCIDENT CLAIM NO:

I / We confirm that I / we have taken delivery of Car / Lorry / Motor Cycle
Registered No. SFD 89C from the repairers,
Messrs MG SOLUTION PTE LTD
And that all repairs necessary as a result of an accident in which the said vehicle was involved on or
about the 16 day of 10 2019 have been completed to my / our satisfaction, and that
I / we have no further claim on the above company in Respect thereof.

Date: Signature:

Co's Stamp: NRIC No:

12/10/2019 - PR1
20/10/2019 - Sunday
22/10/2019 - PH (Deepavali)
28/10/2019 - PH (Deepavali)

Vehicle In - 12/10/2019
Vehicle Out - 02/11/2019
Loan - 17 days x \$200
= \$3,400



New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Google's Smart Speaker

Shop Google's smallest & Learn more about Google Store,

SEARCH

honda stream

Price Range

Depreciation

> 10 year(s)

Vehicle Type

Search

View All

Advanced Search

Used Car Comparison

--- Comparing 4 Vehicles ---

Honda Stream 1.8A (COE till 07/2023)



Add to Shortlist

Honda Stream 1.8A X (COE till 10/2023)



Add to Shortlist

Honda Stream 1.8A RSZ Sunroof (COE till 10/2023)



Add to Shortlist

Honda Stream 1.8A S (COE till 11/2023)



Add to Shortlist

Clear All

Add all to Shortlist

Back to search result

CAR DETAILS

	Honda Stream 1.8A (COE till 07/2023)	Honda Stream 1.8A X (COE till 10/2023)	Honda Stream 1.8A RSZ Sunroof (COE till 10/2023)	Honda Stream 1.8A S (COE till 11/2023)
Price	\$26,800	\$27,800	\$31,800	\$32,800
Instalment	N.A.	N.A.	N.A.	N.A.
Registration Date	23-Jul-2008	24-Oct-2008	17-Nov-2008	22-Nov-2008
Manufactured	2008	2008	2008	2007
Mileage	-	190,000 km	215,000 km	-
Transmission	Auto	Auto	Auto	Auto
Engine Cap	1,799 cc	1,799 cc	1,799 cc	1,799 cc
Road Tax	\$1,076 /yr	\$1,076 /yr	\$1,076 /yr	\$1,076 /yr
Power	103.0 kW (138 bhp)	103.0 kW (138 bhp)	103.0 kW (138 bhp)	103.0 kW (138 bhp)
Curb Weight	1,370 kg	1,350 kg	1,385 kg	1,385 kg
Features	1.8L I-VTEC 16 Valves DOHC Engine. 5 Speed Automatic Transmission. SRS Airbags. View Specs Of The Honda Stream (2007-2014)	1.8L I-VTEC 16 Valves DOHC Engine. 5 Speed Automatic Transmission. SRS Airbags.	RSZ Model With Electric Sunroof, Reliable 1388hp 1.8 Litre VTEC, 5 Speed Auto, 4 Disc Brakes, Automatic HID Headlights, Retractable Side Mirrors.	1.8L I-VTEC 16 Val Speed Automatic T Airbags.
Accessories	Leather Seats, Sports Rims, Reverse Sensors, Audio Player, Auto Retractable Side Mirrors, Knockdown Rear Seats.	Auto Climatic Aircon, Leather Seats, Sports Rims, Reverse Sensors And Camera, UV Films, Knockdown Rear Seats.	Original RSZ Rims, Leather Seats, Wear And Tear Done, New Disc Brakes, Suspension, Mountings, Aircon Cooling Coil, New Tyres, Touch Screen Head Unit.	Leather Seats, Spo Auto Climatic Airco And Camera, UV Fi Seats.
Description	Cheapest In Town, Tax Pay Till 07/2020, Well Kept, Accident Free, Good Fuel Efficiency Family Car Ideal For Daily Drives. Car Is In Good Condition. Selling Cheap! Hurry View Now. Price Can Still Be Negotiable. Easy Loan Available.	RFS Retired Old Man Take Care Of GrandChild Don't Need Such Big Car.	RSZ Model With Sunroof, HID Headlamps And 4 Disc Brakes, 80% Loan Of Car Price Available From 3.18%! Very Well Maintained By Fussy Owner, Drive With No Worries As Wear And Tear Replaced Within The Last Year With Receipts, Reliable And Low-Cost Family MPV, Trade-In Available, Consignment Unit, Viewing By Appointment Only, Contact Us Now!	Tip Top Condition, Specs From Agent, Now!
COE	\$18,444	\$16,140	\$16,140	\$16,061
OMV	\$19,860	\$17,446	\$25,032	\$21,090
ARF	\$19,860	\$17,446	\$25,032	\$16,112
Depreciation	\$7,120 /yr	\$6,920 /yr	\$7,870 /yr	\$8,000 /yr
No. of Owners	3	4	4	4
Type of Vehicle	MPV	MPV	MPV	MPV
Category	COE Car	COE Car, Direct Owner Sale	COE Car, Premium Ad Car	COE Car
Availability	Available	Available	Available	Available
Remarks				

文 禮 合 衆 藥 房

Cecilia

BOON LAY CORPORATION CLINIC PTE LTD

[Co. Reg. No.: 200510297N]

Blk 350 Jurong East Ave. 1 #01-1225 Singapore 600350 Tel: 6899 4569 Fax: 6564 6303

29 Dec 2019

Ms Cecilia Chong(Case Handler)

LKK Auto Consultants Pte Ltd

51 UBI AVE 1 #01-25

PAYA UBI INDUSTRIAL PARK

SINGAPORE 408933

RE: **Your Ref : CC4/ASM19018431/Agb3**

Our Ref : SMD 3808S

Accident Involving SMD 3808S / SFD 89C /Others Along/At Clementi Road on 16/10/2019

Police Report t: attached

Driver's License: attached

Driver's Work Permit: I am the Director of Boon Lay Corporation Clinic Pte Ltd, No work permit

Employment Letter from your Company: Director of Boon Lay Corporation Clinic Pte Ltd.

No Employment letter. Employment letter is not required.

Authorization Letter: I am the Director of Boon Lay Corporation Clinic Pte Ltd (Lee Chang Long & Cho Shu Beng). No Authorization letter is required.

Rental agreement: the company car belongs to me (Lee Chang Long) & my wife(Cho Shu Beng).

No rental agreement is required

Colure Photo of damage to all vehicles involved: attached (x5)

COUNTER CLAIM STATUS AGAINST THIRD PARTY: No claim of me/passenger against the involved

Third Party(s). Minor accident

Video Footage of accident: Nil

Statement and/or police report from independent witness: Nil

Yours faithfully

Dr Lee Chang Long, Director

Boon Lay Corporation Clinic Pte Ltd



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 16/01/2020

Survey Details:

Date of loss	16-Oct-19
Date of appointment	18-Oct-19
Date of survey	17-Oct-19
Location of survey	MG SOLUTION PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SFD 89C
Make and Model	HONDA STREAM 1.8X A
Date of registration	8/9/2008
Excess	
Market Value	\$26,000
Parf Rebate	\$13,545
Nett Loss	\$12,455

Repair details:

Initial Estimate	\$ 21,173.60
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 8,260.08
Check items (estimate)	\$ -
Labour	\$ 4,000.00
Total	\$ 12,260.08
Lump Sum(if applicable)	\$ 9,800.00
Number of days for repair	14



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

14 RECOMMENDED REPAIR DAYS + 2 SUNDAYS + 1 PRS = 17 DAYS

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 10,486.00	W/GST
Loss of use	\$ 1,700.00	17days x \$100
Loss of rental	\$ -	
Loss of income	\$ -	
LTA search fees	\$ 7.45	
Others	\$ -	
Proposed Total	\$ 12,193.45	



<MANDATE IA> - S9M023YO {ACCIDENT INVOLVING SMD 3808S (OI) & SFD 89C (TP) ON 16/10/2019}

Type

Question

Message

LIABILITY: 100% BOLA S28 (OI LAST) - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$12,193.45 (CLAIMING LOU). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL
16/01/2020

Reply



MG SOLUTION PTE LTD

23 Kaki Bukit Ave 4, AAS Kaki Bukit Centre #02-03 Singapore 415933

Tel: 6243 1373 Fax: 6243 1376

(GST Reg. No. 20-1427944-N)

TAX INVOICE

Bill To:

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

INVOICE No : TI 209035

PB No : 198388

Date : 04-February-2020

ATTN : MOTOR CLAIMS DEPARTMENT

Vehicle Number : SFD 89C

QTY	DESCRIPTION	AMOUNT
1	To carried out accident repair as per surveyor's recommendation (Lump Sum)	\$ 9,800.00
BEFORE GST		9,800.00
7% GST		686.00
TOTAL		\$ 10,486.00

Cheque should be made payable to MG Solution Pte Ltd



Co's stamp & Authorised Signature



Re:<MANDATE IA> - S9M023YO {ACCIDENT INVOLVING SMD 3808S (OI) & SFD 89C (TP) ON 16/10/2019}

Type

🔍 Question

Message

Hi CCL, proceed. Thanks

Reply



MG SOLUTION PTE LTD

23 Kaki Bukit Ave 4, AAS Kaki Bukit Centre #02-03 Singapore 415933

Tel: 6243 1373 Fax: 6243 1376

(GST Reg. No. 201427944N)

Date : 06/12/2019

Your Ref : SMD3808S

To : AXA INSURANCE SINGAPORE PTE LTD

Attn : Motor Claims Department

Dear Sir/Mdm,

**RE: ACCIDENT INVOLVING VEHICLE SFD89C & SMD3808S ON 16/10/2019 AT
JUNCTION OF CLEMENTI ROAD AND KENT RIDGE CRESCENT.**

We refer to the above matter.

Attached copies of the following for your kind perusal:

- 1) Proforma Bill No.198388 @ S\$10,486.00 (Inclusive Of 7% GST)
- 2) Loss of Use @ S\$3,400.00 (17 Days x S\$200)
- 3) LTA Search @ S\$7.45
- 4) Authorisation to Act
- 5) GIA Report

Hope the above is in order and kindly let us have your confirmation soon.

Tax invoice will be issue upon amount finalized.

Thank You,

Yours faithfully,



Sharon Chia

HP: 9188 6931

E-mail: mg3solution@gmail.com



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM19018431/Aga3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: LYNN KHONG		Date : 10-02-2020 Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMD 3808S	Veh. Inspected	SFD 89C
Policy No.		Coverage (\$)	0.00
Claim No.	S9M023YO	Excess (\$)	0.00
Assign From	LYNN KHONG	Assign Date	18/10/2019
2. Vehicle Particulars & Condition			
Make & Model	HONDA STREAM	c.c	1799
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	RN61064334	Colour	SILVER
Odometer	194557	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/45 R17	WEST LAKE	6 mm
L/H Front Tyre	215/45 R17	WEST LAKE	6 mm
R/H Rear Tyre	215/45 R17	WEST LAKE	6 mm
L/H Rear Tyre	215/45 R17	WEST LAKE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	16/10/2019	Inspection Date	17/10/2019
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFD 89C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET (CONSISTENT)	BUCKLED	1,030.00	639.00
2	BONNET HINGE @ \$103.20 (CONSISTENT)	NOT NECESSARY	206.40	-
1	BONNET LOCK (CONSISTENT)	NOT NECESSARY	320.00	-
1	BONNET LOCK BRACE PANEL (CONSISTENT)	NOT NECESSARY	168.00	-
1	FRONT BUMPER (CONSISTENT)	DEFORMED	922.30	638.00
2	FRONT BUMPER SIDE RETAINER @ \$84.60 (CONSISTENT)	NECESSARY	169.20	64.00
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	BENT	430.00	249.00
1	FRONT BUMPER LOWER GRILLE (CONSISTENT)	DEFORMED	288.90	123.00
1	CENTRE GRILLE (CONSISTENT)	CRACKED	420.00	241.00
1	CENTRE GRILLE MOULDING (CONSISTENT)	CRACKED	220.00	220.00
1	CENTRE GRILLE LOGO (CONSISTENT)	NECESSARY	95.80	40.00
2	HEADLAMP @ \$758.30 (CONSISTENT)	CRACKED	1,516.60	1,366.00
2	HEAD LAMP LOWER BRACKET @ \$95.00 (CONSISTENT)	CRACKED	190.00	90.00
2	FRONT FENDER @ \$933.50 (CONSISTENT)	TO REPAIR SEE LABOUR	1,867.00	-
2	FRONT FENDER SIGNAL LAMP @ \$188.90 (CONSISTENT)	NOT NECESSARY	377.80	-
1	AIR-CON CONDENSOR (CONSISTENT)	DENTED	895.30	895.30
1	TAILGATE (CONSISTENT)	DISTORTED	1,250.30	903.00
1	TAILGATE LOGO (CONSISTENT)	NOT NECESSARY	62.00	-
1	TAILGATE EMBLEM 'STREAM' (CONSISTENT)	NECESSARY	55.00	55.00
1	TAILGATE INNER LOCK (CONSISTENT)	DAMAGED	194.60	145.00
1	TAILGATE WEATHERSTRIP (CONSISTENT)	CUT	157.80	157.80
1	TAILGATE INNER BOARD (CONSISTENT)	DEFORMED	211.00	211.00
1	TAILGATE WINDSCREEN MOULDING (CONSISTENT)	NECESSARY	133.00	133.00
1	REAR BUMPER (CONSISTENT)	DEFORMED	633.20	633.20
1	REAR BUMPER TOWING COVER (CONSISTENT)	NECESSARY	48.00	48.00
2	REAR BUMPER BRACKET @ \$58.20 (CONSISTENT)	N/S BENT	116.40	28.00
2	REAR BUMPER SIDE RETAINER @ \$42.30 (CONSISTENT)	NECESSARY	84.60	84.60
1	TAILLAMP LH (CONSISTENT)	CRACKED	412.00	339.00
1	REAR FENDER LH (CONSISTENT)	BUCKLED	987.50	987.50

Report Ref No. CC4/ASM19018431/Aga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FENDER INNER TRIM (CONSISTENT)	CRACKED	380.00	285.00
1	REAR FENDER GLASS WITH MOULDING LH (CONSISTENT)	NOT NECESSARY	598.10	-
1	REAR FENDER AIR VENT LH (CONSISTENT)	CRACKED	111.20	111.20
1	REAR END PANEL (CONSISTENT)	DISTORTED	580.00	580.00
1	REAR END PANEL TOP GARNISH (CONSISTENT)	DEFORMED	160.00	160.00
1	TAILLAMP PANEL (CONSISTENT)	DENTED	286.00	286.00
	LESS 20% DISCOUNT		-3,115.60	-1,942.52
			12,462.40	7,770.08
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	SET FRONT BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	20.00	20.00
1	SET FRONT BUMPER LOWER GRILLE CLIPS (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
1	SET CENTRE GRILLE CLIP (SN) (CONSISTENT)	NECESSARY	20.00	20.00
1	SET HEADLAMP CLIP (SN) (CONSISTENT)	NECESSARY	20.00	20.00
1	REAR NUMBER PLATE (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	20.00	20.00
1	SET TAILGATE INNER BOARD CLIP (SN) (CONSISTENT)	NECESSARY	20.00	20.00
1	TAILGATE WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	100.00	40.00
1	TAILGATE WINDSCREEN INNER SEAL (SN) (CONSISTENT)	NECESSARY	80.00	40.00
1	SET REAR FENDER INNER TRIM CLIP (SN) (CONSISTENT)	NECESSARY	20.00	20.00
1	SET TAILLAMP CLIP (SN) (CONSISTENT)	NECESSARY	20.00	20.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN) (CONSISTENT)	NECESSARY	20.00	10.00
1	REAR END PANEL INSULATION SEAL (SN) (CONSISTENT)	NECESSARY	80.00	60.00
1	REVERSE SENSOR (SN) (CONSISTENT)	DAMAGED	220.00	200.00
			760.00	490.00
	LABOUR			
	TO PANEL BEAT, REMOVE AND REPLACE PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER.		3,200.00	1,800.00
	TO SPRAY PAINT AFFECTED AREA.		3,200.00	1,600.00

Report Ref No. CC4/ASM19018431/Aga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TUFF COAT.		500.00	100.00
	WIRING AND BULB CHECKING.		260.00	60.00
	REMOVE AND REFILL AIRCON CONDENSOR AND REFILL GAS.		120.00	120.00
	REMOVE AND REFILL CUSHION SEAT / UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR.		150.00	80.00
	REMOVE AND REFILL REVERSE SENSOR AND DISTANCE SETTING.		150.00	50.00
	REMOVE AND REFILL REVERSE CAMERA.		220.00	50.00
	REMOVE AND REFILL TAILGATE WINDSCREEN.		140.00	120.00
	TRANSFER TAILGATE MECHANISM.		120.00	80.00
	TO REMOVE AND REFILL QUARTER GLASS.		120.00	60.00
			8,180.00	4,120.00
	GRAND TOTAL		21,402.40	12,380.08
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			9,800.00

Report Ref No. CC4/ASM19018431/Aga3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.