

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19018513/BBA3Q2

**Date:** 20/08/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant**  
**Vehicle No :** SMP3871U **Insured Vehicle No :** SLA3179B

**Date of Loss:** 01/10/2019 **Nature of Claim:** TP **Claim No:** 9530133549SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

<b>Reg No:</b>	<b>SMP3871U</b>		
<b>Make &amp; Model:</b>	TOYOTA VELLFIRE, 2.5 Z G-EDITION CVT (A)	<b>Engine No:</b>	2ARJ184665
<b>Reg. Date:</b>	24/09/2019 (Man. Year: 2018)	<b>Chassis No:</b>	AGH300210748
<b>Colour:</b>	Black	<b>Odometer:</b>	5944 km
<b>Engine Capacity:</b>	2493 cc		
<b>Market Value/New Car Price:</b>	N/A		
<b>Sum Insured (S\$):</b>	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Toyo 7 mm	Rear Left Side:	Toyo 7 mm
Front Right Side:	Toyo 7 mm	Rear Right Side:	Toyo 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,014.37	1,866.80	4,147.57	68.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	940.00	1,760.00	65.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,714.37</b>	<b>2,806.80</b>	<b>5,907.57</b>	<b>67.79</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,300.00</b>		
<b>Nett Amount (S\$)</b>	<b>8,714.37</b>	<b>2,300.00</b>	<b>6,414.37</b>	<b>73.61</b>
<b>+ Loss of Use (1.0 x S\$100.00/day) (S\$)</b>		100.00		
<b>+ Car Rental (4.0 x S\$160.00/day + 7.00% GST) (S\$)</b>		684.80		
<b>+ Doc/Search Fee (S\$)</b>		29.00		
<b>Nett Liability (S\$)</b>		<b>3,113.80</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,100.00</b>		

### INSPECTION

**Date of Assignment:** 21/10/2019

**Date Inspected:** 21/10/2019 **Inspected At:**

160 SIN MING DRIVE #01-14

Repairer: Team Autopro Pte Ltd (HQ)

**Estimated Period of Repair:** 4.0 days

**Adjuster:** Lim Teow Guan

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR	Dented	1,589.00 FL	*1,589.00 FL
2	1		*FRONT DOOR LOWER PANEL	Cut	328.40 FL	*328.40 FL
3	1		*FRONT DOOR LOWER PANEL RETAINER	Not Applicable	121.60 FL	*- FL
4	1		*FRONT DOOR INNER GARNISH	Not Applicable	288.60 FL	*- FL
5	1		*FRONT DOOR REGULATOR ASSY	Not Damaged	462.20 FL	*- FL
6	1		*FRONT DOOR WEATHER STRIP	Not Damaged	234.20 FL	*- FL
7	1		*FRONT FENDER	Not Damaged	678.50 FL	*- FL
8	1		*FRONT FENDER INNER SHIELD	Not Damaged	325.60 FL	*- FL
9	1		*FRONT BUMPER	Repair	1,273.60 FL	*- FL
10	2		*FRONT BUMPER SIDE RETAINER	Necessary	298.80 FL	*225.00 FL
11	1		*FRONT DOOR LOCK MECHANISM	Not Damaged	452.00 FL	*- FL
12	1		*SUNDRIES	Not Applicable	80.00 FS	*- FS
13	1		*FRONT DOOR LOWER PANEL CLIPS	Necessary	50.00 FS	*30.00 FS
14	1		*FRONT FENDER INNER SHIELD CLIPS	Not Damaged	60.00 FS	*- FS
15	1		*FRONT TYRE	Not Damaged	325.00 FS	*- FS
16	1		*SPORT RIM (LOCAL REPAIR)	Cut	800.00 FS	*200.00 FS
17	1		*FRONT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
18	1		*FRONT DOOR SEALANT	Not Applicable	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>7,527.50</b>	<b>2,402.40</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	<b>1,513.13</b>	<b>535.60</b>
<b>Total Parts (\$)</b>	<b>6,014.37</b>	<b>1,866.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	R&R FRONT DOOR COMPONENT	New	200.00	80.00
2	R&R FRONT DOOR REGULATOR ASSY AND SENSOR	New	150.00	0.00
3	R&R FRONT SIDE GLASS	New	150.00	0.00
4	PANEL BEAT	New	1,000.00	400.00
5	RUST PROOFING	New	200.00	60.00
6	SPRAY PAINTING	New	1,000.00	400.00
<b>Gross Labour Cost (\$)</b>			<b>2,700.00</b>	<b>940.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >