

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Oct 2019		21 Oct 2019 14:36 Edit Adj Rpt	S\$3,313.20 Edit Estimates	S\$3,313.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS [Created by insurer]																								
Insured: -, Co. Reg. No.: - Main Claimant: K NANDA KUMARI , ID: S1177625F Vehicle Reg. No.: SDY116X Date of Loss: 16/10/2019 22:00 - :59 [12 Months and 18 Days From LTA Reg Date (Man Yr)] Claim Type: TP / SNM19D204986C02 Policy/Cover Note No.: DMPCSN30394919000 Vehicle Reg. No. (Insured): SLC9509H Policy No. (Claimant): 5112823878 Excess: S\$500.00 Repairer: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174 Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Susan Teo - 6389 6178] Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel: Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 02/09/2020]																								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail																								
CHINA_TAIPING (31/08/2020): Report Send Back Alerts - SDY116X (TP)																								
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete																								
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Claim Documents

*SDY116X (SNM19D204986C02)
[SLC9509H]
TP
K NANDA KUMARI
Oct 16 2019 10:00PM
[-]
Performance Motors Limited

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ▼

Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/03/20 15:19	General View	Load JPG	☒
2	13/03/20 15:19	General View	Load JPG	☒
3	13/03/20 15:19	General View	Load JPG	☒
4	13/03/20 15:19	General View	Load JPG	☒
5	13/03/20 15:19	General View	Load JPG	☒
6	13/03/20 15:19	General View	Load JPG	☒
7	13/03/20 15:19	General View	Load JPG	☒
8	13/03/20 15:20	General View	Load JPG	☒
9	13/03/20 15:20	General View	Load JPG	☒
10	13/03/20 15:20	General View	Load JPG	☒
11	13/03/20 15:20	Odometer Reading	Load JPG	☒
12	13/03/20 15:20	Chassis Number	Load JPG	☒
13	13/03/20 15:20	General View	Load JPG	☒
14	13/03/20 15:20	General View	Load JPG	☒
15	13/03/20 15:20	General View	Load JPG	☒
16	17/08/20 10:10	Reinspection Photo	Load JPG	☒
17	17/08/20 10:10	Reinspection Photo	Load JPG	☒
18	17/08/20 10:10	Reinspection Photo	Load JPG	☒
19	17/08/20 10:10	Reinspection Photo	Load JPG	☒
20	17/08/20 10:11	Reinspection Photo	Load JPG	☒

Linked Accident Report Documents

View [View in Browser](#) ▼

Assessment Reports			1 per page ▼	☒
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail	Print
1	06/12/19 19:04	Accident Statement	Load HTM	
2	06/12/19 19:05	Accident Statement	Load HTM	
3	06/12/19 19:06	Accident Statement	Load HTM	
4	06/12/19 19:07	Accident Statement	Load HTM	

Photos/Images			3 per page ▼	☒
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail	Print
1	17/10/19 12:19	Accident Photo	Load JPG	☒
2	17/10/19 12:19	Accident Photo	Load JPG	☒
3	17/10/19 12:19	Accident Photo	Load JPG	☒
4	17/10/19 12:19	Accident Photo	Load JPG	☒
5	17/10/19 12:19	Accident Photo	Load JPG	☒
6	17/10/19 12:19	Accident Photo	Load JPG	☒
7	17/10/19 12:19	Accident Photo	Load JPG	☒

Documentation			1 per page ▼	☒
---------------	--	--	--------------	-------------------------------------

Assessment Reports				1 per page ▾	☒
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)		Thumbnail	Print
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)		Thumbnail	Print
1	17/10/19 12:14	Sketch Plan		Load JPG	☒
2	17/10/19 12:14	Sketch Plan #2		Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI19018523/R1QF3S2**Date:** 01/09/2020**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30394919000
Claimant Vehicle No :	SDY116X	Insured Vehicle No :	SLC9509H
Date of Loss:	16/10/2019	Nature of Claim:	TP
		Claim No:	SNM19D204986C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDY116X	Engine No:	32945396B38B15A
Make & Model:	BMW 318I, 1.5 SEDAN LED NAV (A)	Chassis No:	WBA8E32090A548699
Reg. Date:	28/09/2018 (Man. Year: 2018)	Odometer:	23291 km
Colour:	Red		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,482.40	1,379.20	103.20	6.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,490.00	1,934.00	556.00	22.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,972.40	3,313.20	659.20	16.59
+ GST 7.00/7.00% (S\$)	278.07	231.92	46.15	16.60
Nett Amount (S\$)	4,250.47	3,545.12	705.35	16.59

INSPECTION

Date of Assignment:	21/10/2019	Performance Motors Limited (Alexandra)
Date Inspected:	18/02/2020 Inspected At:	303 Alexandra Road, Sime Darby Performance Centre
Estimated Period of Repair:	3.0 days	Singapore 159941

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 31 Aug 2020)

Parts: 143 BMW 318I 1.5 SEDAN LED NAV (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SDY116X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER BLACK TRIM STRIP	Serviceable	83.00 FS	*- FS
2	1		*REAR BUMPER PANEL PRIMED (LINES)	Scratched	1,178.85 FS	*1,178.85 FS
3	4		*DECOUPLING RING PDC TORQUE CONVERTE	Serviceable	20.20 FS	*- FS
4	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
5	1		*SET MOUNTING PDC/PMA SENSOR REAR	Necessary	67.30 FS	*67.30 FS
6	1		*(DG/SL) ADHESIVE SET K6	Necessary	53.05 FS	*53.05 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **1,482.40** **1,379.20**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACING REAR BUMPER PANEL AND ATTACHMENT.	New	1,275.00	850.00
2	SPRAY REAR BUMPER.	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION.	New	177.00	150.00
Gross Labour Cost (\$)			2,490.00	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >