



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBC 8525K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT LH SIDE COVER (CONSISTENT)	NOT NECESSARY	305.00	-
1	FRONT FENDER (CONSISTENT)	DENTED	550.00	550.00
1	HANDLE BAR (CONSISTENT)	NOT NECESSARY	645.00	-
1	SET FRONT FORK TUBE (CONSISTENT)	REPEATED	1,650.00	-
1	RH FORK GUARD (CONSISTENT)	CUT	228.00	228.00
1	FRONT FORK ASSY (CONSISTENT)	DISTORTED	1,650.00	1,650.00
1	SET FRONT WHEEL SLIDER O/S (CONSISTENT)	CUT	450.00	225.00
1	SET HAND GUARD O/S (CONSISTENT)	CUT	450.00	225.00
1	REAR CENTRE COVER LH (CONSISTENT)	NOT NECESSARY	395.00	-
1	REAR WHEEL SLIDER (CONSISTENT)	NOT NECESSARY	250.00	-
	LESS 10% DISCOUNT		-657.30	-287.80
			5,915.70	2,590.20
	<u>LABOUR</u>			
	TOWING FEE.	NOT NECESSARY	60.00	-
	REMOVE & REPLACE NECESSARY PARTS, ALIGN & ETC.		250.00	150.00
	REMOVE & REPLACE FRONT FORK , TOP UP FORK OIL & CHECK FROMT RIM -REPRESS & FRONT BRAKE DISC.		280.00	80.00
	RESPRAY PAINT & TOUCH UP.		300.00	100.00
			890.00	330.00
GRAND TOTAL			6,805.70	2,920.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,300.00

Report Ref No. CC4/ASM19018532/Dps3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.