

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**PRE-REPAIR INSPECTION REPORT**

AXA INSURANCE PTE LTD  
8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN: RUIHONG LI

Ref: CS3/ASM19018533/Hpb3s2

Date: 17-12-2019



Code: ASM

**1. Policy Particulars :- (THIRD PARTY CLAIM)**

<b>Insured Veh.</b>	SHD 9354D	<b>Veh. Inspected</b>	SGY 4455E
<b>Policy No.</b>	VFX/P2203857	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S9M023ND	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	RUIHONG LI	<b>Assign Date</b>	21/10/2019


**2. Vehicle Particulars & Condition**

<b>Make &amp; Model</b>	ALFA ROMEO 159	<b>c.c</b>	2198
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2010
<b>Chassis No.</b>	ZAR93900007258404	<b>Colour</b>	WHITE
<b>Odometer</b>	328074 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
<b>R/H Front Tyre</b>	225/45 R17	GOODYEAR	5 mm
<b>L/H Front Tyre</b>	225/45 R17	GOODYEAR	5 mm
<b>R/H Rear Tyre</b>	225/45 R17	GOODYEAR	5 mm
<b>L/H Rear Tyre</b>	225/45 R17	GOODYEAR	5 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.	
--	---

**5. General Information**

<b>Accident Date</b>	14/10/2019	<b>Inspect Date / Time</b>	21/10/2019 ( 05:40 PM )
<b>Survey held at</b>	MOTOR INTEL AUTOMO PTE LTD 13 KAKI BUKIT ROAD 4 @ BARTLEY BIZ CENTRE #01-20 SINGAPORE 147807		

**5a. Remarks**

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,000
--

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>2 Working Days</b>
-------------------------------------	-----------------------

Report Ref No. CS3/ASM19018533/Hpb3s2

**Inspected By**

LEE HOCK ANN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.