

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III19018534/KGA3Q2

**Date:** 27/04/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> PC2590U	<b>Insured Vehicle No :</b>	SH7732H
Date of Loss: 16/10/2019	Nature of Claim: TP	Claim No: MCT19100388

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC2590U		
Make & Model:	TOYOTA REGIUS ACE, 3.0 DX M (A)	Engine No:	1KD2307546
Reg. Date:	10/04/2014 (Man. Year: 2013)	Chassis No:	KDH2010118725
Colour:	Yellow	Odometer:	496824 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,265.69	6,443.47	822.22	11.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	1,710.00	1,490.00	46.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,465.69</b>	<b>8,153.47</b>	<b>2,312.22</b>	<b>22.09</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,500.00</b>		
<b>(S\$)</b>	10,465.69	6,500.00	3,965.69	37.89
<b>+ GST 7.00/7.00% (S\$)</b>	732.60	455.00	277.60	37.89
<b>Nett Amount (S\$)</b>	<b>11,198.29</b>	<b>6,955.00</b>	<b>4,243.29</b>	<b>37.89</b>
<b>+ Car Rental (8.0 x S\$150.00/day) (S\$)</b>		1,200.00		
<b>+ Doc/Search Fee (S\$)</b>		36.45		
<b>Nett Liability (S\$)</b>		<b>8,191.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>8,190.00</b>		

### INSPECTION

Date of Assignment:	21/10/2019	
Date Inspected:	21/10/2019 Inspected At:	COMPLETE VMS PTE LTD (HQ)
		176 Sin Ming Drive #03-14 Sin Ming
		Autocare Complex
		Singapore 575721
Estimated Period of Repair:	5.0 days	

---

**Adjuster:** KENNETH KONG**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 06 Dec 2019)	
<b>Parts:</b>	N/A	TOYOTA REGIUS ACE 3.0 DX M (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for PC2590U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	786.20 FL	*786.20 FL
2	1		*BONNET HINGE	N/S Distorted	97.70 FL	*48.85 FL
3	1		*TOYOTA LOGO	Necessary	66.15 FL	*66.15 FL
4	1		*FRONT CORNER PANEL L/H	Buckled	270.29 FL	*270.29 FL
5	2		*HEADLAMP	O/S Mtg Broken / N/S Cracked	1,478.40 FL	*1,478.40 FL
6	1		*FRONT DOOR PILLAR OUTER L/H	Repair	377.08 FL	*- FL
7	1		*RADIATOR GRILLE	Cracked	464.09 FL	*464.09 FL
8	4		*RADIATOR GRILLE CLIP	Necessary	22.00 FL	*22.00 FL
9	1		*W/SCREEN WASHER TANK	Dented	149.50 FL	*149.50 FL
10	1		*FRONT SUPPORT PANEL	Bent	533.60 FL	*533.60 FL
11	1		*FRONT BUMPER	Cracked	485.00 FL	*485.00 FL
12	1		*FRONT BUMPER REINFORCEMENT	Bent	374.40 FL	*374.40 FL
13	6		*FRONT BUMPER CLIP	Necessary	39.00 FL	*39.00 FL
14	1		*FRONT BUMPER FOG LAMP COVER L/H	Missing	78.00 FL	*78.00 FL
15	1		*FRONT BUMPER TOW COVER	Missing	17.20 FL	*17.20 FL
16	1		*AIR CON CONDENSER	Bent / Punctured	1,276.00 FL	*972.10 FL
17	1		*RADIATOR ASSY	Punctured	2,068.20 FL	*1,897.60 FL
18	1		*FRONT BUMPER CENTRE GRILLE TOP	Dented	165.20 FL	*165.20 FL
19	1		*FRONT BUMPER CENTRE GRILLE BOTTOM	Distorted	185.08 FL	*185.08 FL
20	1		*FRONT BONNET LOCK	Repair	127.50 FL	*- FL
21	1		*FRONT BONNET LOCK PANEL	Repair	56.70 FL	*- FL
22	1		*RADIATOR SPARE TANK	Dented	525.30 FL	*525.30 FL
23	1		*RADIATOR COOLANT	Necessary	33.75 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>9,676.34</b>	<b>8,582.96</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>2,410.65</b>	<b>2,139.49</b>
<b>Total Parts (\$\$)</b>	<b>7,265.69</b>	<b>6,443.47</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	RUST PROOFING TREATMENT	New	100.00	60.00
2	CHARGE HEAD LAMP & DO LIGHT BEAM LEVEL ADAPTATION	New	90.00	20.00
3	REMOVE & REINSTALL FRONT W/SCREEN GLASS	New	180.00	0.00
4	SPRAY PAINT DAMAGED AREA AFFECTED	New	1,100.00	750.00
5	COMPANY LOGO AND LETTERING	New	280.00	80.00
6	TO CUT OFF L/H FRONT DOOR PILLAR ,FRONT SUPPORT PANEL,KNOCK AND STRAUGHTEN FRONT CHASSIS FRAME ,RE-ALIGN BODY AND CHANGE ALL NECESSARY PARTS	New	1,200.00	700.00
7	REMOVE & REINSTALL AIRCON CONDENSER & CHARGE GAS	New	250.00	100.00
<b>Gross Labour Cost (\$)</b>			<b>3,200.00</b>	<b>1,710.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >