

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jeannie Cheng Jin Rong

Date: 21 Nov 2019

**Preliminary Advice**

|                    |                                                                                            |                         |              |
|--------------------|--------------------------------------------------------------------------------------------|-------------------------|--------------|
| Vehicle No         | : SLC3663J                                                                                 | Accident Date           | : 08/10/2019 |
| Make               | : MERCEDES-BENZ C180                                                                       | Policy No.              | : 29123465   |
| Assignment Date    | : 21/10/2019                                                                               | Excess                  | : S\$500.00  |
| Date of Inspection | : 22/10/2019                                                                               | Est. Duration of Repair | : 10 days    |
| Inspection At      | : Cycle & Carriage Industries Pte Ltd (Pandan Loop)<br>188 Pandan Loop<br>Singapore 128378 |                         |              |

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 29,746.67 |
| Revised Amount              | :S\$ | 19,769.23 |
| Check Items (Estimated)     | :S\$ | 0.00      |
| Total                       | :S\$ | 19,769.23 |
| Lump Sum Repair             | :S\$ |           |

**Total Loss Consideration**

|                    |      |            |
|--------------------|------|------------|
| New for Old Value  | :S\$ |            |
| Pre-Accident Value | :S\$ | 107,000.00 |
| COE / PARF Rebate  | :S\$ | 63,315.00  |
| Salvage Value      | :S\$ |            |
| Margin for Repair  | :S\$ | 43,685.00  |

**Remarks**

( X ) The vehicle is economical for repair.

( ) The above survey was conducted on a 'without prejudice' basis.