

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19018579/AHA3N2

Date: 20/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994322

Claimant
Vehicle No : SKN2910G **Insured Vehicle No :** SMJ7108X

Date of Loss: 18/10/2019 Nature of Claim: TP Claim No: 0548104893SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKN2910G		
Make & Model:	HYUNDAI ELANTRA, 1.6 ABS D/AB 2WD 4DR (A)	Engine No:	G4FGEU256234
Reg. Date:	29/05/2014 (Man. Year: 2014)	Chassis No:	KMHDH41CMEU129409
Colour:	White	Odometer:	191386 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,450.56	7,917.92	13,532.64	63.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,990.00	2,690.00	1,300.00	32.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,440.56	10,607.92	14,832.64	58.30
Approved Total (Overridden) (S\$)		7,000.00		
Nett Amount (S\$)	25,440.56	7,000.00	18,440.56	72.48
+ Loss of Use (12.0 x S\$60.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		36.49		
Nett Liability (S\$)		7,756.49		
Global Sum Settlement (S\$)		7,700.00		

INSPECTION

Date of Assignment: 21/10/2019

Date Inspected: 21/10/2019 Inspected At:

Ace Autolution Pte Ltd (KAKI BUKIT)

13 Kaki Bukit Road 4, #03-29/30

Bartley Biz Centre

Singapore 417807

Estimated Period of Repair: 10.0 days

Adjuster: ADRIAN LING**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BONNET	Not Necessary	1,602.50 FL	*- FL
2	2	*FRONT BONNET HINGE LH & RH	Not Necessary	242.00 FL	*- FL
3	1	*FRONT BONNET LOCK	Not Necessary	185.70 FL	*- FL
4	1	*FRONT BUMPER	Deformed	721.40 FL	*495.00 FL
5	2	*FRONT BUMPER SIDE RETAINER LH & RH	Necessary	131.60 FL	*70.00 FL
6	2	*FRONT BUMPER SIDE BRACKET LH & RH	Not Necessary	140.60 FL	*- FL
7	2	*FRONT BUMPER FOGLAMP COVER LH & RH	Not Necessary	422.00 FL	*- FL
8	1	*FRONT BUMPER SPONGE	Cracked	152.20 FL	*152.20 FL
9	1	*FRONT BUMPER REINFORCEMENT	Not Necessary	715.20 FL	*- FL
10	1	*FRONT BUMPER LOWER AIR GRILLE	Not Necessary	410.20 FL	*- FL
11	1	*FRONT HEADLAMP LH & RH	N/S Cracked	3,688.80 FL	*1,482.30 FL
12	2	*FRONT HEADLAMP BRACKET LH & RH	Not Necessary	304.60 FL	*- FL
13	1	*FRONT GRILLE LOGO	Necessary	71.00 FL	*71.00 FL
14	1	*FRONT CHROME GRILLE	Cracked	460.20 FL	*356.00 FL
15	2	*FRONT FENDER LH & RH	Not Necessary	912.40 FL	*- FL
16	2	*FRONT FENDER INNER SHIELD LH & RH	Not Necessary	292.60 FL	*- FL
17	1	*FRONT SUPPORT PANEL	Not Necessary	959.30 FL	*- FL
18	1	*FRONT RADIATOR	Not Necessary	658.00 FL	*- FL
19	1	*FRONT A/C CONDENSER	Not Necessary	856.00 FL	*- FL
20	1	*REAR BOOTLID	Distorted	1,188.70 FL	*1,188.70 FL
21	1	*REAR BOOTLID LOGO	Necessary	61.00 FL	*61.00 FL
22	2	*REAR BOOTLID LAMP LH & RH	N/S Cut / O/S Cracked	710.00 FL	*710.00 FL
23	1	*REAR BOOTLID LOCK	Damaged	210.00 FL	*210.00 FL
24	1	*REAR BOOTLID INNER TRIM BOARD	Crumpled	290.00 FL	*290.00 FL
25	1	*REAR BOOTLID WEATHERSTRIP	Cut	125.80 FL	*125.80 FL
26	2	*REAR BOOTLID HINGE LH & RH	Bent	379.20 FL	*234.00 FL
27	1	*REAR BUMPER	Distorted	953.70 FL	*489.00 FL
28	1	*REAR BUMPER LOWER	Deformed	241.00 FL	*241.00 FL
29	2	*REAR BUMPER SIDE RETAINER LH & RH	Necessary	158.00 FL	*70.00 FL
30	2	*REAR BUMPER BRACKET LH & RH	Not Necessary	165.20 FL	*- FL
31	1	*REAR BUMPER REINFORCEMENT	Cracked	441.10 FL	*346.00 FL
32	1	*REAR BUMPER REINFORCEMENT BRACKET	Bent	176.90 FL	*176.90 FL
33	1	*REAR BUMPER UNDER COVER	Not Necessary	81.00 FL	*- FL
34	1	*REAR BUMPER INNER KEYLESS SENSOR	Cracked	228.00 FL	*85.00 FL
35	1	*REAR BUMPER INNER SPONGE	Not Necessary	162.80 FL	*- FL
36	2	*REAR BUMPER MUD FLAP LH & RH	Not Necessary	150.40 FL	*- FL
37	2	*REAR TAILLAMP LH & RH	Cracked	1,459.20 FL	*727.00 FL
38	1	*REAR END PANEL	Distorted	485.90 FL	*485.90 FL
39	1	*REAR END PANEL TOP GARNISH	Deformed	203.10 FL	*203.10 FL
40	2	*REAR FENDER INNER TRIM BOARD LH & RH	Torn	1,098.40 FL	*535.00 FL
41	2	*REAR FENDER LH & RH	Repair	1,543.00 FL	*- FL
42	1	*REAR SPARE TYRE PANEL	Repair	982.00 FL	*- FL
43	1	*REAR SPARE TYRE PANEL TOP COVER	Deformed	280.00 FL	*280.00 FL
44	1	*REAR SPARE TYRE PANEL SEALANT	Necessary	360.00 FS	*200.00 FS
45	1	*SET FRONT CAR PLATE WITH HOLDER	Cracked	70.00 FS	*60.00 FS
46	1	*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
47	1	*SET FRONT FENDER COWLING CLIPS	Not Necessary	100.00 FS	*- FS
48	1	*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
49	1	*REVERSE CAMERA	Not Necessary	350.00 FS	*- FS
50	1	*SET REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
51	1	*SET REAR CAR PLATE WITH HOLDER	Deformed	70.00 FS	*60.00 FS
52	1	*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
53	1	*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	80.00 FS	*10.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*COOLANT	Not Necessary	100.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$)	26,390.70
					9,734.90	
					- List Item Discount on L Items 20.00/20.00% (\$)	4,940.14
						1,816.98
					Total Parts (\$)	21,450.56
						7,917.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,800.00	1,400.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY RESPRAY PAINT ON PARTS REPLACED	New	1,400.00	1,000.00
3	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS	New	100.00	60.00
4	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	200.00	60.00
5	TO REMOVE AND REPLACE REVERSE SENSORS AND CHECK FOR PROPER FUNCTIONS	New	120.00	50.00
6	TO REMOVE AND REFIX REAR BOOT MECHANISM	New	150.00	60.00
7	TO TOP UP COOLANT	New	120.00	0.00
8	TO TUFF COAT	New	100.00	60.00
Gross Labour Cost (\$\$)			3,990.00	2,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >