

VEHICLE NO: FBK 3624Z

BAJAJ PULSAR 200NS FI

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
	<b>PARTS</b>			
1	Front Headlamp Assembly X		450.00	
1	Front Headlamp top cover X		78.00	
1	RHS Front fairing outer cover X		350.00	
1	RHS fairing inner garnish X		250.00	
2	Front spring fork RH & LH @450.00 X		900.00	
1	Front steering stem upper X		150.00	
1	Front steering stem lower X		230.00	
2	Front steering bearing (upper & lower) / APC		140.00	98 /
1	Handle bar / BT		150.00	135 /
1set	Handle bar grips / CUT		50.00	30 /
1set	Handle bar balancer / BT		75.00	25 /
1	RHS Side mirror assy X		160.00	
1	RHS Front signal lamp / BR		120.00	60 /
1	RHS Rear signal lamp / BR		120.00	60 /
1	Clutch lever X		35.00	
1	Front wheel Fender / CUT		80.00	/
1	Rear wheel fender X		120.00	
1	RHS side stand X		55.00	
1	Inner chassis securing bracket front X		98.00	
1	Rear Brake pedal / BT		75.00	55 /
1	Brake pedal foot rest / BT		55.00	35 /
			3741.00	
		less 10%	374.10	
			3366.90	
	<b>SPECIAL NETT ITEMS</b>			
1	Front number plate / CUT		45.00	30 /
1	RHS Front protector guard / BT		98.00	/
1	Rear top box assembly / CUT		300.00	/
1	Rear top box bracket support / BT		100.00	/
	<b>TOTAL PARTS</b>		3909.90	

578  
-19%  
570.70

578

VEHICLE NO: FBK 3624Z      BAJAJ PULSAR 200NS FI

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	<b>LABOUR</b>		
1	To remove and replace damaged parts and components	450.00 250	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	250.00 200	
3	To remove, refix wiring system at accident damaged	60.00 30	
4	To align front left & right fork	60.00 /	
5	Transport motorcycle to workshop for repairs	60.00 50	
	Labour Total :	880.00	590
	TOTAL (PARTS & LABOUR):	4789.90	

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

Steve (LKK) WHL Arrive 21/10/19  
 8322 8813 L/S  
 Rj AL SPJ

P-520.20

NI-528

L-590

1638.20

L/S-1310.56

= 1300

3 repair days

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: