

2/03/2002

ASS. REC. BY:

REF: CS/CT2 19018603/kvf367 Special Instruction:

Surveyor: Kenneth ASSIGNMENT (Office)

From (Person): Tan Kah Leong of CTI Date/Time: 22.10.19 8.40a.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLK 2959X Insured: SLP 5933Z

at Workshop m/s Estium Performance Tel: 67532112 | 64841221

of 385 Sin ming Drive

Policy No: DM PSN 3042131920 Claim No: SNM190704942

Sum Insured: Excess:

Make of Veh: D.O.A. 17.10.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 22.10.19 9.44 a.m Person Contacted: Jenny H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLK 2959X - X
	SLP 5933Z - X
	1771.42
29/11	@ 1786.36 email & confirm (Red 2026.48, 5319)

ASS. REC. BY:

REF: 0121

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLK 2959X Yr Regn: 01, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Toy Pnu c.c. 1798

Colour: M. Silver A/C: Insured / Std / NI / NA

Sp. Reading: 176753 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: J70KB3F403542277

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pavani

Front

Rear

R/Bal. 7 mm

R/Bal. 7 mm

L/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 17/10/19

D.O.I. 22/10/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to

RECEIVED 29 10 2019

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 29/11 -typist

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) 1771.42

meimen

270

270

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Oct 2019		22 Oct 2019 08:40 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	[Created by insurer]		
Main Claimant:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Vehicle Reg. No.:	SLK2959X	Date of Loss:	17/10/2019 18:00 - :59
Claim Type:	TP / SNM19D204942-SLP5933Z-TKL	Policy/Cover Note No.:	DMPCSN3042131900 (Comprehensive) Coverage: 12/06/2019 - 11/06/2020
Vehicle Reg. No. (Insured):	SLP5933Z	Policy No. (Claimant):	A29114756MKF
Repairer:	Esteem Performance Pte Ltd - Sin Ming (HQ) 385 Sin Ming Drive, 575718 Sin Ming - Tel: 63896193		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/11/2019]		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Complete Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/10/2019 09:53
Date Of Accident	17/10/2019 18:20
Exact Location Of Accident	JUNC OF ROCHOR RD / NORTH BRIDGE RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK2959X
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-31388644

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS HYBRID-1.8 CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29114756MKF
Cover Note Number	

Driver

Name of Driver	ONG LONG HAN
NRIC No	S7400074F
Date Of Birth	01/01/1974
Occupation	OUTDOOR
Date Of Driving Pass	23/08/1994
Driving Experience	25 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97263387
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 722 JURONG WEST AVE 5 #09-136
Postcode	640722
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - LESSEE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NOT APPLICABLE GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 17/10/19 AT AROUND 6:20PM, I WAS DRIVING MY CAR ALONG ROCHOR ROAD TOWARDS BUKIT TIMAH. AS I MOVE OFF AT THE TRAFFIC JUNCTION OF ROCHOR ROAD AND NORTH BRIDGE ROAD ON LANE 1, VEHICLE B DROVE UP FROM BEHIND AND COLLIDED INTO MY CAR'S REAR. MY CAR SUSTAINED REAR BUMPER DAMAGE. VEHICLE B SUSTAINED FRONTAL DAMAGE. NO ONE WAS INJURED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	SD CARD WITH WORKSHOP
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLP5933Z
Vehicle Make/Model/Colour	HONDA / CIVIC
Details Of Properties	VEH B
Vehicle Category	PRIVATE CAR
Name of Driver	LAWRENCE JOSHUA NAN YONG LIANG
NRIC/Passport Number	S8243826B
Contact Number	87495398
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

FRONT PORTION

1

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

CLASSIC SketchPlanForm_V3

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 17/10/2019 at around 6.30 p.m., I was driving my car (Veh. A SLK 2959 X) along Rochor Road towards Bukit Timah. As I move off at the traffic junction of Rochor Rd. and North Bridge Rd on lane 1, Veh. B. (SLP 5933 Z) drove up from behind and collided into my car's rear. My car sustained rear bumper damage. Veh. B sustained frontal damage. No one was injured.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

09.45am

18/10/19

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

1033RMC SketchPlanForm_V3

Esteem Performance Pte Ltd
385 Sin Ming Drive, Vicom Vehicle
Inspection Centre (575718)

Insurer Reference:
Repairer Reference: 019387
Date calculated: 18/10/2019 12:57 PM

Full Report
Registration: SLK2959X
Printed: 18/10/2019 12:57 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Carmen SG	Currency:	SGD
Claim Reference:		Date of Incident:	17/10/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	PRIUS IV
Sub Model:	BASE MODEL
Model Sheet Number:	70 P5 01
Registration:	SLK2959X
VIN number:	
Odometer:	

*Not Authorised
Repair B4 repair
2 days*


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Time Base 10 WU/h

Price = 50.00 SGD/h

Code	Description	WU	Price SGD
B290	RENEW REAR END PANEL	39.0	195.00
B420	RENEW REAR BUMPER INCLUDES: REAR BUMPER AND REQUIRED ATTACHED PARTS R + R	12.0	60.00
B410)	R + R REAR BUMPER REINFORCEMENT	1.0	5.00
B450	R + R REAR SEAT CUSHION CPL	2.0	10.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		5.40	54.0
Total of Labour			270.00

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h
Code	Description	WU	Price SGD
	REAR PANEL NEW PART PAINTING	17.0	
	REAR BUMPER NEW PART PAINT K1R	10.0	
	BOOT/T-GATE MOULDING SURFACE PAINT PLAST.	5.0	

Paint Material Per Part

Code	Description	Price SGD
2711	REAR PANEL NEW PART PAINTING	16.61
2583	REAR BUMPER NEW PART PAINT K1R	39.09
2979	BOOT/T-GATE MOULDING SURFACE PAINT PLAST.	10.18

Labour Cost - Paint

	Factor	50.00 SGD/h	Hrs	WU	Price SGD
	Time Paint			32.0	
	Preparation Main Work Metal		1.70	17.0	85.00
	Preparation Comp. Work Plastic		0.30	3.0	15.00
Total		10 WU/h	5.20	52.0	260.00

Material Cost - Paint

	Price SGD
New Part Painting	16.61
New Part Painting - Plastic K1R	39.09
Surface Painting Plastic	10.18
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	92.98

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
2583	REAR BUMPER	52159 47913		Buckem 497.50 ✓✓
2587	REAR COVER BUMPER	52453 47010		cm 582.60 ✓✓
2589	REAR BUMPER COVER	52169 47020		nu 31.70 ✓✓
2621	LEFT RETAINER	90467 09237		su 112.70 x

Code	Description	Part Number	Supplier	Price SGD	
2622	RIGHT RETAINER	90467 09237		112.70	X
2640	REAR BUMPER REINF	52023 47030		398.90	7✓
2711	REAR PANEL	58307 47090		596.60	X
2944	BOOT/TAILGATE SEAL	67881 47050		353.10	X
3285	L/R LOWER LAMP	81591 47021		511.60	X
3286	R/R LOWER LAMP	81581 47020		511.60	X
1000	REAR BUMPER CLIP	R.BUMPER CLIP		40.00	✓
1001	END PANEL GARNISH	E.PANEL GARNISH		151.60	X
1002	E.PANEL GARNISH CLIP	CLIP		35.00	X

f: OEM Parts	Savings	0.00
n: Non-OEM Parts	Subtotal	3,935.60
u: Used parts	Subtotal Discount(+30.00%)	-1,180.68
	Total	2,754.92

Extras

Code	Description	Price SGD	
1003	REVERSE SENSOR REVERSE SENSOR	200.00*	✓✓
1004	R&R REVERSE SENSOR LABOUR	120.00*	50.✓
1005	TUFF COAT TUFF COAT	100.00*	X
	Total Extras	420.00	

Final Calculation

	SGD	SGD
Parts	3,935.60	
Total Discount(+30.00%)	-1,180.68	
Total Parts		2,754.92
Labour Time Base 10 WU/h		
Total 54.0 WU X 50.00 SGD/h	270.00	140
Total of Labour		270.00
Total Of Extras		420.00
Paint Work Time Base 10 WU/h		
Labour Cost 52.0 WU X 50.00 SGD/h	260.00	190
Material Cost	92.98	105.93
Total Paint Including Material		352.98
Repair Cost Excludes GST		3,797.90
GST (+7.0%)		265.85
Repair Cost Included GST		4,063.75

7/610-85

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

Esteem Performance Pte Ltd
385 Sin Ming Drive, Vicom Vehicle
Inspection Centre (575718)

Insurer Reference:
Repairer Reference: 019387
Date calculated: 27/11/2019 7:46 PM

Full Report
Registration: SLK2959X
Printed: 27/11/2019 7:46 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Carmen SG	Currency:	SGD
Claim Reference:		Date of Incident:	17/10/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	PRIUS IV
Sub Model:	BASE MODEL
Model Sheet Number:	70 P5 01
Registration:	SLK2959X
VIN number:	
Odometer:	

Model Specs

TWO COAT METALLIC


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h WU Price SGD	
B420	RENEW REAR BUMPER INCLUDES: REAR BUMPER AND REQUIRED ATTACHED PARTS R + R		12.0	60.00
B410)	R + R REAR BUMPER REINFORCEMENT		1.0	5.00
2711	REAR PANEL REPAIR		15.0*	75.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		2.80	28.0	140.00
Total of Labour				140.00

Paint

Code	Description - TWO COAT METALLIC	Time Basis 10 WU/h WU Price SGD
	REAR BUMPER NEW PART PAINT K1R	12.0
	REAR PANEL SURFACE PAINT	5.0
	BOOT/T-GATE MOULDING SURFACE PAINT PLAST.	5.0

Paint Material Per Part

Code	Description	Price SGD
2583	REAR BUMPER NEW PART PAINT K1R	55.10
2711	REAR PANEL SURFACE PAINT	9.46
2979	BOOT/T-GATE MOULDING SURFACE PAINT PLAST.	14.27

Labour Cost - Paint

Factor	50.00 SGD/h	Hrs	WU	Price SGD
Time Paint			22.0	
Preparation Main Work Metal		1.10	11.0	55.00
Preparation Comp. Work Plastic		0.50	5.0	25.00
Total	10 WU/h	3.80	38.0	190.00

Material Cost - Paint

	Price SGD
New Part Painting - Plastic K1R	55.10
Surface-/Blend Paint	9.46
Surface Painting Plastic	14.27
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	105.93

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01 Price SGD
2583	REAR BUMPER	52159 47913		497.50

Code	Description	Part Number	Supplier	Price SGD
2587	REAR COVER BUMPER	52453 47010		582.60
2589	REAR BUMPER COVER	52169 47020		31.70
2640	REAR BUMPER REINF	52023 47030		398.90
1000	REAR BUMPER CLIP	R.BUMPER CLIP		40.00

f: OEM Parts	Savings	0.00
n: Non-OEM Parts	Subtotal	1,550.70
u: Used parts	Subtotal Discount(+30.00%)	-465.21
	Total	1,085.49

Extras

Code	Description	Price SGD
1004	R&R REVERSE SENSOR LABOUR	50.00*
1006	REVERSE SENSOR REVERSE SNESOR	200.00*
	Total Extras	250.00

Final Calculation

	SGD	SGD
Parts		
Total Discount(+30.00%)	1,550.70	
	-465.21	
Total Parts		1,085.49
Labour Time Base 10 WU/h		
Total 28.0 WU X 50.00 SGD/h	140.00	
Total of Labour		140.00
Total Of Extras		250.00
Paint Work Time Base 10 WU/h		
Labour Cost 38.0 WU X 50.00 SGD/h	190.00	
Material Cost	105.93	
Total Paint Including Material		295.93
Repair Cost Excludes GST		1,771.42
GST (+7.0%)		124.00
Repair Cost Included GST		1,895.42

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Oct 2019		22 Oct 2019 08:40 Edit Adj Rpt	S\$1,771.42 Edit Estimates	S\$1,771.42 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	0, Co. Reg. No.: 0								
Main Claimant:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Vehicle Reg. No.:	SLK2959X	Date of Loss:	17/10/2019 18:00 - :59 [33 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D204942-SLP5933Z-TKL	Policy/Cover Note No.:	DMPCSN3042131900 (Comprehensive) Coverage: 12/06/2019 - 11/06/2020						
Vehicle Reg. No. (Insured):	SLP5933Z	Policy No. (Claimant):	A29114756MKF						
		Excess:	S\$500.00						
Repairer:	Esteem Performance Pte Ltd - Sin Ming (HQ) 385 Sin Ming Drive, 575718 Sin Ming - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 01/11/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLK2959X (SNM19D204942-SLP5933Z-TKL)
[SLP5933Z]
TP
GRAB RENTALS PTE LTD
Oct 17 2019 6:00PM
[0]
Esteem Performance Pte Ltd - Sin Ming

Upload Documents Upload Photos Compose New Letter

View View in Browser

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/11/19 09:46	General View	Load PDF	
2	29/11/19 09:46	Reinspection Photo	Load PDF	

Linked Accident Report Documents

View View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Formteam Accident Services Taskforce Pte Ltd (HQ)	Thumbnail	Print
1	18/10/19 10:22	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Formteam Accident Services Taskforce Pte Ltd (HQ)	Thumbnail	Print
1	18/10/19 10:18	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	18/10/19 10:18	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	18/10/19 10:18	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	18/10/19 10:18	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	18/10/19 10:18	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	18/10/19 10:18	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	18/10/19 10:18	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	18/10/19 10:18	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	18/10/19 10:21	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	18/10/19 10:21	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	18/10/19 10:21	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	18/10/19 10:21	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	18/10/19 10:21	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
14	18/10/19 10:21	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
15	18/10/19 10:21	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
16	18/10/19 10:21	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
17	18/10/19 10:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Formteam Accident Services Taskforce Pte Ltd (HQ)	Thumbnail	Print
1	18/10/19 10:17	Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	18/10/19 10:17	Sketch Plan #2	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>
--

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119018608/KVF3E2

Date: 02/12/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3042131900		
Claimant Vehicle No :	SLK2959X	Insured Vehicle No :	SLP5933Z		
Date of Loss:	17/10/2019	Nature of Claim:	TP	Claim No:	SNM19D204942-SLP5933Z-TKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK2959X		Engine No:	2ZRR985740
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)		Chassis No:	JTDKB3FU403542277
Reg. Date:	12/01/2017 (Man. Year: 2016)		Odometer:	176753 km
Colour:	Metallic Silver			
Engine Capacity:	1798 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 7 mm	Rear Left Side:	Davanti 7 mm
Front Right Side:	Davanti 7 mm	Rear Right Side:	Davanti 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,954.92	1,285.49	1,669.43	56.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	855.93	485.93	370.00	43.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,810.85	1,771.42	2,039.43	53.52
+ GST 7.00/7.00% (S\$)	266.76	124.00	142.76	53.52
Nett Amount (S\$)	4,077.61	1,895.42	2,182.19	53.52

INSPECTION

Date of Assignment:	22/10/2019	
Date Inspected:	22/10/2019 Inspected At:	Esteem Performance Pte Ltd - Sin Ming (HQ) 385 Sin Ming Drive Singapore 575718
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Dec 2019)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK2959X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Cracked	497.50 FL	*497.50 FL
2	1		*REAR COVER BUMPER	Cracked	582.60 FL	*582.60 FL
3	1		*REAR BUMPER COVER	Dented	31.70 FL	*31.70 FL
4	1		*LEFT RETAINER	Serviceable	112.70 FL	*- FL
5	1		*RIGHT RETAINER	Serviceable	112.70 FL	*- FL
6	1		*REAR BUMPER REINF	Bent	398.90 FL	*398.90 FL
7	1		*REAR PANEL	Repair	596.60 FL	*- FL
8	1		*BOOT / TAILGATE SEAL	Serviceable	353.10 FL	*- FL
9	1		*L/R LOWER LAMP	Serviceable	511.60 FL	*- FL
10	1		*R/R LOWER LAMP	Serviceable	511.60 FL	*- FL
11	1		*REAR BUMPER CLIP	Necessary	40.00 FL	*40.00 FL
12	1		*END PANEL GARNISH	Serviceable	151.60 FL	*- FL
13	1		*E.PANEL GARNISH CLIP	Not Necessary	35.00 FL	*- FL
14	1		*REVERSE SENSOR	Dented	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,135.60	1,750.70
- List Item Discount on L Items 30.00/30.00% (\$\$)	1,180.68	465.21
Total Parts (\$\$)	2,954.92	1,285.49

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R REVERSE SENSOR	New	120.00	50.00
2	TUFF COAT	New	100.00	0.00
3	54.0 WU X 50.00 SGD/H	New	270.00	140.00
4	LABOUR COST 52.0 WU X 50.00 SGD/H	New	260.00	190.00
5	MATERIAL COST	New	105.93	105.93
Gross Labour Cost (S\$)			855.93	485.93

Report was unsubmitted during this print-out.

< END OF ESTIMATES >