



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FV 8060L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
2	HANDLE BAR @\$78.00	N/S BENT	156.00	78.00
2	HANDLE BAR GRIP @\$25.00	NOT NECESSARY	50.00	-
2	HANDLE BAR BALANCER @\$12.00	N/S CUT	24.00	12.00
1	BRAKE LEVER	NOT NECESSARY	25.00	-
1	BRAKE LEVER CABLE	NOT NECESSARY	45.00	-
1	CLUTCH LEVER	CUT	25.00	25.00
1	R/H THROTTLE UNIT	NOT NECESSARY	180.00	-
1	R/H THROTTLE UNIT CABLE	NOT NECESSARY	65.00	-
2	MIRROR ASSY @\$45.00	DAMAGED	90.00	90.00
1	SPEEDOMETER UNIT	CRACKED	380.00	380.00
1	SPEEDOMETER UNIT BRACKET	BENT	120.00	120.00
1	HEADLAMP	MISSING	110.00	110.00
1	HEADLAMP STAY	BENT	45.00	45.00
1	HEADLAMP COWLING	MISSING	110.00	110.00
2	FRONT SIGNAL LAMP @\$25.00	MISSING	50.00	50.00
2	FRONT SIGNAL LAMP GARNISH @\$35.00	DEFORMED	70.00	70.00
1	HORN	DAMAGED	35.00	35.00
1	HORN BRACKET	BENT	35.00	35.00
1	FRONT VISOR	MISSING	55.00	55.00
1	FRONT MUDGUARD	CRACKED	45.00	45.00
2	FRONT FORK @\$250.00	BENT	500.00	500.00
1	FRONT FORK CENTRE BRACKET	BENT	65.00	65.00
1	FRONT FORK TOP BRACKET	BENT	80.00	80.00
1	FRONT FORK CENTRE BRACKET	BENT	80.00	80.00
1	FRONT RIM	NOT NECESSARY	250.00	-
1	RADIATOR	DENTED	280.00	280.00
1	RADIATOR LOWER HOSE	NOT NECESSARY	25.00	-
2	FRONT FAIRING @\$160.00	MISSING	320.00	320.00
1	FUEL TANK	DENTED	350.00	350.00
2	REAR FAIRING @\$150.00	N/S CUT	300.00	150.00
1	FRONT L/H FOOTREST WITH BRACKET	CRACKED	45.00	45.00

Report Ref No. CS/FCI19018658/Atd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT L/H GEARSHIFT LEVER	CUT	65.00	65.00
1	REAR FOOTREST L/H	CUT	25.00	25.00
1	L/H SIDE STAND	NOT NECESSARY	35.00	-
1	REAR RIM	NOT NECESSARY	250.00	-
	LESS 10% DISCOUNT		-438.50	-322.00
			3,946.50	2,898.00
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT TYRE (SN)	NOT NECESSARY	150.00	-
1	REAR TYRE (SN)	NOT NECESSARY	120.00	-
			270.00	-
	<u>LABOUR</u>			
	TO PANEL BEATING, WELDING, REMOVING DAMAGED PARTS AND REPLACEMENT OF THE NEW PARTS AS MENTIONED ABOVE ETC.		500.00	280.00
	TO APPLY UNDERSEAL.		50.00	30.00
	TO RESPRAY AFFECTED PART.		350.00	250.00
	TRANSPORTATION CHARGES.		40.00	40.00
	TO CHECK WIRINGS.		30.00	30.00
			970.00	630.00
GRAND TOTAL			5,186.50	3,528.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (REPAIR COST NOT CONCLUDE)				2,800.00

Report Ref No. CS/FCI19018658/Atd3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.