

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 2523K

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	R/R DOOR TAPE (N) (CONSISTENT)	NECESSARY	25.50	25.50
1	R/R DOOR TAPE (N) (CONSISTENT)	NECESSARY	19.50	19.50
1	DOOR -REAR RH (N) (CONSISTENT)	BADLY DENTED	919.60	919.60
1	R/F DOOR TAPE (N) (CONSISTENT)	NECESSARY	19.50	19.50
1	R/F DOOR TAPE (N) (CONSISTENT)	NECESSARY	19.50	19.50
1	DOOR -FRONT RH (N) (CONSISTENT)	DENTED	919.60	919.60
1	FENDER-FRONT RH (N) (CONSISTENT)	DENTED	598.80	598.80
	LESS 20% DISCOUNT		-504.40	-504.40
	ADDITIONAL 5% DISCOUNT		-	-100.88
			2,017.60	1,916.72
	SPECIAL NETT ITEMS			
1	SUNDRIES (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
			50.00	-
	<u>LABOUR</u>			
	LABOUR CHARGES TO REPAIR RH CENTER PILLAR ,RENEW RH FRT FENDER AND BOTH RH DOORS.		780.00	500.00
	CHARGES TO SPRAY PAINTING SAME.		900.00	800.00
	REMOVE AND INSTALL BOTH RH DOORS MECHANISM.		160.00	160.00
	APPLY SEALANT TO BOTH RH DOORS.		200.00	200.00
	ADDITIONAL 5% DISCOUNT		-	-83.00
			2,040.00	1,577.00
	GRAND TOTAL		4,107.60	3,493.72

RECOMMENDED COST OF REPAIRS		3,493.72

Report Ref No. CC4/ASM19018663/Uga3q2

CHUA KANG SENG
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.