



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19018663/Uga3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN:LYNN

Date : 09-04-2020



Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |            |                |            |
|--------------|------------|----------------|------------|
| Insured Veh. | SJU 5416Y  | Veh. Inspected | SLH 2523K  |
| Policy No.   | GA471408/1 | Coverage (\$)  | 0.00       |
| Claim No.    | S9M023ZG   | Excess (\$)    | 0.00       |
| Assign From  |            | Assign Date    | 22/10/2019 |

### 2. Vehicle Particulars & Condition

|              |                     |              |            |
|--------------|---------------------|--------------|------------|
| Make & Model | NISSAN NOTE OPC (A) | c.c          | 1198       |
| Engine No.   | HIDDEN              | Year of Reg. | 2016       |
| Chassis No.  | JN1TBAE12Z0982830   | Colour       | RED        |
| Odometer     | 19482               | Steering     | IN ORDER   |
| Brakes       | IN ORDER            | Modification | SPORTS RIM |
| General      | GOOD                |              |            |

### 3. Conditions of Tyres

|                | Size       | Make        | Balance |
|----------------|------------|-------------|---------|
| R/H Front Tyre | 185/65 R15 | CONTINENTAL | 8 mm    |
| L/H Front Tyre | 185/65 R15 | CONTINENTAL | 8 mm    |
| R/H Rear Tyre  | 185/65 R15 | CONTINENTAL | 8 mm    |
| L/H Rear Tyre  | 185/65 R15 | CONTINENTAL | 8 mm    |

### 4. Description of Damages

|                                                                        |
|------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.<br>DAMAGES SEE DETAILS. |
|------------------------------------------------------------------------|

### 5. General Information

|                |                                                                    |                 |            |
|----------------|--------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 15/10/2019                                                         | Inspection Date | 05/11/2019 |
| Survey held at | AUTOLUTION INDUSTRIAL PTE LTD<br>19 UBI ROAD 4<br>SINGAPORE 408623 |                 |            |

### 5a. Remarks

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

### 5b. Estimate Days of Repair

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 4 Working Days |
|-------------------------------------|----------------|