



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JQH 1173

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	HANDLE BAR (CONSISTENT)	BENT	135.00	135.00
1	HEAD LAMP (CONSISTENT)	CUT	280.00	280.00
1	HEAD LAMP COVER (CONSISTENT)	CUT	180.00	180.00
1	FRONT COVER (CONSISTENT)	CUT	145.00	145.00
1	FRONT SIGNAL LH (CONSISTENT)	BROKEN	65.00	65.00
1	LEG SHIELD (CONSISTENT)	NOT NECESSARY	135.00	-
1	FRONT MUDGUARD (CONSISTENT)	TO REPAIR SEE LABOUR	250.00	-
1	FORK UNDER BRACKET (CONSISTENT)	DAMAGED	135.00	135.00
1	SET FRONT FORK (CONSISTENT)	DISTORTED / BENT	480.00	480.00
1	FRONT LH SIDE FAIRING (CONSISTENT)	BROKEN	135.00	135.00
1	GEAR PEDAL (CONSISTENT)	NOT NECESSARY	65.00	-
1	FRONT FOOTREST (CONSISTENT)	NOT NECESSARY	75.00	-
1	FOOTREST RUBBER (CONSISTENT)	NOT NECESSARY	55.00	-
1	SET MIRROR (O/S) (CONSISTENT)	BROKEN	135.00	135.00
1	BRAKE LEVER (CONSISTENT)	CUT	65.00	65.00
1	FRONT RH FAIRING (CONSISTENT)	CUT	155.00	155.00
1	EXHAUST GUARD (CONSISTENT)	CUT	185.00	185.00
1	PILLION GRIP (CONSISTENT)	CUT	65.00	65.00
1	REAR RH FOOTREST (CONSISTENT)	CUT	78.00	78.00
1	METER COVER (CONSISTENT)	NOT NECESSARY	210.00	-
1	LH FAIRING INNER GARNISH (CONSISTENT)	CUT	158.00	158.00
1	FRONT RIM (CONSISTENT)	TO REPAIR SEE LABOUR	325.00	-
1	RADIATOR ASSY (CONSISTENT)	BENT / PUNCTURE	350.00	350.00
	LESS 10% DISCOUNT		-386.10	-274.60
			3,474.90	2,471.40
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT NUMBER PLATE (SN) (CONSISTENT)	NECESSARY	25.00	15.00
1	REAR NUMBER PLATE (SN) (CONSISTENT)	NOT NECESSARY	15.00	-
			40.00	15.00

Report Ref No. CC4/ASM19018670/Dgs3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TOWING FEE.	NOT NECESSARY	40.00	-
	REMOVE & REPLACE NECESSARY PARTS,ALIGN & ETC.INCLUSIVE OF THE REPAIR OF FRONT MUDGUARD AND FRONT RIM.		280.00	200.00
	REMOVE & REPLACE FORK ASSY ,RIM & TOP UP FORK OIL.		150.00	80.00
	SUPPLY BODY DECAL STICKER .		120.00	80.00
			590.00	360.00
	GRAND TOTAL		4,104.90	2,846.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,700.00

Report Ref No. CC4/ASM19018670/Dgs3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.