




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM19018670/Dgs3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:JAS			Date : 19-10-2020	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGP 9828C	Veh. Inspected	JQH 1173	
Policy No.	GA416063	Coverage (\$)	0.00	
Claim No.	S9M021Z5	Excess (\$)	0.00	
Assign From		Assign Date	22/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA 135LC	c.c	135	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	PMYUG0410E0244650	Colour	MULTI COLOUR	
Odometer	23594	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	70/90 R17	MAXXIS	3 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	80/90 R17	MAXXIS	3 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION & N/S AND O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/09/2019	Inspection Date	22/10/2019	
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		