

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19018671/EKA3Q2

Date: 02/06/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SKM1276R **Insured Vehicle No :** SLL3655K

Date of Loss: 19/10/2019 **Nature of Claim:** TP **Claim No:** 4886716025SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKM1276R		
Make & Model:	BMW 218I, 1.5 CONVERTIBLE HID ABS NAV (A)	Engine No:	F4471560B38B15A
Reg. Date:	30/03/2017 (Man. Year: 2016)	Chassis No:	WBA1M32050V819724
Colour:	Black	Odometer:	23788 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,189.20	3,308.20	881.00	21.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,632.00	5,273.00	1,359.00	20.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	10,821.20	8,581.20	2,240.00	20.70
+ GST 7.00/7.00% (\$\$)	757.48	600.68	156.80	20.70
Nett Amount (\$\$)	11,578.68	9,181.88	2,396.80	20.70
+ Loss of Use (8.0 x S\$60.00/day) (\$\$)		480.00		
+ Medical Costs (\$\$)		70.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		9,739.33		

INSPECTION

Date of Assignment: 18/12/2019

Date Inspected: 18/12/2019 Inspected At:

Performance Motors Limited
(Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*NO PLATE	Bent	83.00 FS	*83.00 FS
3	1		*BOOTLID	Dented	1,141.80 FS	*1,141.80 FS
4	1		*REAR BUMPER CARRIER	Not Necessary	416.45 FS	*- FS
5	1		*REAR BUMPER CENTRE GUIDE	Broken	61.35 FS	*61.35 FS
6	1		*LH SIDE GUIDE FOR BUMPER	Not Necessary	55.75 FS	*- FS
7	1		*RH SIDE GUIDE FOR BUMPER	Not Necessary	55.75 FS	*- FS
8	1		*REAR BUMPER TRIM STRIP (LINE SPORT)	Broken	91.15 FS	*91.15 FS
9	1		*REAR BUMPER PANEL PRIMED (BASIS)	Dented	1,024.65 FS	*1,024.65 FS
10	1		*TAIL LIGHT RH	Broken	450.00 FS	*403.80 FS
11	4		*DECOUPLING RING PDC TORQUE CONVERTE	Necessary	20.40 FS	*20.40 FS
12	1		*RR PDC SENSOR BLACK SAPPHIRE (475)	Not Necessary	236.85 FS	*- FS
13	1		*SET MOUNTS PDC SENSOR REAR	Necessary	58.90 FS	*58.90 FS
14	2		*EXPANDING NUT	Necessary	2.00 FS	*2.00 FS
15	1		*EMBLEM ADHERED REAR 218I	Necessary	64.45 FS	*64.45 FS
16	1		*BOOTLID /TAILGATE PUSH BUTTON	Necessary	48.65 FS	*48.65 FS
17	1		*THIRD STOPLAMP	Necessary	175.00 FS	*175.00 FS
18	1		*(DG/SL) ADHESIVE SET K6	Necessary	53.05 FS	*53.05 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 4,189.20 3,308.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACING REAR BUMPER PANEL AND ATTACHMENTS ,BOOTLID REWORK TAIL PANEL	New	3,400.00	2,550.00
2	SPRAY BUMPER ,BOOTLID AND TAIL PANEL	New	2,666.00	2,473.00
3	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	0.00
4	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
5	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
Gross Labour Cost (\$\$)			6,632.00	5,273.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >