



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

LONPAC INSURANCE BHD  
300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555

INV No. AC2005268  
INV Date 28/07/2020  
Reference CC4/LPC19018672/R1ba3n2  
Code LPC2



### PROFESSIONAL SERVICE FEE

Vehicle No. SLZ 8561R  
Insured Veh. SJF 3505R  
Claim No. 19/19/19/VP05/022549  
Policy No. Z19VP05023267  
Accident Date 21/10/2019  
Inspection Date 22/10/2019

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

*HYN*



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC19018672/R1ba3n2

300 BEACH ROAD  
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 28-07-2020



Code : LPC2

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJF 3505R	Veh. Inspected	SLZ 8561R
Policy No.	Z19VP05023267	Coverage (\$)	0.00
Claim No.	19/19/19/VP05/022549	Excess (\$)	0.00
Assign From	GERALD	Assign Date	22/10/2019

### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA C-HR 1.2 T A A	c.c	1197
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JTNKY3BXX01007010	Colour	RED
Odometer	21508	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R17	DUNLOP	6 mm
L/H Front Tyre	215/60 R17	DUNLOP	6 mm
R/H Rear Tyre	215/60 R17	DUNLOP	6 mm
L/H Rear Tyre	215/60 R17	DUNLOP	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	21/10/2019	Inspection Date	22/10/2019
Survey held at	BORNEO MOTORS (S) PTE LTD 17 UBI ROAD 4 SINGAPORE 408611		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 8561R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	COVER,RR BUMPER (SN)	DEFORMED	353.10	353.10
1	GUARD,RR BUMPER (SN)	DEFORMED	372.70	372.70
6	OUTSIDE RETAINER (SN)	NECESSARY	23.40	23.40
1	PLATE,RR BUMPER (SN)	CUT	17.70	17.70
1	RETAINER,RR BUMPER (SN)	SERVICEABLE	102.20	-
1	RETAINER,RR BUMPER (SN)	SERVICEABLE	51.70	-
1	RETAINER,RR BUMPER (SN)	SERVICEABLE	102.20	-
1	RETAINER,RR BUMPER (SN)	SERVICEABLE	51.70	-
1	REINFORCEMENT (SN)	BENT	332.70	332.70
1	PLATE,RR BUMPER,RH (SN)	SERVICEABLE	90.80	-
1	PLATE,RR BUMPER,LH (SN)	SERVICEABLE	90.80	-
10	PIECE,RR BUMPER (SN)	NECESSARY	41.00	41.00
1	STAY RR BUMPER (SN)	SERVICEABLE	32.30	-
1	BRACKET,FOG LAMP (SN)	SERVICEABLE	80.20	-
1	REFLECTOR ASSY (SN)	SERVICEABLE	59.80	-
1	REFLECTOR ASSY (SN)	SERVICEABLE	59.80	-
1	PANEL SUB-ASSY,BODY (SN)	TO REPAIR SEE LABOUR	716.00	-
1	COVER,DECK TRIM,RR (SN)	SERVICEABLE	254.40	-
2	STRIKER ASSY (SN)	SERVICEABLE	54.40	-
2	RETAINER,ULTRASONIC (SN)	NECESSARY	40.60	40.60
1	RETAINER,ULTRASONIC (SN)	NECESSARY	15.40	15.40
1	RETAINER,ULTRASONIC (SN)	NECESSARY	15.40	15.40
2	SENSOR,ULTRASONIC (SN)	SERVICEABLE	785.60	-
2	SENSOR,ULTRASONIC (SN)	SERVICEABLE	785.60	-
1	PIPE ASSY,EXHAUST (SN)	BENT	1,463.60	1,463.60
1	SUNDRY (SN)	NECESSARY	100.00	50.00
1	SEALANT (SN)	NOT NECESSARY	100.00	-
			6,193.10	2,725.60
<b><u>LABOUR</u></b>				
	DRILL HOLE AND INSTALL REVERSE SENSOR.		180.00	180.00

Report Ref No. CC4/LPC19018672/R1ba3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	CHECK WIRING AND CONDUCT WATER TEST.		122.40	122.40
	REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR.	NOT NECESSARY	720.00	-
	TO RESET ECU AND REPROGRAMME.		180.00	180.00
	REPLACE REAR EXHAUST PIPE TO FAC REPAIR.		720.00	720.00
	REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY,BODY.		3,600.00	1,440.00
	RESPRAY ACC AFFECTED AREAS.		3,540.00	1,180.00
	TITANIUM COATING FOR (REAR SIDE BUMPER AREA) (ADDITIONAL).		150.00	150.00
			9,212.40	3,972.40
<b>GRAND TOTAL</b>			<b>15,405.50</b>	<b>6,698.00</b>

<b>RECOMMENDED COST OF REPAIRS</b>				<b>6,698.00</b>
------------------------------------	--	--	--	-----------------

Report Ref No. CC4/LPC19018672/R1ba3n2

**MOHAMMED RASUL BIN MOHD YUNUS**

Automotive Assessor

**HO LEONG CHUAN**

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLZ 8561R

INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLZ 8561R

RE-INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

