

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG19018677/T1DA3Q2**Date:** 14/07/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994314
Claimant
Vehicle No : SGC9018S **Insured Vehicle No :** SLZ7262K
Date of Loss: 15/10/2019 Nature of Claim: TP Claim No: 0208700637SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGC9018S**
Make & Model: NISSAN LATIO, 1.5 L T (A) Engine No: HR15082343
Reg. Date: 25/01/2006 (Man. Year: 2005) Chassis No: SC11017708
Colour: Beige Odometer: 181619 km
Engine Capacity: 1498 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	12,373.00	10,125.45	2,247.55	18.16	
Miscellaneous Items	0.00	0.00	0.00		
Labour	8,100.00	5,460.00	2,640.00	32.59	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	20,473.00	15,585.45	4,887.55	23.87	
Approved Total (Overridden) (S\$)		12,450.00			
	(S\$)	20,473.00	12,450.00	8,023.00	39.19
	+ GST 7.00/7.00% (S\$)	1,433.11	871.50	561.61	39.19
	Nett Amount (S\$)	21,906.11	13,321.50	8,584.61	39.19
	Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 21/10/2019
Date Inspected: 21/10/2019 Inspected At: Teamwork Garage Pte Ltd (HQ)
53 Ubi Ave 1 #01-24, Paya Ubi
Industrial Park
Singapore 408934
Estimated Period of Repair: 14.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	456.30 F	*456.30 FL
2	1		*REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
3	2		*REAR BUMPER SIDE RETAINER	Necessary	146.40 F	*146.40 FL
4	1		*REAR REVERSE SENSOR	Not Working	200.00 F	*200.00 FL
5	1		*REAR END PANEL	Bent	434.40 F	*434.40 FL
6	1		*REAR BUMPER SPONGE	Deformed	37.00 F	*37.00 FL
7	1		*REAR END PANEL TOP GARNISH	Deformed	92.40 F	*92.40 FL
8	1		*BOOTLID	Bent	787.50 F	*787.50 FL
9	1		*BOOTLID LOCK	Bent	109.00 F	*109.00 FL
10	1		*BOOTLID CHROME MOULDING	Deformed	280.60 F	*280.60 FL
11	1		*BOOTLID NISSAN EMBLEM	Necessary	50.70 F	*50.70 FL
12	1		*BOOTLID LATIO EMBLEM	Necessary	73.60 F	*73.60 FL
13	2		*REAR TAILLAMP	Cracked	518.80 F	*518.80 FL
14	1		*REAR FENDER LH	Buckled	627.00 F	*627.00 FL
15	1		*REAR FENDER RH	Repair	627.00 F	*- FL
16	1		*REAR WINDSCREEN MOULDING	Necessary	130.90 F	*130.90 FL
17	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 F	*50.00 FL
18	2		*REAR FENDER INNER TRIM LH & RH	Deformed	585.00 F	*585.00 FL
19	1		*SPARE TYRE PANEL	Repair	495.50 F	*- FL
20	1		*FRT NUMBER PLATE	Missing	45.00 F	*45.00 FL
21	1		*FRT BUMPER	Deformed	476.00 F	*476.00 FL
22	1		*FRT BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
23	1		*FRT BUMPER SIDE RETAINER	Necessary	64.00 F	*64.00 FL
24	1		*FRT BUMPER SPONGE	Deformed	207.20 F	*207.20 FL
25	1		*FRT BUMPER REINFORCEMENT	Bent	444.90 F	*444.90 FL
26	2		*FRT HEAD LAMPS	Cracked	772.60 F	*772.60 FL
27	1		*FRT LH FENDER	Bent	457.40 F	*457.40 FL
28	1		*FRT LH FENDER INNER SHIELD	Deformed	63.60 F	*63.60 FL
29	1		*FRT BONNET	Bent	860.00 F	*860.00 FL
30	1		*FRT BONNET LOCK	Bent	45.80 F	*45.80 FL
31	1		*FRT BONNET HINGE	Bent	102.00 F	*102.00 FL
32	1		*FRT SUPPORT PANEL	Bent	811.20 F	*811.20 FL
33	1		*AIR CON CONDENSER	Bent	675.90 F	*675.90 FL
34	1		*RADIATOR	Bent	596.30 F	*596.30 FL
35	1		*RADIATOR COWLING	Cracked	120.30 F	*120.30 FL
36	1		*RADIATOR FAN	Jammed	433.30 F	*433.30 FL
37	1		*AIRCON FAN MOTOR ASSY	Cracked	335.40 F	*335.40 FL
38	1		*RADIATOR COOLANT	Necessary	40.00 F	*40.00 FL
39	1		*RADIATOR COOLANT SPARE TANK	Deformed	60.00 F	*60.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	12,373.00	11,250.50
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	1,125.05
Total Parts (S\$)	12,373.00	10,125.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR & REPLACE REAR PORTION	New	2,000.00	1,500.00
2	TO SPRAY PAINTING REAR PORTION	New	1,800.00	1,400.00
3	WIRING	New	100.00	60.00
4	TUFF COAT	New	100.00	80.00
5	TO REPAIR & REPLACE FRONT PORTION	New	2,000.00	1,200.00
6	TO SPRAY PAINTING FRONT PORTION	New	1,800.00	1,000.00
7	TO REMOVE/REFIX REAR WINDSCREEN	New	150.00	120.00
8	TOP UP AIR CON GAS	New	150.00	100.00
Gross Labour Cost (S\$)			8,100.00	5,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >