5/12/2021 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/AIG19018710/EBA3Q2

Date:

12/05/2021

REFERENCE

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

0999994322

Claimant Vehicle

SG5810J

Insured Vehicle No:

SMJ8977Y

No: Date of Loss:

11/10/2019

Nature of Claim:

TP

Claim No:

134558 km

4263151411SG

Yes

DESCRIPTION & IDENTIFICATION OF VEHICLE

Rea No:

SG5810J

Make & Model:

MAN A95, 10.5 D (A) 06/06/2017 (Man. Year: 2016) Engine No: Chassis No: Odometer:

50344481284450 WMAA95ZZ7G7003457

Reg. Date: Colour:

Multi-colour

10518 cc

Engine Capacity: Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Handbrake (Serviceable):

Engine Modification: Yes

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: Front Left Side:

275/70 R22.5 Firenza 5 mm Rear Tyre Size: Rear Left Side:

275/70 R22.5 Firenza 5 mm

Front Right Side:

Firenza 5 mm

Rear Right Side:

Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		0.00	0.00	0.00	
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,241.00	854.00	387.00	31.18
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	1,241.00	854.00	387.00	31.18

350.00 + Loss of Use (1.0 x S\$350.00/day) (S\$)

(S\$) 1,204.00

602.00 Liable Amount (50.00%) (S\$) + Doc/Search Fee (S\$) 7.00

> **Nett Liability (S\$)** 609.00

Global Sum Settlement (S\$) 600.00

INSPECTION

Date Inspected:

Date of Assignment:

21/10/2019

21/10/2019 Inspected At:

SMRT Automotive Services Pte Ltd (Woodlands)

60 Woodlands Industrial Park E4

Singapore 757705

Estimated Period of Repair:

1.0 days

5/12/2021 Adjuster Report

Adjuster: **CHEN TSUE YEE** Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	<u>our Items</u>			
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	795.00	530.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	446.00	324.00
	Gross Labou	ır Cost (S\$)	1,241.00	854.00
	Report was unsubmitted during this p	rint-out.		

< END OF ESTIMATES >