

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

NZE1617065453

YEO AH HEE
BLK 589D MONTREAL DRIVE
#04-124
S 754589

TP111
Xiao Tony

Date : 01.11.2019
Vehicle No : SH 2807 J
Make/Model : TOYOTA AXIO
Accident date : 18.10.2019

No	DESCRIPTION	Qty	Amount (\$\$)
List Items			
1	Front bonnet Distorted	1	\$ 890.6 ✓
2	Front bonnet hinges @ \$62.20 Best	2	\$ 124.4 ✓
3	Front bonnet lock bracket New	1	\$ 151.5 X
4	Front bonnet lock New	1	\$ 143.2 X
5	Front support panel Repair	1	\$ 1075.4 X
6	Front bumper Distorted	1	\$ 535.4 ✓
7	Front bumper side holder @ \$57.10 LH Damaged	2	\$ 114.2 57.10
8	Front bumper lower side grille cut	1	\$ 78.8 ✓
9	Front bumper centre lower grille New	1	\$ 267.7 X
10	Front bumper clips (1 set) New	1	\$ 66 30
11	Front LH headlamp could	1	\$ 736.8 ✓
12	Front LH headlamp bulbs @ \$65.70 New	2	\$ 131.4 X
13	Front LH fender Distorted	1	\$ 790.4 ✓
14	Front LH fender inner shield Torn	1	\$ 176.9 ✓
15	Front LH fender inner shield clips (1 set) New	1	\$ 66 30
16	Front LH door Repair	1	\$ 1012.6 X
17	Front LH door glass outer moulding cut	1	\$ 134.3 ✓
18	Front LH door side mirror	1	\$
19	Front LH door side mirror lamp Damaged	1	\$ 1215.2 995
20	Front LH door side mirror housing	1	\$
21	Front LH door frame black sticker (1 set) New	1	\$ 70.8 X
22	Rear LH door Distorted	1	\$ 924.4 ✓
23	Rear LH door glass outer moulding New	1	\$ 134.3 X
24	Rear LH door frame black sticker (1 set) New	1	\$ 70.8 ✓
25	Front LH wheel cap cut	1	\$ 189 60 (SN)
26	Air cleaner assy could	1	\$ 923.9 565
			\$ 10024
S.N: 60 Less 25% Disc			\$ 2506
Total			\$ 7518

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

YEO AH HEE
BLK 589D MONTREAL DRIVE
#04-124
S 754589

Date :01.11.2019
Vehicle No :SH 2807 J
Make/Model :TOYOTA AXIO
Accident date :18.10.2019

No	DESCRIPTION	Qty	Amount (S\$)
Labour Cost			
1	Remove & reinstall aircon fill in gas		\$ 150 120
2	Remove & reinstall door glass fittings		\$ 150 80
3	To check wiring		\$ 80 30
4	Remove ,replace & repair consistent to the accident	2610	\$ 1500 1000
5	Respray painting		\$ 1400 1300
6	Tuff kote		\$ 100 80
Total			\$ 3380
Grand Total			\$ 10898

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 7252.42

4/s: 5.8K.

07 Days

581c