

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19018797/KEA3Q2

Date: 13/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800010591
Claimant		
Vehicle No : SHF604G	Insured Vehicle No :	SLV7990M
Date of Loss: 19/10/2019	Nature of Claim: TP	Claim No: 6910141479SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHF604G		
Make & Model:	RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C001696
Reg. Date:	27/06/2014 (Man. Year: 2014)	Chassis No:	VF1ABL15AUC278443
Colour:	Metallic White/Red	Odometer:	822513 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 9 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,887.60	2,652.71	9,234.89	77.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,140.00	1,780.00	13,360.00	88.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,027.60	4,432.71	22,594.89	83.60
Approved Total (Overridden) (S\$)		3,550.00		
(S\$)	27,027.60	3,550.00	23,477.60	86.87
+ GST 7.00/7.00% (S\$)	1,891.93	248.50	1,643.43	86.87
Nett Amount (S\$)	28,919.53	3,798.50	25,121.03	86.87
+ Loss of Use (7.0 x S\$50.00/day) (S\$)		350.00		
+ Car Rental (7.0 x S\$95.04/day) (S\$)		665.28		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		4,821.27		

INSPECTION

Date of Assignment:	22/10/2019	
Date Inspected:	22/10/2019	Inspected At: Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR PANEL REAR RH	Bent	758.70 FL	*758.70 FL
2	1		*DOOR LOCK REAR RH	Repair	467.30 FL	*- FL
3	1		*DOOR BLIND REAR RH	Serviceable	506.90 FL	*- FL
4	1		*DOOR WEATHERSTRP REAR RH	Serviceable	311.60 FL	*- FL
5	1		*DOOR SEAL REAR RH	Serviceable	119.80 FL	*- FL
6	1		*ROCKER PANEL INNER GARNISH RH	Serviceable	466.51 FL	*- FL
7	1		*ROCKER PANEL INNER RH	Repair	1,024.79 FL	*- FL
8	1		*ROCKER PANEL OUTER RH	Repair	1,184.99 FL	*- FL
9	1		*ROCKER PANEL CENTER RH	Repair	990.25 FL	*- FL
10	1		*FENDER PANEL REAR RH	Bent	1,933.20 FL	*1,933.20 FL
11	1		*FENDER PANEL INNER TRIM REAR RH	Serviceable	671.45 FL	*- FL
12	1		*WHEELARCH REAR RH	Serviceable	275.40 FL	*- FL
13	1		*BUMPER COVER REAR	Serviceable	561.70 FL	*- FL
14	1		*BUMPER LOWER REAR	Serviceable	411.90 FL	*- FL
15	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*- FL
16	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	*- FL
17	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	*- FL
18	1		*BUMPER REFLECTOR RH	Serviceable	16.60 FL	*- FL
19	1		*BUMPER BEAM REAR	Repair	547.80 FL	*- FL
20	1		*BUMPER BEAM BRACKET RH REAR	Serviceable	100.90 FL	*- FL
21	1		*TAILLAMP RH	Serviceable	313.10 FL	*- FL
22	1		*REAR DOOR STICKER 6555-3333	Necessary	80.00 FS	*60.00 FS
23	1		*FENDER INNER TRIM CLIP RH	Not Necessary	28.00 FS	*- FS
24	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*- FS
25	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS
26	2		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
27	1		*WINDSCREEN MOULDING	Necessary	100.00 FS	*100.00 FS
28	1		*REAR WINDSCREEN INNER SPONGE SEAL	Necessary	100.00 FS	*30.00 FS
29	1		*REAR RIGHT TYRE	Serviceable	300.00 FS	*- FS
30	1		*REAR RIGHT TYRE RIM	Serviceable	380.00 FS	*- FS
31	1		*REAR WHEEL RIM COVER	Serviceable	50.00 FS	*- FS
32	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
33	1		*SET REAR BUMPER CLIP	Not Necessary	66.00 FS	*- FS
34	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	33.00 FS	*- FS
35	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
36	1		*SET BUMPER RETAINER CLIP RH RR	Not Necessary	20.00 FS	*- FS
37	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
38	1		*SET BUMPER LOWER REAR CLIP	Not Necessary	66.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	12,977.89	2,921.90
- List Item Discount on L Items 10.00/10.00% (\$)	1,090.29	269.19
Total Parts (\$)	11,887.60	2,652.71

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	6,000.00	700.00
2	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH TO FACILITATE REPAIR	New	380.00	0.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	100.00
4	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
5	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	120.00
6	TO TRANSFER OF REAR DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	380.00	60.00
7	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
8	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
9	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	60.00
10	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
12	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
13	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	660.00
14	TOWING FEES	New	170.00	0.00
Gross Labour Cost (\$\$)			15,140.00	1,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >