

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119018799/R1YD3E2
Date: 26/05/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSN30814019011	
Claimant Vehicle No : FBM2117S	Insured Vehicle No : SKR9650P	
Date of Loss: 17/10/2019	Nature of Claim: TP	Claim No: SNM19D204955C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBM2117S		
Make & Model:	HONDA SILVERWING, 398cc GT 400	Engine No:	NF01E1401926
Reg. Date:	16/12/2014 (Man. Year: 2014)	Chassis No:	NF031001929
Colour:	Purple	Odometer:	74249 km
Engine Capacity:	398 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/80-14	Rear Tyre Size:	150/70-15
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	870.00	870.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	750.00	500.00	250.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	1,620.00	1,370.00	250.00	15.43

INSPECTION

Date of Assignment:	22/05/2020	
Date Inspected:	25/10/2019 Inspected At:	Hkl Lim Team Motorsport (HQ) BLK 1008 #01-24 BUKIT MERAH LANE 3 Singapore 159722
Estimated Period of Repair:	2.0 days	

Adjuster: MOHD RASUL

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 May 2020)	
Parts:	N/A	HONDA SILVERWING 398cc GT 400 (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBM2117S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEAD COWLING	Cracked	420.00 FS	*420.00 FS
2	1		*SIDE PANEL RH	Scratched	300.00 FS	*300.00 FS
3	1		*FRONT SIGNAL RH	Cracked	150.00 FS	*150.00 FS
Total Parts (S\$)						870.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTING	New	400.00	300.00
2	LABOUR	New	350.00	200.00
Gross Labour Cost (\$\$)			750.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >