

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19018804/UPA3Q2

Date: 16/04/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : JMJ6844	Insured Vehicle No :	SHA7645T
Date of Loss: 14/10/2019	Nature of Claim: TP	Claim No: MCT19100303

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	JMJ6844		
Make & Model:	HONDA AFX110S, 109cc	Engine No:	JC46E5007750
Reg. Date:	02/08/2010 (Man. Year: 2010)	Chassis No:	PMKJC4690AB007787
Colour:	Red/Silver	Odometer:	43217 km
Engine Capacity:	109 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70-90-17	Rear Tyre Size:	70-90-17
Front Left Side:	Deestone 5 mm	Rear Left Side:	Deestone 5 mm
Front Right Side:	Deestone 0 mm	Rear Right Side:	Deestone 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,109.50	2,190.70	1,918.80	46.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	510.00	285.00	225.00	44.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,619.50	2,475.70	2,143.80	46.41
Approved Total (Overridden) (S\$)		1,300.00		
Nett Amount (S\$)	4,619.50	1,300.00	3,319.50	71.86
+ Loss of Use (4.0 x S\$25.00/day) (S\$)		100.00		
Nett Liability (S\$)		1,400.00		

INSPECTION

Date of Assignment:	22/10/2019	
Date Inspected:	23/10/2019 Inspected At:	Erofia Motor Trading Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-62 Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Mar 2020)	
Parts:	N/A	HONDA AFX110S 109cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JMJ6844)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FORK INNER TUBES	Bent / Twisted	240.00 FL	*240.00 FL
2	2		*FORK INNER TUBES	Bent / Twisted	250.00 FL	*250.00 FL
3	1		*FORK UNDER BRACKET	Bent	185.00 FL	*185.00 FL
4	1		*FRONT SPORT RIM	Bent / Warped	320.00 FL	*320.00 FL
5	1		*FRONT RIM SHAFT	Bent	42.00 FL	*42.00 FL
6	1		*FRONT RIM BEARING	Necessary	38.00 FL	*38.00 FL
7	1		*FRONT BRAKE DISC	Bent	155.00 FL	*155.00 FL
8	1		*HEADLAMP	Cracked	95.00 FL	*95.00 FL
9	1		*SIDE MIRROR	Cracked	48.00 FL	*48.00 FL
10	1		*FRONT SIGNAL	Not fitted	50.00 FL	*- FL
11	1		*HANDLE -BAR	Bent	8.00 FL	*8.00 FL
12	1		*HANDLE -BAR END	Scratched	35.00 FL	*35.00 FL
13	1		*BRAKE LEVER	Scratched	32.00 FL	*32.00 FL
14	1		*FRONT FOOTREST BRACKET	Bent	55.00 FL	*55.00 FL
15	1		*FRONT FOOTREST RUBBER -R/H	Torn	28.00 FL	*28.00 FL
16	1		*BRAKE PEDAL	Bent	42.00 FL	*42.00 FL
17	1		*O/S ENGINE COVER	Not Necessary	145.00 FL	*- FL
18	2		*REAR FOOTRESTS	Not fitted	76.00 FL	*- FL
19	2		*REAR FOOTREST BRACKETS	Not Necessary	130.00 FL	*- FL
20	1		*EXHAUST ASSY	Repair	425.00 FL	*- FL
21	1		*EXHAUST PROTECTOR	Bent	65.00 FL	*65.00 FL
22	1		*REAR TAILLAMP	Not Necessary	88.00 FL	*- FL
23	2		*REAR ABSORBERS	Not Necessary	390.00 FL	*- FL
24	1		*SWING -ARM	Not Necessary	385.00 FL	*- FL
25	1		*REAR FENDER	Not Necessary	68.00 FL	*- FL
26	1		*BASKET	Not Necessary	35.00 FL	*- FL
27	1		*SET FAIRING ASSY	Cracked	485.00 FL	*485.00 FL
28	1		*SET NUMBER PLATE	Necessary	28.00 FS	*15.00 FS
29	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
30	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
31	1		*SET STEERING CONE BEARING	Necessary	85.00 FS	*85.00 FS
32	1		*ENGINE OIL	Not Necessary	15.00 FS	*- FS
33	1		*ENGINE COVER GASKET	Not Necessary	22.00 FS	*- FS
34	1		*REAR BOX	Cut	250.00 FS	*180.00 FS
35	1		*REAR BOX BRACKET	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,501.00	2,403.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	391.50	212.30
Total Parts (\$\$)	4,109.50	2,190.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE TOWING SERVICE	New	50.00	35.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	380.00	250.00
Gross Labour Cost (\$\$)			510.00	285.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >