

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19018815/DPA3Q2

Date: 22/09/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SHB4274U	Insured Vehicle No :	SHA7995H
Date of Loss: 22/10/2019	Nature of Claim: TP	Claim No: MCT19100537

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB4274U		
Make & Model:	HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A)	Engine No:	D4FDFU548049
Reg. Date:	26/03/2015 (Man. Year: 2014)	Chassis No:	KMHLB41UMFU065970
Colour:	Blue	Odometer:	594277 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	DURATURN 5 mm	Rear Left Side:	DURATURN 5 mm
Front Right Side:	DURATURN 5 mm	Rear Right Side:	DURATURN 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,403.30	17,896.24	3,507.06	16.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,660.00	2,440.00	2,220.00	47.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,063.30	20,336.24	5,727.06	21.97
Approved Total (Overridden) (S\$)		16,000.00		
(S\$)	26,063.30	16,000.00	10,063.30	38.61
+ GST 7.00/7.00% (S\$)	1,824.43	1,120.00	704.43	38.61
Nett Amount (S\$)	27,887.73	17,120.00	10,767.73	38.61
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	23/10/2019	
Date Inspected:	23/10/2019 Inspected At:	Chunni Motor Work Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint Singapore 568047
Estimated Period of Repair:	9.0 days	

Adjuster: BRYAN TANI**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Aug 2020)
Parts:	143	HYUNDAI I40 1.7 L CRDI AT ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB4274U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER SHIELD (RH)	Not Necessary	174.90 FL	*- FL
2	1		*FRONT WHEEL RIM (RH)	Bent	325.30 FL	*325.30 FL
3	1		*FRONT WHEEL HUB CAP (RH)	Not Necessary	107.10 FL	*- FL
4	1		*FRONT WHEEL BEARING	Damaged	540.50 FL	*540.50 FL
5	1		*FRONT SHOCK ABSORBER (ASSY) (RH)	Distorted	342.20 FL	*342.20 FL
6	1		*FRONT SHOCK ABSORBER MOUNTING (RH)	Not Necessary	108.80 FL	*- FL
7	1		*FRONT DRIVE SHAFT (RH)	Damaged	1,030.80 FL	*1,030.80 FL
8	1		*RACK & PINION ASSY	Damaged	969.60 FL	*969.60 FL
9	1		*STG TIE END	Distorted	62.60 FL	*62.60 FL
10	1		*STABILIZER BAR	Not Necessary	252.30 FL	*- FL
11	1		*STABILIZER BAR BUSH (RH)	Not Necessary	16.40 FL	*- FL
12	1		*STABILIZER BAR LINK	Not Necessary	61.10 FL	*- FL
13	1		*STABILIZER BRACKET	Not Necessary	24.00 FL	*- FL
14	1		*FRONT SUSPENSION LOWER ARM (RH)	Distorted	529.30 FL	*529.30 FL
15	1		*KNUCKLE ARM (RH)	Distorted	552.00 FL	*552.00 FL
16	1		*ENGINE UNDER COVER	Repeated	334.60 FL	*- FL
17	1		*ENGINE CROSSMEMBER	Distorted	2,094.40 FL	*2,094.40 FL
18	1		*FRONT TYRE (RH)	Not Necessary	216.00 FS	*- FS
19	1		*BOOT LID LAMP (LH)	Cracked	565.60 FL	*565.60 FL
20	1		*REAR BUMPER	Cut / Distorted	553.00 FL	*553.00 FL
21	1		*REAR BUMPER REINFORCEMENT	Not Necessary	428.40 FL	*- FL
22	1		*REAR BUMPER REINFORCEMENT BRACKET (LH)	Not Necessary	80.30 FL	*- FL
23	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
24	1		*REAR BUMPER BRACKET N/S	Broken	35.60 FL	*35.60 FL
25	1		*REAR BUMPER SPONGE	Not Necessary	118.40 FL	*- FL
26	1		*REAR BUMPER UNDER COVER	Mtg Broken	228.00 FL	*228.00 FL
27	1		*TAIL LAMP(LH)	Cracked / Broken	697.80 FL	*697.80 FL
28	1		*TAIL LAMP QUARTER PANEL (LH)	Dented	226.50 FL	*226.50 FL
29	1		*REAR FENDER WITH HOUSING (LH)	Dented	4,736.80 FL	*4,736.80 FL
30	1		*REAR FENDER INNER LINING (LH)	Not Necessary	169.30 FL	*- FL
31	1		*REAR FENDER AIR-DUCT	Not Necessary	51.60 FL	*- FL
32	1		*REAR FENDER TRIM BOARD (LH)	Torn / Bent	188.75 FL	*188.75 FL
33	1		*REAR WINDSCREEN MOULDING	Necessary	28.30 FL	*28.30 FL
34	1		*FUEL TANK SUB HOSE	Not Necessary	78.20 FL	*- FL
35	1		*FUEL TANK UPPER NECK	Not Necessary	221.10 FL	*- FL
36	1		*FUEL LID OUTER GARNISH	Not Necessary	59.40 FL	*- FL
37	1		*REAR DOOR (LH)	Dented	2,201.10 FL	*2,201.10 FL
38	1		*REAR TYRE RIM (LH)	Distorted	325.30 FL	*325.30 FL
39	1		*REAR WHEEL HUB -CAP (LH)	Bent	107.10 FL	*107.10 FL
40	1		*REAR WHEELBEARING ING & HUB	Damaged	362.00 FL	*362.00 FL
41	1		*REAR TRAILING ARM (LH)	Distorted	192.00 FL	*192.00 FL
42	1		*REAR ASSIST (LH)	Distorted	145.70 FL	*145.70 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR SHOCK ABSORBER (LH)	Distorted	276.30 FL	*276.30 FL
44	1		*REAR SHOCK ABSORBER MOUNTING (LH)	Not Necessary	81.30 FL	*- FL
45	1		*REAR CROSSMEMBER	Not Necessary	1,021.50 FL	*- FL
46	1		*STABILIZER BAR	Not Necessary	199.60 FL	*- FL
47	1		*STABILIZER LINK	Not Necessary	85.90 FL	*- FL
48	1		*REAR UPPER ARM (LH)	Distorted	335.75 FL	*335.75 FL
49	1		*REAR LOWER ARM (LH)	Distorted	353.80 FL	*353.80 FL
50	1		*REAR KNUCKLE ARM (LH)	Distorted	545.60 FL	*545.60 FL
51	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	135.70 FS	*- FS
52	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
53	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
54	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (LH)	Necessary	80.00 FS	*80.00 FS
55	1		*REAR TYRE (LH)	Serviceable	216.00 FS	*- FS
56	1		*FRONT BUMPER COVER	Dented	544.50 FL	*544.50 FL
57	1		*FRONT BUMPER REINFORCEMENT	Bent	402.10 FL	*402.10 FL
58	1		*HEADLAMP SUPPORT PANEL ASSY	Bent / Broken	907.40 FL	*907.40 FL
59	1		*HEADLAMP (RH)	Mtg Cracked	1,388.00 FL	*1,388.00 FL
60	1		*ENGINE UNDER COVER	Cracked	334.60 FL	*334.60 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 26,568.20 22,326.30
- List Item Discount on L Items 20.00/20.00% (S\$) 5,164.90 4,430.06
Total Parts (S\$) 21,403.30 17,896.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,200.00	800.00
2	SPRAY PAINTING CHARGE	New	1,000.00	800.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	50.00	0.00
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
8	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
9	REMOVE/REFIX FUEL TANK	New	150.00	0.00
10	TRANSFER OF DOOR	New	120.00	60.00
11	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	200.00	150.00
12	REMOVE/REFIX UNDERCARRIAGE (RR)	New	200.00	150.00
13	FOUR WHEEL ALIGNMENT	New	120.00	60.00
14	RE-SET FRT & REAR ABS SYSTEM }	New	400.00	150.00
15	RE-SET REAR POWER WINDOW SYSTEM }	New	200.00	0.00
16	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE }	New	480.00	0.00
Gross Labour Cost (\$\$)			4,660.00	2,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >