

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG19018819/ASF3E2

**Date:** 05/08/2020

### REFERENCE

Insured/Claimant:	SERENE CHING LI-LING	Policy No:	1800057221
Date of Loss:	18/10/2019	Nature of Claim:	OD
		Claim No:	7569270105SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA575Z		
Make & Model:	AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A)	Engine No:	DAX032647
Reg. Date:	21/05/2018 (Man. Year: 2018)	Chassis No:	WAUZZZFV2J2136244
Colour:	Blue	Odometer:	18689 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$170,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	15,354.00	1,985.44	13,368.56	87.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,472.00	3,272.00	4,200.00	56.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>22,826.00</b>	<b>5,257.44</b>	<b>17,568.56</b>	<b>76.97</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	1,597.82	368.02	1,229.80	76.97
<b>Nett Amount (\$\$)</b>	<b>24,423.82</b>	<b>5,625.46</b>	<b>18,798.36</b>	<b>76.97</b>

### INSPECTION

Date of Assignment:	23/10/2019		
Date Inspected:	23/10/2019	Inspected At:	Premium Automobiles Pte Ltd (UBI)
			55 Ubi Road 1
			Singapore 408699
Estimated Period of Repair:	4.0 days		

**Adjuster:** ADRIAN LING

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,364.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	244.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP - RH	Not Necessary	34.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - RH	Not Necessary	101.00 FS	*- FS
5	1		*FRONT BUMPER SPOILER	Not Necessary	685.00 FS	*- FS
6	1		*FRONT BUMPER UNDERRUN BAR	Not Necessary	431.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	519.00 FS	*- FS
8	1		*FRONT BUMPER END CAP - RH	Not Necessary	83.00 FS	*- FS
9	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	34.00 FS	*- FS
10	1		*FRONT FENDER - RH	Dented	1,301.00 FS	*1,040.80 FS
11	1		*FRONT FENDER BRACE - RH	Not Necessary	206.00 FS	*- FS
12	1		*FRONT BUMPER BRACKET - RH	Not Necessary	16.00 FS	*- FS
13	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	246.00 FS	*- FS
14	1		*WHEEL HOUSING LINER ATTACHMENT PARTS - FRONT	Not Necessary	35.00 FS	*- FS
15	1		*WHEEL SPOILER - RH	Not Necessary	139.00 FS	*- FS
16	2		*FRONT WHEEL COVER - LH / RH	Necessary	1,154.00 FS	*922.40 FS
17	1		*HEADLIGHT MOUNTING - RH	Not Necessary	107.00 FS	*- FS
18	1		*LED HEADLIGHT - RH	Not Necessary	7,227.00 FS	*- FS
19	1		*LIFT CYLINDER - RH	Not Necessary	128.00 FS	*- FS
20	1		*SUNDRIES	Necessary	300.00 FS	*22.24 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)** **15,354.00** **1,985.44**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	1,000.00
3	TO RESPRAY FRONT BUMPER, FRONT LOWER SPOILER, RHS FRONT FENDER AND BOTH FRONT WHEEL ARCH TRIMS	New	4,000.00	1,600.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (S\$)</b>			<b>7,472.00</b>	<b>3,272.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >