

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG19018828/EEA3Q2
Date: 07/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994368
Claimant Vehicle No :	SLF2984Z	Insured Vehicle No :	SLX3678G
Date of Loss:	12/10/2019	Nature of Claim:	TP
		Claim No:	0337239383SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF2984Z		
Make & Model:	TOYOTA SIENTA, 1.5 X (A)	Engine No:	2NR8640227
Reg. Date:	22/08/2016 (Man. Year: 2016)	Chassis No:	NSP1707040464
Colour:	Silver	Odometer:	228534 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Firenza 5 mm	Rear Left Side:	Firenza 5 mm
Front Right Side:	Firenza 5 mm	Rear Right Side:	Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,675.26	1,056.40	2,618.86	71.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,920.00	970.00	950.00	49.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,595.26	2,026.40	3,568.86	63.78
Approved Total (Overridden) (S\$)		1,600.00		

(S\$)	5,595.26	1,600.00	3,995.26	71.40
+ GST 7.00/7.00% (S\$)	391.67	112.00	279.67	71.40
Nett Amount (S\$)	5,986.93	1,712.00	4,274.93	71.40
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 23/10/2019

Date Inspected: 23/10/2019

Estimated Period of Repair: 3.0 days

Inspected At:

Lcrf Pte Ltd (HQ)
 60 JALAN LAM HUAT, #04-01 SINGAPORE 737869
 Singapore 737869

Adjuster: CHEN TSUE YEE**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,879.00 FL	*1,086.00 FL
2	1		*REAR TAILGATE TOYOTA LOGO	Necessary	60.00 FL	*60.00 FL
3	1		*REAR BUMPER	Repair	1,257.83 FL	*- FL
4	1		*REAR BUMPER RH RETAINER	Broken	104.40 FL	*104.40 FL
5	1		*REAR BUMPER RH SUPPORT	Not Necessary	88.05 FL	*- FL
6	1		*REAR BUMPER RH EXTENSION	Not Necessary	216.00 FL	*- FL
7	1		*REAR BUMPER PAD	Cut	64.80 FL	*64.80 FL
8	1		*R/R TAILLAMP	Not Necessary	550.00 FL	*- FL
9	1		*REAR BUMPER RH REFLECTOR	Not Necessary	93.60 FL	*- FL
10	1		*SET BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
11	1		*SET REVERSE SENSOR	Not Necessary	260.00 FS	*- FS
12	1		*WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,753.68	1,385.20
- List Item Discount on L Items 25.00/25.00% (S\$)	1,078.42	328.80
Total Parts (S\$)	3,675.26	1,056.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND INSTALL REAR TAILGATE GLASS	New	120.00	120.00
2	TRANSFER TAILGATE MECHANISM	New	100.00	50.00
3	TO LABOUR CHARGE FOR REMOVING REAR TAILGATE ,REAR BUMPER ,OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS ,ALSO STRAIGHTEN R/R FENDER	New	900.00	400.00
4	TO RESPRAY REAR TAILGATE ,REAR END PANEL,SPARE TYRE PANEL AND REAR BUMPER	New	800.00	400.00
Gross Labour Cost (S\$)			1,920.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >