

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWER

SINGAPORE 079909

INV No. AC2003202

INV Date 16/04/2020

Reference CC6/CTI19018838/Kha3n2

Code CT



PROFESSIONAL SERVICE FEE

Vehicle No. SKK 9902A

Insured Veh. GBH 9669X

Claim No. SNM19D204959

Policy No. DMCVSN303377190

Accident Date 18/10/2019

Inspection Date 29/10/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

CHINA TAIPING INSURANCE (S) PTE LTD Ref : CC6/CTI19018838/Kha3n2 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909 Code : CTI 1.	Affiliated to Federation Internationale Des Experts En Automobile									
Code : CTI										
Insured Veh. GBH 9669X Veh. Inspected SKK 9902A										
Policy No. DMCVSN303377190 Coverage (\$) 0.00	1. Policy Particulars :- THIRD PARTY CLAIM									
Claim No. SNM19D204959 Excess (\$) 0.00 Assign From Assign Date 29/10/2019 Vehicle Particulars & Condition Make & Model MERCEDES R300 (A) c.c 2996 Engine No. HIDDEN Year of Reg. 2013 Chassis No. WDC2511542A161876 Colour METALLIC BLACK Odometer 76469 Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD										
Assign From Assign Date 29/10/2019 2. Vehicle Particulars & Condition Make & Model MERCEDES R300 (A) c.c 2996 Engine No. HIDDEN Year of Reg. 2013 Chassis No. WDC2511542A161876 Colour METALLIC BLACK Odometer 76469 Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD										
2. Vehicle Particulars & Condition Make & Model MERCEDES R300 (A) c.c 2996 Engine No. HIDDEN Year of Reg. 2013 Chassis No. WDC2511542A161876 Colour METALLIC BLACK Odometer 76469 Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD	0.00									
Make & ModelMERCEDES R300 (A)c.c2996Engine No.HIDDENYear of Reg.2013Chassis No.WDC2511542A161876ColourMETALLIC BLACKOdometer76469SteeringIN ORDERBrakesIN ORDERModificationSPORTS RIMGeneralGOOD	29/10/2019									
Engine No. HIDDEN Year of Reg. 2013 Chassis No. WDC2511542A161876 Colour METALLIC BLACK Odometer 76469 Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD										
Chassis No. WDC2511542A161876 Colour METALLIC BLACK Odometer 76469 Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD	DEDES R300 (A) c.c 2996									
Odometer 76469 Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD										
Brakes IN ORDER Modification SPORTS RIM General GOOD										
General GOOD										
Joseph Market Ma										
3. Conditions of Tyres										
Size Make Balance										
R/H Front Tyre 265/45 ZR20 CONTINENTAL 6 mm										
L/H Front Tyre 265/45 ZR20 CONTINENTAL 6 mm	<u> </u>									
R/H Rear Tyre 265/45 ZR20 CONTINENTAL 6 mm										
L/H Rear Tyre 265/45 ZR20 CONTINENTAL 6 mm										
4. Description of Damages										
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.										
DAMAGES SEE DETAILS.										
5. General Information										
Accident Date 18/10/2019 Inspection Date 29/10/2019										
Survey held at LIM TAN MOTOR PTE LTD										
BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721										
5a. Remarks										
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.										
5b. Estimate Days of Repair										
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days										



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKK 9902A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (N)	BUCKLED	2,000.00	2,000.00
1	REAR BUMPER REINFORCEMENT (N)	TO REPAIR SEE LABOUR	980.00	-
1	REAR BUMPER LH REFLECTOR (N)	MISSING	80.00	80.00
2	REAR BUMPER SENSOR @\$150.00 (N)	SHORTED (1 PC ONLY)	300.00	150.00
1	REAR BUMPER TOP CHROME (N)	CRACKED	480.00	480.00
1	TAILGATE STAR (N)	NECESSARY	60.00	60.00
1	TAILGATE R300 EMBLEM (N)	NECESSARY	53.00	53.00
	LESS 10% DISCOUNT		-395.30	-282.30
			3,557.70	2,540.70
	<u>LABOUR</u>			
	TO PUTTY AND SPRAY PAINT.		500.00	450.00
	TO CHECK REAR WIRING & REPLACE PARKING SENSOR .		80.00	60.00
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT .		400.00	350.00
			980.00	860.00
	GRAND TOTAL		4,537.70	3,400.70

RECOMMENDED COST OF LUMP SUM REPAIRS		2,700.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC6/CTI19018838/Kha3n2

KONG SENG CHEONG

Licensed Appraiser