

22/03/2018

ARS. REC. BY:

REF: C8/FCI/19018874/Dsd3ⁿ²

Special Instruction:

Assigned: Bryan

ASSIGNMENT (Office)

CWS

Sithum

of

FCI

Date/Time: 23/10/2019 @ 4.24pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHB 41832

Insured:

SHC 7581H

at Workshop m/s

chunni Motor

Tel:

65425119

of

10 mk Autopoint #01-05/06

Policy No:

Claim No:

D19006754 MFSH

Sum Insured:

Excess:

D.O.A. 22/10/2019

Make of Veh:
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:17am @ 24/10/19

Person Contacted:

Lynn

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate
	SHB 41832-CC4 / III 17022088 / 7/10/342	2A: 15/11/2017
	SHC 7581H-X	
04/11/19	@ 16:23 pm revised PA to Sithum via email.	

2023 DEC 19

6415

ASSIGNMENT

COB Nov 2023

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12 days

Res: Yes or No

Loss Sum:

20 %

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No

SHB4183Z

Yr Regn

2015 / Nov

Type: M.Car / M.Cycle / Bus / Van / Lorry

(Taxi) Prime Mover /

Truck / Trailer or

Make:

Hyundai I40

c.c. 1685

Colour

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

529494

T/Radio: Insured / Std / NI / NA

Eng/No:

D4FDFU561677

C/No:

KMHCB41UMGU080373

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/60 R 16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Flanbak

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

22/10/2019

D.O.A.

24/10/2019

Survey held at

Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

26/11/19

First Capital SHC 7581H

Insured with Lymm 4/5 (8000/-) with 12 days of repair

(\$ 21,485.04 Red - 54%)

RECEIVED 2019

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Form:

Amount Paid / H.R. Fee:

\$ 18,000/- 45

Days Of Repair:

12

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Week end (\$

Survey Fee:

Transportation:

S + RS, SI

Photos:

Other:

26/11/19

TOTAL

29x15 = 435

170 + 435

50

50 + 50

194

580

949



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19006759MFSH

Date: 04 November 2019

Our Ref: CS/FCI19018874/Dsd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHB 4183Z .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 24/10/2019 at the premises of M/s Chunni Motor Works Pte Ltd and have the following to report:-


Workshop Estimate Amount	: S\$ 39,485.04 .
Revised Estimate Amount	: S\$ 21,039.92 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the front portion.

Comments/ Present Status:

Damages Consistent.
Repair days: 10 days



Yours faithfully

Bryan Ang
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	23-10-2019	Our Ref No. D19006759MFSH
Accident Date	22-10-2019	Claim Type. Third Party
Insured Vehicle	SHC7581H	Third Party Vehicle. SHB4183Z
Survey Location	BLK 10 ANG MO KIO INDUSTRIAL PARK 2AAMK AUTOPOINT #03-19	
Contact Person.	LYNN OR IRENE - 65421726	
Contact No.	65427162/ 0	Fax No. 65426039
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Nivitha (LKK Auto)

From: Aini Binte Md Min <Aini@msfirstcapital.com.sg>
Sent: Wednesday, 23 October 2019 4:24 PM
To: 'assignments@lkkauto.com'
Cc: Sithara
Subject: NEW ASSIGNMENT (Accident involving veh no: SHC7581H & SHB4183Z on 22.10.19)
Attachments: FW: Accident involving veh no: SHB 4183Z & SHC 7581H on 22.10.19 (267 KB)

Dear Nivitha

O/REF: NC-19010614 (SHC7581H)

Refer to our telephone conversation of just.

New assignment for your handling.

Thanks & Regards

Aini
Motor Claims Department

MS First Capital Insurance Ltd | 36 Robinson Road, City House, #16-01 Singapore 068877 | TEL: 6507 3848
Fax: 6507 3849 | Company Reg. No. 195000106C

A Member of **MS&AD** INSURANCE GROUP

Personal Data Protection Act 2012 ("PDPA"):
Under the PDPA, there are various requirements that regulate the processing of your personal data.
Please refer to www.msfirstcapital.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.
If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.
If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Chunni Motor <chunnimotor@gmail.com>
Sent: Wednesday, October 23, 2019 3:38 PM
To: Aini Binte Md Min <Aini@msfirstcapital.com.sg>
Cc: Sithara <Sithara@msfirstcapital.com.sg>
Subject: Re: FW: Accident involving veh no: SHB 4183Z & SHC 7581H on 22.10.19

Dear Sir,

We appoint LKK Auto Consultants P/L

Thank you

Regards,
Chunni Motor Work P/L

On Wed, Oct 23, 2019 at 12:09 PM Aini Binte Md Min <Aini@msfirstcapital.com.sg> wrote:

Dear Sirs

We refer to your survey request dated 23.10.19.

Please find below our list of surveyors for your reference. Kindly select from our list below and inform us of your choice within the next 2 days.

1. LKK Auto Consultants Pte Ltd
2. Vicom Ltd

Once you inform us of your choice, the surveyor will be appointed within 2 working days of your email.

If you do not agree to any of the surveyors above, you may proceed to appoint your own surveyor. In this instance, we will also appoint a surveyor from our list above to conduct the PRI. Upon completion of repairs, please contact our appointed surveyor to conduct a physical re-inspection of the vehicle.

Thanks & Regards

Aini

Motor Claims Department

MS First Capital Insurance Ltd | 36 Robinson Road, City House, #16-01 Singapore 068877 | TEL: 6507 3848

Fax: 6507 3849 | Company Reg. No. 195000106C

A Member of **MS&AD** INSURANCE GROUP

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data.

Please refer to www.msfirstcapital.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Rosliza Bte AB Rahman <Rosliza@msfirstcapital.com.sg>
Sent: Wednesday, October 23, 2019 12:02 PM
To: Aini Binte Md Min <Aini@msfirstcapital.com.sg>
Subject: FW: Accident involving veh no: SHB 4183Z & SHC 7581H on 22.10.19

PRI NC-19010614 (CCPL)

From: Chunni Motor <chunnimotor@gmail.com>
Sent: Wednesday, October 23, 2019 10:50 AM
To: Motor_Claims <Motor_Claims@msfirstcapital.com.sg>
Subject: Fwd: Accident involving veh no: SHB 4183Z & SHC 7581H on 22.10.19

----- Forwarded message -----

From: Chunni Motor <chunnimotor@gmail.com>
Date: Tue, Oct 22, 2019 at 4:39 PM
Subject: Accident involving veh no: SHB 4183Z & SHC 7581H on 22.10.19
To: motor_claims <motor_claims@first-insurance.com.sg>

Dear Sir/Mdm,

We refer the above mentioned matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

Kindly survey at AMK Autopoint, Soon Hock Motor, #01-05/06.

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 6542 7162

Thank you for your kind assistance.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Monday, 4 November 2019 4:23 pm
To: 'Sithara'; Admin-D (LKKAuto); 'CWS Motor Claims'
Cc: SUR; assignments
Subject: RE: SURVEY ASSESSMENT - D19006759MFSH/1
Attachments: PRELI ADVISE - SHB 4183Z.pdf

Dear Sithara,

Enclosed preliminary revised of vehicle SHB 4183Z.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Thursday, 24 October 2019 2:34 pm
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19006759MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Thursday, 24 October 2019 2:27 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19006759MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHB 4183Z

DATE : 22.10.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

FCI

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet <i>Dental</i>			\$ 2,265.90
	Bonnet Hinge (LH/RH) <i>bt</i>	\$	41.00	\$ 82.00
	Bonnet Lock <i>bt</i>			\$ 36.90
	Bonnet Absorber <i>new</i>	\$	58.10	\$ 116.20
	Bonnet Insulator <i>new</i>			\$ 196.50
	Bonnet Insulator Clips <i>new</i>			\$ 8.40
	Radiator Grille <i>broken</i>			\$ 1,110.10
	Radiator Grille H Emblem <i>broken/dislodged</i>			\$ 39.50
	Front Bumper Cover <i>turn</i>			\$ 1,052.20
	Front Bumper Sponge <i>turn</i>			\$ 99.20
	Front Bumper Reinforcement <i>broken</i>			\$ 402.10
	Front Bumper Grille (LH/RH) <i>o/s cut new</i>	\$	93.60	\$ 187.20
	Front Bumper Grille Airduct (LH/RH) <i>new</i>	\$	26.20	\$ 52.40
	Front Bumper Lip <i>new</i>			\$ 54.90
	Front Bumper Bracket Top (LH/RH) <i>new</i>	\$	22.40	\$ 44.80
	Front Bumper Bracket (LH/RH) <i>new</i>	\$	24.60	\$ 49.20
	Headlamp Support Top Cover <i>broken</i>			\$ 222.60
	Headlamp Support Panel Assy <i>broken/bt</i>			\$ 907.40
	Headlamp (LH/RH) <i>broken/muddy broken</i>	\$	1,388.00	\$ 2,776.00
	Radiator <i>bt/punctured</i>			\$ 698.30
	Radiator Fan Blade, Cowling, Motor Assy <i>broken</i>			\$ 792.95
	Radiator Bracket (RH/LH) <i>new</i>	\$	6.50	\$ 13.00
	Radiator Hose Upper <i>defunct</i>			\$ 36.50
	Radiator Hose Lower <i>new</i>			\$ 36.50
	Radiator Expansion Tank <i>new</i>			\$ 28.30
	Radiator Guard <i>new</i>	\$	20.00	\$ 40.00
	Horn Unit (LH/RH) <i>broken</i>	\$	73.80	\$ 147.60
	Horn Wire <i>new</i>			\$ 156.50
	Front Fender (LH/RH) <i>new new o/s new</i>	\$	566.30	\$ 1,132.60
	Front Fender Shield (LH/RH) <i>new</i>	\$	174.90	\$ 349.80
	Air Duct <i>new</i>			\$ 134.60
	Aircon Condenser <i>punctured/bt</i>			\$ 927.50
	Aircon Suction & Liquid Hose <i>bt</i>			\$ 624.00
	Aircon Discharge Hose <i>bt</i>			\$ 162.60
	Aircon Compressor <i>new</i>			\$ 2,578.00
	Frt Safety Belt (Assy) (LH/RH) <i>actuated</i>	\$	475.40	\$ 950.80
	Wiper Panel Top Garnish <i>new</i>			\$ 222.60
	Wiper Container <i>defunct</i>			\$ 61.90
	Wiper Container Motor <i>down</i>			\$ 75.00
	Front Chasis Member <i>o/s bt</i>			\$ 1,060.70
	Engine Mounting <i>new</i>			\$ 456.30
	Engine Under Cover <i>turn</i>			\$ 334.60
	Engine Crossmember <i>new</i>			\$ 2,094.40
	Inter Cooler <i>bt/punctured</i>			\$ 1,032.50
	Inter Cooler Mounting (2 PCS) <i>new</i>			\$ 25.90
	Hose B To Inter Cooler <i>new</i>			\$ 229.70
	Hose C To Inter Cooler Inlet <i>new</i>			\$ 294.50

SHB 4183Z

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Pipe To Inter Cooler NH			\$ 167.05 X
	Pipe To Inter Cooler Outlet NH			\$ 244.55 X
	Wiring-Engine NH			\$ 3,326.00 X
	Wiring-ECM NH Socket broken			\$ 3,243.00 X ✓
	Actuator - Swirl Control broken			\$ 814.60 ✓
	Throttle Body Assy NH			\$ 1,096.60 X
	Intake Manifold Assy NH			\$ 1,141.10 X
	Airbag Complete activated			\$ 2,948.50 ✓
	Airbag Control Module activated			\$ 1,140.40 ✓
	Steering Angle Assy NH			\$ 1,150.60 X
	Sensor Assy Impact -Frt Impact NH			\$ 198.30 X
	Airbag Sensor 2 activated		\$ 580.00	\$ 1,160.00 2 ✓
			25298.95	\$ 41,031.85
	SUB TOTAL			\$ 8,206.37
	LESS 20%		20239.16	\$ 32,825.48
	DISCOUNTED TOTAL			
	Front Number Plate broken/damaged			\$ 25.00 Nett ✓
	Front No Plate Trim Cover broken			\$ 30.00 Nett ✓
	Front Fender Advertisement Logo (LH/RH) L/R NH		\$ 100.00	\$ 200.00 Nett ✓
			145.00	\$ 255.00
	Labour Charge			
	Panel Beating			\$ 1,500.00 1000/-
	Spray Painting Charge			\$ 1,500.00 800/-
	Wiring Charge			\$ 100.00 30/-
	Tuff Kote			\$ 150.00 40/-
	Towing Charge			\$ 50.00 NH
	Front Chassis Alignment Charge			\$ 400.00 150/-
	Remove/Refix Aircon & Refill Gas			\$ 150.00 80/-
	Remove/Refix Engine/Gearbox			\$ 650.00 250/-
	Remove/Refix Dashboard		2870.00	\$ 450.00 150/-
	Remove/Refix Fuse Box			\$ 180.00 50/-
	R/Refix Air Bag/Steering Wheel/Dashboard/Seat			\$ 550.00
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00 } 320/-
	24/10/2019 @ 1500m		23254.16	\$ 6,160.00
	Not Author		244.56	\$ 39,240.48
	12 days.		23498.72	39485.04
	1 year		18000/-	
	LKK Auto			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19018874/Dsd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 27-11-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7581H	Veh. Inspected	SHB 4183Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19006759MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	23/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KMHLB41UMGU080373	Colour	BLUE	
Odometer	529494	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	HANKOOK	5 mm	
L/H Front Tyre	205/60 R16	HANKOOK	5 mm	
R/H Rear Tyre	205/60 R16	HANKOOK	5 mm	
L/H Rear Tyre	205/60 R16	HANKOOK	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/10/2019	Inspection Date	24/10/2019	
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 4183Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	DENTED	2,265.90	2,265.90
2	BONNET HINGE (LH/RH) @\$41.00	BENT	82.00	82.00
1	BONNET LOCK	BENT	36.90	36.90
2	BONNET ABSORBER @\$58.10	NOT NECESSARY	116.20	-
1	BONNET INSULATOR	NOT NECESSARY	196.50	-
1	BONNET INSULATOR CLIPS	NOT NECESSARY	8.40	-
1	RADIATOR GRILLE	BROKEN	1,110.10	1,110.10
1	RADIATOR GRILLE H EMBLEM	BROKEN / DISLODGE	39.50	39.50
1	FRONT BUMPER COVER	TORN	1,052.20	1,052.20
1	FRONT BUMPER SPONGE	TORN	99.20	99.20
1	FRONT BUMPER REINFORCEMENT	BROKEN	402.10	402.10
2	FRONT BUMPER GRILLE (LH/RH) @\$93.60	O/S CUT / N/S NOT NECESSARY	187.20	93.60
2	FRONT BUMPER GRILLE AIRDUCT (LH/RH) @\$26.20	NOT NECESSARY	52.40	-
1	FRONT BUMPER LIP	NOT NECESSARY	54.90	-
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$22.40	NOT NECESSARY	44.80	-
2	FRONT BUMPER BRACKET (LH/RH) @\$24.60	NOT NECESSARY	49.20	-
1	HEADLAMP SUPPORT TOP COVER	BROKEN	222.60	222.60
1	HEADLAMP SUPPORT PANEL ASSY	BROKEN / BENT	907.40	907.40
2	HEADLAMP (LH/RH) @\$1388.00	BROKEN / MOUNTING BROKEN	2,776.00	2,776.00
1	RADIATOR	BENT / PUNCTURE	698.30	698.30
1	RADIATOR FAN BLADE,COWLING,MOTOR ASSY	BROKEN	792.95	792.95
2	RADIATOR BRACKET (RH/LH) @\$6.50	NOT NECESSARY	13.00	-
1	RADIATOR HOSE UPPER	DEFORMED	36.50	36.50
1	RADIATOR HOSE LOWER	NOT NECESSARY	36.50	-
1	RADIATOR EXPANSION TANK	NOT NECESSARY	28.30	-
2	RADIATOR GUARD @\$20.00	NOT FITTED	40.00	-
2	HORN UNIT (LH/RH) @\$73.80	BROKEN	147.60	147.60
1	HORN WIRE	NOT NECESSARY	156.50	-

Report Ref No. CS/FCI19018874/Dsd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT FENDER (LH/RH) @\$566.30	O/S NOT NECESSARY / N/S TO REPAIR SEE LABOUR	1,132.60	-
2	FRONT FENDER SHIELD (LH/RH) @\$174.90	NOT NECESSARY	349.80	-
1	AIR DUCT	NOT NECESSARY	134.60	-
1	AIRCON CONDENSER	PUNCTURE / BENT	927.50	927.50
1	AIRCON SUCTION & LIQUID HOSE	BENT	624.00	624.00
1	AIRCON DISCHARGE HOSE	BENT	162.60	162.60
1	AIRCON COMPRESSOR	NOT NECESSARY	2,578.00	-
2	FRT SAFETY BELT (ASSY)(LH/RH) @\$475.40	ACTIVATED	950.80	950.80
1	WIPER PANEL TOP GARNISH	NOT NECESSARY	222.60	-
1	WIPER CONTAINER	DEFORMED	61.90	61.90
1	WIPER CONTAINER MOTOR	DAMAGED	75.00	75.00
1	FRONT CHASIS MEMBER O/S	BENT	1,060.70	1,060.70
1	ENGINE MOUNTING	NOT NECESSARY	456.30	-
1	ENGINE UNDER COVER	TORN	334.60	334.60
1	ENGINE CROSSMEMBER	NOT NECESSARY	2,094.40	-
1	INTER COOLER	BENT / PUNCTURE	1,032.50	1,032.50
1	INTER COOLER MOUNTING (2 PCS)	NOT NECESSARY	25.90	-
1	HOSE B TO INTER COOLER	NOT NECESSARY	229.70	-
1	HOSE C TO INTER COOLER INLET	NOT NECESSARY	294.50	-
1	PIPE TO INTER COOLER	NOT NECESSARY	167.05	-
1	PIPE TO INTER COOLER OUTLET	NOT NECESSARY	244.55	-
1	WIRING-ENGINE	NOT NECESSARY	3,326.00	-
1	WIRING-ECM	SOCKET BROKEN	3,243.00	3,243.00
1	ACTUATOR-SWIRL CONTROL	BROKEN	814.60	814.60
1	THROTTLE BODY ASSY	NOT NECESSARY	1,096.60	-
1	INTAKE MANIFOLD ASSY	NOT NECESSARY	1,141.10	-
1	AIRBAG COMPLETE	ACTIVATED	2,948.50	2,948.50
1	AIRBAG CONTROL MODULE	ACTIVATED	1,140.40	1,140.40
1	STEERING ANGLE ASSY	NOT NECESSARY	1,150.60	-
1	SENSOR ASSY IMPACT-FRT IMPACT	NOT NECESSARY	198.30	-
2	AIRBAG SENSOR @\$580.00	ACTIVATED	1,160.00	1,160.00

Report Ref No. CS/FCI19018874/Dsd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FAN BELT (ADDITIONAL)	TORN	116.20	116.20
1	FAN IDLER PULLEY (ADDITIONAL)	BROKEN	189.50	189.50
	LESS 20% DISCOUNT		-8,267.51	-5,120.93
			33,070.04	20,483.72
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NO PLATE TRIM COVER (SN) }	BROKEN	30.00	45.00
1	FRONT NUMBER PLATE (SN) }	BROKEN / DISLODGE	25.00	-
2	FRONT FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN)	N/S NECESSARY / O/S NOT NECESSARY	200.00	100.00
			255.00	145.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF N/S FRONT FENDER.		1,500.00	1,000.00
	SPRAY PAINTING CHARGE.		1,500.00	800.00
	WIRING CHARGE.		100.00	30.00
	TUFF KOTE.		150.00	40.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	FRONT CHASSIS ALIGNMENT CHARGE.		400.00	150.00
	REMOVE/REFIX AIRCON & REFILL GAS.		150.00	80.00
1	REMOVE/REFIX ENGINE/GEARBOX.		650.00	250.00
	REMOVE/REFIX DASHBOARD.		450.00	150.00
	REMOVE/REFIX FUSE BOX.		180.00	50.00
	R/REFIX AIR BAG/STEERING WHEEL/DASHBOARD/SEAT. }		550.00	320.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE. }		480.00	-
	-		-	-
	-		-	-
	-		-	-
			6,160.00	2,870.00
	GRAND TOTAL		39,485.04	23,498.72

Report Ref No. CS/FCI19018874/Dsd3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			18,000.00
---	--	--	-----------

Report Ref No. CS/FCI19018874/Dsd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.