

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19018883/AES3Q2

Date: 13/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800029907

Claimant
Vehicle No : SKN3333R **Insured Vehicle No :** SLX4597A

Date of Loss: 05/10/2019 Nature of Claim: TP Claim No: 7579930408SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKN3333R	Engine No:	B3900316N20B20A
Make & Model:	BMW 528I, 2.0 (A)	Chassis No:	WBAXG32040DX83161
Reg. Date:	29/11/2013 (Man. Year: 2012)	Odometer:	182748 km
Colour:	Black		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,040.82	3,728.02	312.80	7.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,430.00	580.00	850.00	59.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,470.82	4,308.02	1,162.80	21.25
Approved Total (Overridden) (\$\$)		3,400.00		
(\$\$)	5,470.82	3,400.00	2,070.82	37.85
+ GST 7.00/7.00% (\$\$)	382.96	238.00	144.96	37.85
Nett Amount (\$\$)	5,853.78	3,638.00	2,215.78	37.85
+ Loss of Use (2.0 x S\$100.00/day) (\$\$)		200.00		
(\$\$)		3,838.00		
Liabile Amount (50.00%) (\$\$)		1,919.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		1,921.00		
Global Sum Settlement (\$\$)		1,920.00		

INSPECTION

Date of Assignment: 23/10/2019

Date Inspected: 23/10/2019 Inspected At:

Kang Car Repairers Pte Ltd (HQ)
No 1 Kaki Bukit Ave 6, #02-06

AutoBay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 2.0 days

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	1,351.15 FL	*1,351.15 FL
2	1		*FRT BUMPER SIDE RETAINER	Not Necessary	65.70 FL	*- FL
3	1		*HEADLAMP LH	Cracked	2,649.65 FL	*2,649.65 FL
4	1		*FRT FOG LAMP LH	Not Necessary	281.85 FL	*- FL
5	1		*FRT GRILLE	Cut	141.45 FL	*141.45 FL
					Sub Total (S\$)	4,489.80
					- List Item Discount on L Items 10.00/10.00% (S\$)	448.98
					Total Parts (S\$)	3,728.02

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	30.00
2	(FRONT) TO SPRAY PAINTING	New	500.00	250.00
3	TO REMOVE AND REPLACE THE DAMAGED PARTS ,KNOCK OUT ACCIDENT DENTED PORTIONS AND FOR CUTTING /WELDING WORKS	New	500.00	250.00
4	TO PROGRAMME	New	280.00	0.00
5	TO REMOVE AND REFIT SENSOR	New	100.00	50.00
Gross Labour Cost (S\$)			1,430.00	580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >