

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJX 549P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	DISTORTED	476.50	331.10
1	REAR BUMPER SIDE RETAINER RH (CONSISTENT)	NOT NECESSARY	98.50	-
1	TAIL LAMP RH (CONSISTENT)	NOT NECESSARY	451.30	-
1	REAR FENDER RH (CONSISTENT)	TO REPAIR SEE LABOUR	775.00	-
1	REAR FENDER INNER COWLING RH (CONSISTENT)	NOT NECESSARY	107.00	-
1	REAR SHOCK ABSORBER RH (CONSISTENT)	SERVICEABLE	151.20	-
1	REAR WHEEL HUB WITH BEARING RH (CONSISTENT)	DAMAGED	571.75	571.75
1	REAR AXLE (CONSISTENT)	SERVICEABLE	1,776.75	-
	LESS 25% DISCOUNT		-1,102.00	-
	LESS 50% DISCOUNT		-	-451.43
			3,306.00	451.42
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN)(CONSISTENT)	NECESSARY	50.00	50.00
1	SET REAR FENDER INNER COWLING CLIPS (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	REAR SPORT RIM RH (SN)(CONSISTENT)	CRACKED	500.00	400.00
1	REAR TYRE RH (LOCAL PURCHASE)(\$200.00)(60%)(SN) (CONSISTENT)	CUT	400.00	120.00
			1,000.00	570.00
	LABOUR			
	WIRE CHECK.		50.00	20.00
	R&R REAR UNDERCARRIAGE.		250.00	120.00
	R&R REAR REVERSE SENSOR.		50.00	40.00
	TUFF COAT.	NOT NECESSARY	100.00	-
	LABOUR.INCLUSIVE OF THE REPAIR OF REAR FENDER RH.		1,000.00	300.00
	PAINTING.		1,000.00	400.00
			2,450.00	880.00
	GRAND TOTAL		6,756.00	1,901.42

Report Ref No. CC4/ASM19018900/Uga3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,900.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM19018900/Uga3q2

CHUA KANG SENG
Licensed Appraiser