

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
|---|--|---|-------------------------------|------------|--|
| AXA INSURANCE PTE LTD | | | Ref : CC4/ASM19018930/Aga3q2 | | |
| 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CYNTHIA LOH | | | Date: 13-05-2020 Code: ASM | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SHD 5348Z | Veh. Inspected | SJH 8220T | |
| | Policy No. | VFX/P1680520 | Coverage (\$) | 0.00 | |
| | Claim No. | S9M024QZ | Excess (\$) | 0.00 | |
| | Assign From | | Assign Date | 24/10/2019 | |
| 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | TOYOTA VIOS | c.c | 1497 | |
| | Engine No. | HIDDEN | Year of Reg. | 2008 | |
| | Chassis No. | MR053HY9305078452 | Colour | GOLD | |
| | Odometer | 417409 | Steering | IN ORDER | |
| | Brakes | IN ORDER | Modification | SPORTS RIM | |
| | General | GOOD | | | |
| 3. | | | | | |
| | | Size | Make | Balance | |
| | R/H Front Tyre | 195/55 R15 | DAYTON | 6 mm | |
| | L/H Front Tyre | 195/55 R15 | DAYTON | 6 mm | |
| | R/H Rear Tyre | 195/55 R15 | DAYTON | 6 mm | |
| | L/H Rear Tyre | 195/55 R15 | DAYTON | 6 mm | |
| 4. | Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE. | | | | |
| | DAMAGES SEE DETAILS. | | | | |
| 5. | General Information | | | | |
| | Accident Date | 24/10/2019 | Inspection Date | 25/10/2019 | |
| | Survey held at | J-MART MOTOR PTE LTD | | | |
| | | BLK 5 DEFU LANE 10 #01-578 DEFU INDUSTRIAL PARK C SINGAPORE 539186 | | | |
| 5a. | Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | Estimate Days of Repair | | | | |
| | ESTIMATED NOR | ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days | | | |