

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19018931/GGA3Q2

Date: 07/09/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549
Claimant Vehicle No :	SJY6380M	Insured Vehicle No :	YP1918R
Date of Loss:	21/10/2019	Nature of Claim:	TP
		Claim No:	MFL2019D0001300

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJY6380M		
Make & Model:	PROTON EXORA, 1.6 AT (M-LINE) ABS D/AB 2WD 5DR (A)	Engine No:	S4PHQQ2932
Reg. Date:	21/09/2010 (Man. Year: 2010)	Chassis No:	PL1FZ6YRRBF041902
Colour:	White	Odometer:	133603 km
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	934.20	0.00	934.20	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,080.00	700.00	380.00	35.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,014.20	700.00	1,314.20	65.25
+ GST 7.00/7.00% (\$\$)	140.99	49.00	91.99	65.25
Nett Amount (\$\$)	2,155.19	749.00	1,406.19	65.25
+ Loss of Use (4.0 x S\$50.00/day) (\$\$)		200.00		
+ Doc/Search Fee (\$\$)		29.00		
Nett Liability (\$\$)		978.00		
Global Sum Settlement (\$\$)		950.00		

INSPECTION

Date of Assignment:	24/10/2019		
Date Inspected:	25/10/2019	Inspected At:	ETHOZ PROTECT PTE LTD 30 Bukit Batok Crescent Singapore 658075
Estimated Period of Repair:	3.0 days		

Adjuster: XING GUO QIANG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Jul 2020)
Parts:	M1-MPV	PROTON EXORA 1.6 AT (M-LINE) ABS D/AB 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJY6380M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	465.50 FL	*- FL
2	1		*FRONT BUMPER RETAINER RH	Not Necessary	85.50 FL	*- FL
3	10		*FRONT BUMPER CLIPS	Not Necessary	50.00 FL	*- FL
4	1		*FRONT FENDER RH	Repair	437.00 FL	*- FL
					Sub Total (\$\$)	1,038.00 0.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	103.80 0.00
					Total Parts (\$\$)	934.20 0.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO FACILITATE REPAIR	New	500.00	300.00
2	TO RESPRAY AFFECTED AREAS	New	500.00	400.00
3	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	30.00	0.00
4	RUST PROOFING	New	50.00	0.00
Gross Labour Cost (\$\$)			1,080.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >