



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2007400
INV Date 04/11/2020
Reference CC3/LPC19018984/Kka3s2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. SHD 5236M
Insured Veh. GZ 2803S
Claim No. 19/19/19/VC05/022603
Policy No. Z19VC05003034
Accident Date 23/10/2019
Inspection Date 24/10/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC3/LPC19018984/Kka3s2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 04-11-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GZ 2803S	Veh. Inspected	SHD 5236M
Policy No.	Z19VC05003034	Coverage (\$)	0.00
Claim No.	19/19/19/VC05/022603	Excess (\$)	0.00
Assign From		Assign Date	24/10/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JTDKB3FUX03078475	Colour	METALLIC WHITE / RED
Odometer	87325	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	GITI	9 mm
L/H Front Tyre	195/65 R15	GITI	9 mm
R/H Rear Tyre	195/65 R15	GOODYEAR	7 mm
L/H Rear Tyre	195/65 R15	GOODYEAR	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	23/10/2019	Inspection Date	24/10/2019
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 5236M

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	MOULDING ASSY, BODY ROCKER PANEL, RH	SERVICEABLE	594.80	-
1	REAR FENDER RH	BENT	854.80	854.80
1	REAR FENDER LINER	SERVICEABLE	139.80	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	442.60	-
1	REAR BUMPER RE-INFORCEMENT	TO REPAIR SEE LABOUR	332.70	-
1	REAR BUMPER TOWING COVER	SERVICEABLE	15.40	-
1	REAR BUMPER UNDER COVER (BLACK)	SERVICEABLE	576.30	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	117.70	-
1	TAILLAMP LOWER RH	SERVICEABLE	502.00	-
1	TAILLAMP UPPER RH	SERVICEABLE	451.80	-
1	REAR BUMPER SIDE RH	SERVICEABLE	123.70	-
1	REAR TAILGATE	TO REPAIR SEE LABOUR	1,147.80	-
1	COVER, FLOOR UNDER, NO.1	SERVICEABLE	175.10	-
1	COVER, FLOOR UNDER, NO.2	SERVICEABLE	241.90	-
1	COVER, REAR FLOOR	SERVICEABLE	229.90	-
1	COVER, DECK TRIM, REAR	SERVICEABLE	126.70	-
1	PANEL SUB-ASSY, REAR DOOR, RH	SERVICEABLE	1,281.70	-
1	LOCK ASSY, REAR DOOR W/MOTOR, RH	SERVICEABLE	561.90	-
1	WEATHERSTRIP, REAR DOOR OPENING TRIM, RH	SERVICEABLE	293.00	-
1	WEATHERSTRIP, REAR DOOR, RH	SERVICEABLE	180.10	-
1	RUN, REAR DOOR GLASS, RH	SERVICEABLE	122.50	-
1	PLATE ASSY, REAR DOOR LOCK STRIKER	SERVICEABLE	39.30	-
1	HUB & BEARING ASSY, REAR AXLE, RH	NOT NECESSARY	725.60	-
1	DISC REAR	SERVICEABLE	450.70	-
1	CARRIER SUB ASSY, REAR AXLE, RH	SERVICEABLE	953.60	-
1	CYLINDER ASSY, DISC BRAKE, REAR RH	SERVICEABLE	1,001.90	-
1	PAD KIT, DISC BRAKE, REAR	SERVICEABLE	188.40	-
1	COVER, DISC BRAKE DUST, REAR RH	SERVICEABLE	58.20	-
1	BAR, STABILIZER, REAR	SERVICEABLE	295.70	-

Report Ref No. CC3/LPC19018984/Kka3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LINK ASSY, REAR STABILIZER, RH	SERVICEABLE	179.10	-
1	BUSH, STABILIZER, REAR	SERVICEABLE	71.20	-
1	BRACKET, REAR STABILIZER BAR, NO.1	SERVICEABLE	11.50	-
1	BRACKET, REAR SUSPENSION ARM, RH	SERVICEABLE	107.20	-
1	COVER, REAR SUSPENSION ARM, RH	SERVICEABLE	49.70	-
1	ARM ASSY, REAR SUSPENSION, NO.1 RH	SERVICEABLE	239.20	-
1	ARM ASSY, TRAILING, REAR RH	SERVICEABLE	370.40	-
1	ABSORBER ASSY, SHOCK, REAR RH	SERVICEABLE	127.00	-
1	SUPPORT ASSY, REAR SUSPENSION, RH	SERVICEABLE	149.30	-
1	SPRING, COIL, REAR RH	SERVICEABLE	199.00	-
1	INSULATOR, REAR COIL SPRING, LOWER RH	SERVICEABLE	13.90	-
1	INSULATOR, REAR COIL SPRING, UPPER RH	SERVICEABLE	19.80	-
1	ARM ASSY, REAR SUSPENSION, NO.2 RH	SERVICEABLE	497.50	-
1	ARM ASSY, UPPER CONTROL, REAR RH	SERVICEABLE	420.80	-
1	MEMBER SUB ASSY, REAR SUSPENSION	SERVICEABLE	2,245.20	-
1	WIRE, SKID CONTROL SENSOR, RH	SERVICEABLE	94.70	-
1	DUCT ASSY, QUARTER VENT, RH	SERVICEABLE	67.00	-
1	PANEL, QUARTER WHEEL HOUSE, OUTER RH	SERVICEABLE	296.20	-
	LESS 25% DISCOUNT		-4,346.07	-213.70
			13,038.23	641.10
	SPECIAL NETT ITEMS			
1	REAR DOOR STICKER '6555-333' (SN)	NECESSARY	80.00	60.00
1	REAR RIGHT WHEEL RIM (SN)	NOT NECESSARY	1,570.55	-
1	REAR RIGHT WHEEL RIM COVER (SN)	DENTED	175.80	175.80
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	66.00	-
1	REAR BUMPER PROTECTOR (SN)	NOT NECESSARY	100.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	REAR TAILGATE TOYOTA LOGO (SN)	NOT NECESSARY	47.00	-
1	REAR TAILGATE WORDING 'PRIUS' (SN)	NOT NECESSARY	52.90	-
1	REAR TAILGATE WORDING 'HYBRID' (SN)	NOT NECESSARY	53.50	-

Report Ref No. CC3/LPC19018984/Kka3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TAILGATE STICKER 'TRANS-CAB' (SN)	NOT NECESSARY	80.00	-
1	REAR TAILGATE STICKER '6555-3333' (SN)	NOT NECESSARY	80.00	-
			3,285.75	235.80
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	440.00
	TO TRANSFER OF TAILGATE FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	170.00	-
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REAR BUMPER, REAR BUMPER RE-INFORCEMENT AND REAR TAILGATE.		6,000.00	600.00
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	100.00
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO DISMANTLE AND REFIT REAR UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING,	NOT NECESSARY	380.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO DISMANTLE AND REFIT REAR AXLE HOUSING ASSY, REMOVE AND RENEWAL OF PARTS, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			15,270.00	1,250.00

Report Ref No. CC3/LPC19018984/Kka3s2



GRAND TOTAL		31,593.98	2,126.90
RECOMMENDED COST OF REPAIRS			2,126.90

Report Ref No. CC3/LPC19018984/Kka3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 5236M

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 5236M

RE-INSPECTION

