

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19018997/KRA3Q2
Date: 28/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SJN9809H	Insured Vehicle No :	SCY313E
Date of Loss:	23/10/2019	Nature of Claim:	TP
		Claim No:	0129672961SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJN9809H	Engine No:	HR16937755C
Make & Model:	NISSAN SYLPHY, 1.6 (A)	Chassis No:	MNTBBAB17Z0034016
Reg. Date:	31/12/2018 (Man. Year: 2018)	Odometer:	5896 km
Colour:	Blue		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R16	Rear Tyre Size:	195/65 R16
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,863.86	5,452.05	5,411.81	49.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,350.00	1,800.00	1,550.00	46.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,213.86	7,252.05	6,961.81	48.98
Approved Total (Overridden) (S\$)		5,800.00		

Nett Amount (S\$)	14,213.86	5,800.00	8,413.86	59.19
+ Car Rental (10.0 x S\$100.00/day) (S\$)		1,000.00		
Nett Liability (S\$)		6,800.00		

INSPECTION

Date of Assignment: 25/10/2019

Date Inspected: 25/10/2019

Estimated Period of Repair: 6.0 days

Inspected At:

Autoworx House - Sin Ming (HQ)
 176 SIN MING DRIVE #02-01
 Singapore 575721

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LOCK	Repair	194.30 FL	*- FL
2	1		*REAR BOOT LOCK CATCH	Repair	95.90 FL	*- FL
3	1		*REAR END PANEL	Repair	544.20 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT BEAM	Repair	374.50 FL	*- FL
5	1		*FRONT BUMPER SIDE RETAINER (RIGHT)	Distorted	767.00 FL	*39.00 FL
6	1		*FRONT DOOR (RIGHT)	Repair	967.40 FL	*- FL
7	1		*FRONT ANTI ROLLBAR LINKAGE	Serviceable	129.40 FL	*- FL
8	1		*FRONT STEERING TIE ROD	Serviceable	195.40 FL	*- FL
9	1		*FRONT STEERING TIE ROD END JOINT	Serviceable	173.60 FL	*- FL
10	10		*FRONT FENDER DUST COVER CLIP	Necessary	32.00 FN	*32.00 FN
11	1		*FRONT FENDER DUST COVER (RIGHT)	Distorted	214.30 FN	*99.60 FN
12	1		*FRONT FENDER SIGNAL LAMP	Scratched	146.30 FN	*146.30 FN
13	1		*FRONT FENDER (RIGHT)	Bent	858.40 FN	*727.60 FN
14	1		*FRONT BUMPER	Cracked	765.40 FN	*554.70 FN
15	1		*FRONT BUMPER FOG LAMP	Missing	316.40 FN	*316.40 FN
16	1		*FRONT BUMPER FOG LAMP GARNISH	Dented / Distorted	277.60 FN	*128.40 FN
17	1		*FRONT BUMPER SPONGE	Serviceable	316.50 FN	*- FN
18	1		*FRONT BUMPER LOWER DUST COVER	Serviceable	322.30 FN	*- FN
19	1		*FRONT TOP GRILLE	Serviceable	575.10 FN	*- FN
20	1		*FRONT HEAD LAMP LOWER BRACKET	Distorted	63.40 FN	*63.40 FN
21	1		*FRONT HEAD LAMP ASSY	Cracked	975.90 FN	*722.80 FN
22	1		*FRONT LOWER ARM	Distorted	571.20 FN	*252.17 FN
23	1		*FRONT DOOR FRAME STICKER (1)	Not Necessary	96.40 FN	*- FN
24	1		*FRONT DOOR FRAME STICKER (2)	Not Necessary	96.40 FN	*- FN
25	1		*FRONT WHEEL BEARING	Necessary	293.30 FN	*210.10 FN
26	1		*REAR BUMPER	Buckled / Dented	576.40 FN	*576.40 FN
27	1		*WIPER WASHER TANK	Dented	306.30 FN	*204.90 FN
28	1		*RADIATOR SIDE AIR GUIDE	Cracked	249.70 FN	*128.40 FN
29	1		*REVERSE SENSOR	Serviceable	220.00 FS	*- FS
30	1		*TYRE (80%)	Punctured	280.00 FS	*224.00 FS
31	1		*ALLOY RIM	Dented	680.00 FS	*680.00 FS
32	1		*FRONT KNUCKLE ARM	Bent	495.40 FS	*466.50 FS
33	1		*FRONT SHOCK ABSORBER	Bent	431.30 FS	*307.40 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)**12,601.70****5,880.07**

Report was unsubmitted during this print-out.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REPLACE THE PARTS MENTIONED ABOVE ,PANEL BEAT AND REALIGN THE NECESSARY AFFECTED AREAS	New	1,600.00	600.00
2	TO CHECK WIRING SYSTEM	New	50.00	20.00
3	TO APPLY RUST PROOFING ON AFFECTED AREAS	New	120.00	30.00
4	TO INSTALL REVERSE SENSORS AND REVERSE CAMERA	New	60.00	50.00
5	TO TRANSFER DOOR (S) ACCESSORIES	New	80.00	0.00
6	TO APPLY PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	980.00	800.00
7	TO REMOVE AND INSTALL FRONT UNDERCARRIAGE PARTS TO ENABLE REPAIR	New	180.00	140.00
8	TO REPLACE ALLOY RIM AND PERFORM WHEEL BALANCING	New	40.00	20.00
9	TO MACHINE PRESS WHEEL BEARING	New	80.00	30.00
10	TO PERFORM 4 WHEELS COMPUTERISE ALIGNMENT	New	80.00	60.00
11	TOWING CHARGES	New	80.00	50.00
Gross Labour Cost (\$\$)			3,350.00	1,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >